

ACCIDENT REPAIR ESTIMATE

Vehicle Reg. No. : SMU4902G

Vehicle Reg. Date: 17/08/2020

Make / Model : HYUNDAI AVANTE

Engine No. : G4FGLU111437

Chassis No. : KMHD841CMLU098405

SMU4902G

TP INSURER : INCOME

OWN INSURER : AIG

CLAIM TYPE : TP

Date of Accident : 28/04/2023

Surveyor Name and Company :

Rasul - 49 90010068

Date of survey : 03/05/23 @ 1510

Part by Part / Lump Sum 6 days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email : _____

Fax No : _____

HP No : 90010068

COST OF CLAIMS

Parts Cost / List Items : \$ 17,207.60

Plus/Less 20% \$ 3,441.52

Total Cost / List : \$ 13,766.08

Special Nett Items : \$ 365.00

Total Parts Amount : \$ 14,131.08

Total Labour Amount : \$ 4,660.00

Gross Total : \$ 18,791.08

GST % : 8% \$ 1,503.29

Nett Amount : \$ 20,294.37

This claim is handled by : MINOKO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vehicle Reg. No. : **SMU4902G**
 Vehicle Reg. Date: **17/08/2020**
 Make / Model : **HYUNDAI AVANTE**
 Engine No. : **G4FGLU111437**
 Chassis No. : **KMHD841CMLU098405**

PAGE 1

Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	BOOTLID <i>BT</i>	/	\$ 2,032.20		
2	1	BOOTLID GARNISH UPPER <i>X nn</i>		\$ 298.70		
3	1	BOOTLID LOCK <i>X nn</i>		\$ 116.20		
4	1	BOOTLID LOCK SWITCH <i>X nn</i>		\$ 101.40		
5	1	BOOTLID CAMERA <i>X nn</i>		\$ 826.10		
6	4	BOOTLID RUBBER STOPPER <i>nn</i>	/	\$ 19.20		
7	1	BOOLTID LAMP ASSY <i>X nn</i>		\$ 1,273.00		
8	1	BOOTLID LOGO <i>nn</i>	/	\$ 26.10		
9	1	BOOTLID EMBLEM "AVANTE" <i>nn</i>	/	\$ 31.20		
10	1	BOOLTID LOCK CATCH <i>X nn</i>		\$ 13.10		
11	1	BOOTLID WEATHERSTRIP <i>nn</i>	/	\$ 108.30		
12	1	BOOTLID INNER TRIM BOARD <i>X nn</i>		\$ 120.80		
13	1SET	BOOTLID INNER TRIM BOARD CLIPS <i>X nn</i>		\$ 60.00		
14	2	TAIL LAMP LH/RH <i>X nn</i>		\$ 1,753.60		
15	1	TAIL LAMP CLIPS <i>X nn</i>		\$ 4.00		
16	2	TAIL LAMP PANEL LH/RH <i>X nn</i>		\$ 386.20		
17	1	REAR BUMPER <i>de</i>	/	\$ 470.80		
18	1SET	REAR BUMPER CLIPS <i>nn</i>	/	\$ 60.00		
19	2	REAR BUMPER RETAINER LH/RH <i>X nn</i>		\$ 76.20		
20	2	REAR BUMPER REFLECTOR LH/RH <i>X nn</i>		\$ 100.40		
21	1	REAR BUMPER REFLECTOR CENTER <i>sol</i>	/	\$ 201.50		
22	1	REAR BUMPER LOWER SKIRT <i>X nn</i>		\$ 340.60		
23	1SET	REAR BUMPER LOWER SKIRT CLIPS <i>X nn</i>		\$ 60.00		
24	1	REAR BUMPER REINFORCEMENT <i>? cr</i>	/	\$ 294.80		
25	2	REAR BUMPER STAY <i>X nn</i>		\$ 162.40		
26	2	REAR BUMPER UNDER COVER LH/RH <i>X nn</i>		\$ 67.60		
27	1	ANTENNA SENSOR <i>X nn</i>		\$ 48.60		
28	1	REAR NUMBER PLATE BASE <i>X nn</i>		\$ 42.10		
29	5	REAR BUMPER REINFORCEMENT BRACKET <i>X nn</i>	cra	\$ 44.80	228	
30	1	REAR END PANEL <i>? photo: repair</i>		\$ 454.60		
31	1	REAR END PANEL TOP GARNISH <i>? de</i>	/	\$ 69.50		
32	1SET	REAR END PANEL TOP GARNISH CLIPS <i>? nn</i>	/	\$ 80.00		
33	1	SPARE TYRE PANEL <i>X nn</i>		\$ 713.00		
34	1	SPARE TYRE PANEL TOP BOARD <i>X nn</i>		\$ 259.10		
35	2	REAR NUMBER PLATE LAMP ASSY <i>X nn</i>	/	\$ 294.80		
36	2	REAR FENDER LH/RH <i>X nn</i>		\$ 3,784.00		
37	2	REAR FENDER INNER SHIELD (REAR) <i>X nn</i>		\$ 145.60		
38	2	REAR FENDER INNER SHIELD (FRONT) <i>X nn</i>		\$ 141.60		
39	2SET	REAR FENDER INNER SHIELD CLIPS <i>X nn</i>		\$ 100.00		
40	2	REAR FENDER LOWER TRIM BOARD <i>X nn</i>		\$ 418.80		

3912.40
 208
 3129.92

日昇 R & S Autoclaim Pte Ltd

UEN : 202245519N
TEL : (65) 6264 7001
FAX : (65) 6264 7002
EMAIL : rsautoclaim@rseng.com.sg
Address : No.13 Pioneer Sector 1,
Singapore 628424

Vehicle Reg. No. : **SMU4902G**
Vehicle Reg. Date: **17/08/2020**
Make / Model : **HYUNDAI AVANTE**
Engine No. : **G4FGLU111437**
Chassis No. : **KMHD841CMLU098405**

PAGE 2

Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	2SET	REAR FENDER LOWER TRIM BOARD CLIPS <i>X nn</i>		\$ 60.00		X
42	1	EXHAUST MOUNTING <i>X nn</i>		\$ 72.40		X
43	1	EXHAUST HEAT SHIELD <i>X nn</i>		\$ 103.50		X
44	1	EXHAUST PIPE (REAR) <i>X nn</i>		\$ 694.00		X
45	1	REVERSE SENSOR <i>? nw /</i>	sn	\$ 678.80	<i>200? /</i>	<i>?</i>
46	2	TAIL LAMP PAD LH/RH <i>X nn</i>			\$ 80.00	X
47	1	REAR END PANEL SEALANT <i>? X nn</i>		<i>X</i> \$ 80.00		<i>?</i>
48	1	SPARETYRE PANEL SEALANT <i>X nn</i>			\$ 80.00	X
49	1	SUNDRIES <i>nw /</i>			\$ 80.00	<i>20</i>
50	1	REAR NUMBER PLATE WITH FRAME <i>4 /</i>			\$ 45.00	<i>35</i>
51	0	0				
52	0	0				
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

255

Labour

3129.92

255.00

1440.50

4824.92

209

3859.93

C/S - \$3,850

6 days