



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921

Tel: +65 67412845 Fax No: +65 67412170

Email: zero_gravity@singnet.com.sg

Reg.No.: 52888887X

not Allowed
3/5/23
2/s \$8100
12 days.

QUOTATION

No : QT-000369

HSBC LIFE (SINGAPORE) PTE. LTD.

38 BEACH ROAD

#03-11 SOUTH BEACH TOWER

SINGAPORE 189767

Attn: Motor Claim Department

TEL : 62256111

FAX :

Your Ref. : SHA8114C
Vehicle No. : SJP4224S
Make & Model : TOYOTA CAMRY
Chasis No. : MR053BK4107043371
Engine No. : 1AZE131365
Accident Date : 29/04/2023
Policy No. : 5116125435-03
Date : 04/05/2023
Page : 1 of 3

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S\$
1	REAR BUMPER <i>Dis</i>	1 PCS	845.67	845.67
2	BUMPER CAP <i>11</i>	2 PCS	37.00	74.00
3	BUMPER CLIP <i>ru</i>	10 PCS <i>1st</i>	7.00	70.00
4	BUMPER SIDE RETAINER (L/H/R) <i>Buf</i>	1 PCS	171.60	171.60
5	BUMPER SIDE RETAINER (R/H/R) <i>Buf</i>	1 PCS	171.60	171.60
6	REAR BUMPER TOP RETAINER (L/H) <i>ru</i>	1 PCS	72.10	72.10
7	REAR BUMPER TOP RETAINER (R/H) <i>11</i>	1 PCS	72.10	72.10
8	REAR BUMPER SIDE RETAINER (L/H) <i>Repair</i>	1 PCS	124.10	124.10
9	REAR BUMPER SIDE RETAINER (R/H) <i>Repair</i>	1 PCS	124.10	124.10
10	REAR BUMPER REINFORCEMENT <i>Dis</i>	1 PCS	548.20	548.20
11	REAR BUMPER REFLECTOR (L/H) <i>ru</i>	1 PCS	87.34	87.34
12	REAR BUMPER REFLECTOR (R/H) <i>11</i>	1 PCS	87.34	87.34
13	REAR BOOT <i>Buf/Buc</i>	1 PCS	1,090.60	1,090.60
14	REAR BOOT GARNISH (CHROME) <i>11</i>	1 PCS	343.86	343.86
15	REAR BOOT GARNISH <i>ru</i>	1 PCS	254.60	254.60
16	LAMP (NUMBER PLATE) <i>11</i>	2 PCS	92.40	184.80
17	LAMP (REAR) <i>reflector's</i> <i>0/5 11 11/5 11</i>	2 PCS	859.80	1,719.60
18	LAMP (L/H/R) <i>ru</i>	1 PCS	1,063.40	1,063.40
19	LAMP (R/H/R) <i>11</i>	1 PCS	1,063.40	1,063.40
20	REAR TAIL LAMP PANEL (L/H) <i>Body 22</i>	1 PCS	337.00	337.00
21	REAR TAIL LAMP PANEL (R/H) <i>ru</i>	1 PCS	337.00	337.00
22	REAR BOOT INNER TRIM BOARD <i>Torn/De</i>	1 PCS	236.60	236.60
23	REAR BOOT INNER TRIM BOARD CLIPS <i>ru</i>	8 PCS	6.00	48.00
24	REAR BOOT HINGE <i>Buf/11</i>	2 PCS	170.60	341.20
25	REAR BOOT STOPPER BUSH <i>11</i>	2 PCS	14.90	29.80
26	REAR BOOT LOCK STRIKER <i>11</i>	1 PCS	54.10	54.10
27	REAR BOOT INNER LOCK <i>11</i>	1 PCS	454.40	454.40



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921

Tel: +65 67412845 Fax No: +65 67412170

Email: zero_gravity@singnet.com.sg

Reg.No.: 52888887X

QUOTATION

No : QT-000369

HSBC LIFE (SINGAPORE) PTE. LTD.

38 BEACH ROAD

#03-11 SOUTH BEACH TOWER

SINGAPORE 189767

Attn: Motor Claim Department

TEL : 62256111

FAX :

Your Ref. : SHA8114C
Vehicle No. : SJP4224S
Make & Model : TOYOTA CAMRY
Chassis No. : MR053BK4107043371
Engine No. : 1AZE131365
Accident Date : 29/04/2023
Policy No. : 5116125435-03
Date : 04/05/2023
Page : 2 of 3

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price	Amount
			S\$	S\$
28	REAR BOOT CABLE 11	1	PCS 130.10	130.10 X
29	REAR BOOT WEATHERSTRIP 7w1	1	PCS 247.60	247.60
30	REAR END PANEL Body PD	1	PCS 672.10	672.10
31	REAR END PANEL GARNISH D/S	1	PCS 481.10 564.40	564.40
32	CLIP (REAR END PANEL GARNISH) 11	7	PCS 3.00	21.00 X
33	SPARE TYRE BOARD Torn	1	PCS 275.60	275.60
34	SPARE TYRE PANEL Crumpled / Bu	1	PCS 1,014.20	1,014.20
35	SPARE TYRE BRACKET 7w1	1	PCS 56.70	56.70
36	WINDSCREEN MOULDING (REAR) 11	1	PCS 125.49	125.49 X
37	FENDER (L/H/R) R	1	PCS 1,087.37	1,087.37 X
38	TOOL TRAY/BOX 7w1	1	PCS 296.43	296.43
39	FENDER AIR GRILLE Torn	1	PCS 111.40	111.40
40	FENDER INNER TRIM (REAR) (R/H) 11	1	PCS 472.40	472.40 X
41	FENDER INNER TRIM (REAR) (L/H) De Torn	1	PCS 472.40	472.40
42	CLIP (FENDER INNER TRIM) (REAR) 11	16	PCS 5.00	80.00 X
43	LOGO (REAR) 11	1	PCS 40.60	40.60
44	EMBLEM "2.0" 11	1	PCS 37.60	37.60
45	EMBLEM "CAMRY" 11	1	PCS 47.90	47.90
46	Discount 25 % ✓			-3,939.95
47	SubTotal (L)			11,819.85
48	REAR END PANEL SEALANT 11	1	BTL 80.00 50	80.00
49	REAR NUMBER PLATE 50C	1	PCS 45.00	45.00 X
50	SEALANT (WINDSCREEN) 11	1	PCS 35.00	35.00 X
51	INSULATOR (SPARE TYRE PANEL) 11	1	PCS 250.00 100	250.00
52	TYRE (SPARE) 11	1	PCS 220.00	220.00 X
53	RIM 11	1	PCS 180.00	180.00 X
54	REVERSE SENSOR sharp	1	SET 350.00 200	350.00



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921

Tel: +65 67412845 Fax No: +65 67412170

Email: zero_gravity@singnet.com.sg

Reg.No.: 52888887X

QUOTATION

No : QT-000369

HSBC LIFE (SINGAPORE) PTE. LTD.

38 BEACH ROAD

#03-11 SOUTH BEACH TOWER

SINGAPORE 189767

Attn: Motor Claim Department

TEL : 62256111

FAX :

Your Ref. : SHA8114C
Vehicle No. : SJP4224S
Make & Model : TOYOTA CAMRY
Chasis No. : MR053BK4107043371
Engine No. : 1AZE131365
Accident Date : 29/04/2023
Policy No. : 5116125435-03
Date : 04/05/2023
Page : 3 of 3

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S\$
55	REVERSE CAMERA	1 PCS	450.00	450.00
56	SubTotal (S)			1,610.00
57	PANEL BEAT & REPAIR REAR DAMAGE	1 X	1500	1,800.00
58	TO PUTTY AND RE-SPRAY AFFECTED PORTION	1 X	1200	1,500.00
59	TO REMOVE REVERSE SENSOR/CAMERA	1 X	50	250.00
60	TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT	1 X	20	80.00
61	TO CHECK WIRING SYSTEM, FOCUS LIGHTINGS	1 X		50.00
62	TO TRANSFER REAR BOOT FITTING	1 X	60	120.00
63	TO PROVIDE UNDER TURFCODE	1 X	90	250.00
64	TO REMOVE AND REFIT COMPONENTS / FACILITATE THE REPAIR	1 X	80	180.00
65	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	1 X	150 X	150.00
66	SubTotal (LABOUR)			4,380.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

SINGAPORE DOLLAR SEVENTEEN THOUSAND EIGHT HUNDRED NINE AND CENTS EIGHTY FIVE ONLY

Acknowledged by Repairer

Signature:

Date:

E. & O.E

Total S\$ 17,809.85

Discount S\$ 0.00

Net Total S\$ 17,809.85

Customer's Signature/Co. Stamp

ZERO GRAVITY

Terms: C.O.D.

Any claim for faulty workmanship is limited solely to the rectification free of cost of such work, no claim for loss consequential or otherwise being admissible. Any objections to the validity of these charges must be made seven (7) days from the date of this invoice otherwise it is assumed that this bill is accepted as correct.

P-9088-17
257
6816.12
350
3000
10166.12
8132