



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4083J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER COVER	DEFORMED	459.40	459.40
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER CENTRE MOULDING ASSY	DEFORMED	451.25	451.25
1	REAR BUMPER REINFORCEMENT	CRACKED	394.80	394.80
2	REAR BUMPER REINFORCEMENT BRACKET LH RH @ \$138.10	NOT NECESSARY	276.20	-
2	REAR BUMPER SIDE BRACKET LH RH @\$55.80	NOT NECESSARY	111.60	-
1	BOOTLID	BENT	2,549.70	2,549.70
1	BOOTLID HYUNDAI PLATE	NECESSARY	24.30	24.30
1	EMBLEM HYBRID	NECESSARY	24.30	24.30
1	EMBLEM - IONIQ	NECESSARY	31.30	31.30
1	ANTENNA SMARTKEY	NOT NECESSARY	40.50	-
1	REAR BUMPER FOG LAMP	NOT NECESSARY	201.50	-
	LESS 20% DISCOUNT		-917.37	-791.41
			3,669.48	3,165.64
<b><u>NETT ITEMS</u></b>				
1	REAR NUMBER PLATE WITH TRIM COVER (N)	CRACKED	50.00	50.00
1	BOOTLID COMFORT TEL NO STICKER (N)	NECESSARY	40.00	40.00
1	BOOTLID COMFORT LOGO STICKER (N)	NECESSARY	30.00	30.00
1	BOOTLID COMFORT APP STICKER (N)	NECESSARY	30.00	30.00
1	REAR BUMPER REVERSE SENSOR (N)	NOT WORKING	180.00	180.00
	LESS 10% DISCOUNT		-	-33.00
			330.00	297.00
<b><u>LABOUR</u></b>				
	PANEL BEATING.		1,100.00	525.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	REMOVE / REFIX BOOTLID GLASS.		120.00	120.00

Report Ref No. NS/INC23004460/Twp3e2



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE / REFIX REVERSE SENSOR.		80.00	30.00
			1,900.00	1,175.00
GRAND TOTAL			5,899.48	4,637.64
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				3,700.00

Report Ref No. NS/INC23004460/Twp3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.