

LEBENS STRECKE / L.E.S.: 17

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA4083J

Date: 28/04/2023

Make : HYUNDAI

Insurance: INCOME

Model : IONIQ(G3)

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$459.40
10	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
1	REAR BUMPER REINFORCEMENT BRACKET LH RH		\$138.10	\$276.20
2	REAR BUMPER SIDE BRACKET LH RH		\$55.80	\$111.60
1	BOOTLID			\$2,549.70
1	BOOTLID HYUNDAI PLATE			\$24.30
1	EMBLEM HYBRID			\$24.30
1	EMBLEM - IONIQ			\$31.30
1	ANTENNA SMARTKEY			\$40.50
1	REAR BUMPER FOG LAMP			\$201.50
	SUB TOTAL			\$4,586.85
	LESS 20%			\$917.37
	DISCOUNTED TOTAL			\$3,669.48
	REAR NUMBER PLATE WITH TRIM COVER			\$50.00
	BOOTLID COMFORT TEL NO STICKER			\$40.00
	BOOTLID COMFORT LOGO STICKER			\$30.00
	BOOTLID COMFORT APP STICKER			\$30.00
	REAR BUMPER REVERSE SENSOR			\$180.00
		NETT		\$330.00
	Labour Charge			
	PANEL BEATING			\$1,100.00
	SPRAY PAINTING CHARGE			\$600.00
	REMOVE/REFIX BOOTLID GLASS			\$120.00
	REMOVE/REFIX REVERSE SENSOR			\$80.00
	TOTAL LABOUR			\$1,900.00
	ESTIMATE TOTAL			\$5,899.48

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97495749
 'wp' 28/4/23 @ 330
 L/S survey after repair
 3 days
 Tanpin @ Chuan-wei

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: