



HS AUTOMOTIVES PTE LTD

Blk 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHUB #02-25 SINGAPORE 417921.

TEL: 6538 1368 FAX: 6538 1367 EMAIL: HSAUTOMOTIVESPL@GMAIL.COM

ROC: 201907812C

TP HSBC

Veron

Vehicle No:

8729798X

Make/Model:

Y/AT118

CHASSIS NO:

INDEPENDENT SURVEYOR

DIRECT SETTLEMENT

Date:

5.5.23

Estimate cost of repair to the above mentioned

NO. QTY LIST ITEMS

MARKING

UNIT \$

AMOUNT (\$\$)

1	1	RH FRONT FENDER Dented ✓			198	\$ 656.10
2	1	RH FRONT FENDER TUNING STRIP CUT ✓				\$ 144.10
3	1	RH FRONT FENDER TUNING CLIP NEW SPN		30(SN)		\$ 50.00
4	1	RH FRONT FENDER LOGO (DOT-I) NEW ✓				\$ 65.10
5	1	FRONT BUMPER torn ✓				\$ 587.10
6	1	FRONT BUMPER RETAINER Dented ✓		HS		\$ 72.90
7	1	FRONT BUMPER FOOT LAMP NEW X				\$ 255.10
8	1	FRONT BUMPER FOOT LAMP GRABBAR NEW X				\$ 110.30
9	1	FRONT SUPPLY PANEL NEW X				980.30
10	1	FRONT BATTERY Regis X				883.50
11	1	RH FRONT HEAD LAMP Cusht ✓				\$ 723.95
12	1	RH FRONT HEAD LAMP LOWER BRACKET NEW X				45.60
13	1	RH FRONT WHEEL KNUCKLE NEW Dented ✓				\$ 455.10
14	1	RH FRONT WHEEL BEARING Dented ✓				\$ 247.10
15	1	RH FRONT SHOCK ABSORBER NEW				\$ 403.10
16	1	RH FRONT LOWER ARM Best ✓		315		\$ 495.10
17	1	RH FRONT SPORT RIM Cut ✓		400(SN)		\$ 880.45
18	1	RH FRONT TYRE NEW NEW X SPN				\$ 250.00
19					SIN: 430	
20						

3140.45

len 25% : 2355.33

REMARKS:

NO OF DAYS:

AGREED FIGURE/LUMP SUM:

SURVEYOR NAME

CONTACT:

EMAIL ADD:



HS AUTOMOTIVES PTE LTD

Blk 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHUB #02-25 SINGAPORE 417921.

TEL: 6538 1368 FAX: 6538 1367 EMAIL: HSAUTOMOTIVESPL@GMAIL.COM

ROC: 201907812C

Vehicle No:

SJL 97 PPS

Make/Model:

Y1 A418

CHASSIS NO:

INDEPENDENT SURVEYOR

DIRECT SETTLEMENT

Date:

5.5.23

Estimate cost of repair to the above mentioned

NO. QTY LIST ITEMS

MARKING

UNIT \$

AMOUNT (\$\$)

1		DAN M BIA7		500	1200
2					1200
3		SPRAY PAINT7		600	1200
4					1200
5		TO REMOVE/REPAIR UNDERCARRIAGE		180	350
6					
7		TO WHEEL ALIGNMENT7		80	150
8					120
9		CHECK WIRING7	1430	300	80
10					
11		RUST PROOF7		40	80
12					
13					
14					
15					
16					
17					
18					
19					
20					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Adnan C
05/05/23

2/S 05 Days.

Total: 421533.

4/S: 3.3/K

REMARKS:

NO OF DAYS:

AGREED FIGURE/LUMP SUM:

SURVEYOR NAME

CONTACT:

EMAIL ADD:

Hussain & Sons Enterprise Pte Ltd

2 Kaki Bukit Avenue 2

#02-16 Kaki Bukit Autohub

Singapore 417921

Phone Number: 6744 9663

Fax Number: 6748 4765

Customer:	TOYOTA ALTIS SJL9798R	Date:	5/5/2023 1:47 PM
Company:	H S AUTOMOTIVE	VIN	
License NO:	SJL9798R	Technician:	
Odometer:		Order NO:	MSA

VEHICLE ALIGNMENT REPORT

TOYOTA, COROLLA ALTIS E141, 07-12 (Customized)

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	----	2.00°	3.50°	----
		Right	----	2.00°	3.50°	----
	Camber	Left	-0.98°	-1.25°	0.25°	-0.99°
		Right	-0.96°	-1.25°	0.25°	-2.81°
	Toe	Left	0.15°	-0.09°	0.09°	0.16°
		Right	0.29°	-0.09°	0.09°	0.33°
Total		0.44°	-0.19°	0.19°	0.49°	
Rear	Camber	Left	-1.30°	-2.00°	-1.00°	-1.31°
		Right	0.46°	-2.00°	-1.00°	0.46°
	Toe	Left	0.24°	-0.03°	0.22°	0.20°
		Right	0.73°	-0.03°	0.22°	0.78°
		Total	0.97°	-0.05°	0.43°	0.98°
	Max Thrust Angle		0.25°	----		0.29°
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		----	11.25°	11.25°	----
	Right		----	11.25°	11.25°	----
Included Angle	Left		----	----	----	----
	Right		----	----	----	----
Toe Out On Turns	Left		----	----	----	----
	Right		----	----	----	----
Max Turn Inside	Left		----	----	----	----
	Right		----	----	----	----
Toe Curve Change	Left		----	----	----	----
	Right		----	----	----	----
Setback	Front		-0.07"	----	----	-0.15"
	Rear		0.13"	----	----	0.13"
Track Width Diff.			-0.31"			-0.31"
Wheel Base Diff.			-0.20"			-0.28"
Front Ride Height	Left		----	----	----	----
	Right		----	----	----	----
Rear Ride Height	Left		----	----	----	----
	Right		----	----	----	----
Frame Angle						----