

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 02/05/2023

Estimate No: EST2300171
Date: 03 May 2023

Veh Reg No: GBJ396G
Make/Model: TOYOTA DYNA 150 5MT
Chasis No: JTFAT35Y50K211749
Reg. Date: 06/12/2018
Your Ref No: GBD3906Y

Estimate Repair Cost to Vehicle No :GBJ396G

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	List Price		
1	1 PC FRT DOOR LH		
2	2 PCS FRT DOOR HINGE LH		
3	1 PC FRT DOOR HINGE GARNISH LH		
4	1 PC FRT DOOR CHECK		
5	1 PC FRT DOOR LOWER RUBBER LH		
6	1 PC FRT LH DOOR LOCK		
7	1 PC FRT LH DOOR OUTER MOULDING		
8	1 PC FRT DOOR GLASS LH		
9	1 PC FRT DOOR GLASS CHANNEL LH		
10	1 PC FRT DOOR STICKER LH		
11	1 PC FRT DOOR BLACK GARNISH LH		
12	1 PC FRT WINDSCREEN RUBBER		
13	1 PC FRT DOOR PILLER LH		
14	1 PC FRT DOOR SIDE MIRROR LH		
15	1 PC FRT DOOR MIRROR BRACKET LH		
16	1 PC FRT DOOR SMALL MIRROR LH		
17	1 PC FRT DOOR VIDEO CAMERA LH		
18	1 PC FRT FENDER LH		
19	1 PC FRT DOOR MIRROR BRACKET COVER LH		
20	1 PC HEADLAMP LH		
21	1 PC FRT GRILLE		
22	1 SET FRT GRILLE CLIPS		
23	1 PC TAIL GATE CANVAS RAIN COVER LH		
24	1 PC TAIL GATE CANVAS COVER BRACKET LH		
25	1 PC TAIL GATE SIDE RAILING LH		
		0.00	0.00
	Labour		
26	1 TO CHECK WIRING	50.00	
27	1 TO REMOVE AND REFIT DOOR TRIM LH	80.00	
28	1 TO REMOVE AND REFIT REAR DOOR GLASS LH	100.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 02/05/2023

Estimate No: **EST2300171**
Date: 03 May 2023

Veh Reg No: **GBJ396G**
Make/Model: TOYOTA DYNA 150 5MT
Chasis No: JTFAT35Y50K211749
Reg. Date: 06/12/2018
Your Ref No: GBD3906Y

Estimate Repair Cost to Vehicle No :GBJ396G

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
29	1 TO REMOVE AND REFIT TAIL GATE CANVAS RAIN COVER LH	450.00	
30	1 TO SPRAY PANEL SEALANT	80.00	
31	1 TO SPRAY PAINTING DAMAGED PORTION, INCLUDING SUPPLY OF PAINT MATERIALS SUCH AS MASKING TAPE, SAND PAPERS, PRIMER, POLISHING COMPOUND AND CHEMICAL ETC.	1,200.00	
32	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,300.00	
		3,260.00	3,260.00
		Total	S\$ 3,260.00
		Add GST @ 8%	260.80
		Total Amount Payable	<u>S\$ 3,520.80</u>

TOTAL: SINGAPORE DOLLAR THREE THOUSAND FIVE HUNDRED TWENTY AND CENTS EIGHTY ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE