



No. 39 DEFU LANE 12, SINGAPORE 539139

VEHICLES & EQUIPMENT DIVISION Tel: (65) 382 2736 FAX: (65) 6382 2817

ACCIDENT REPAIR ESTIMATES

Our Ref: TP / SMH7283H

Type of Claim : TP

Vehicle No. : SMH7283H

Make & Model : BLUECAR

Year of Manufacture : 2018

Chassis No. : VL4BCEB4RJT003465

Ins Company : MS FIRST CAPITAL

Engine No. : _____

Excess : _____

Policy No. : _____

Date of Accident : 15/04/2023

Time of Accident : _____

Suggested Days of Repair : 18

Case Owner : BLUECAR EAST ASIA PTE LTD

TP Vehicle No. : SHB1319U

Repair Estimates

Parts (a) Cost / List Price Items	<u>\$ 25,896.00</u>
Plus/Less- 20.0%	<u>\$ 5,179.20</u>
Total of Cost / List	<u>\$ 31,075.20</u>
(b) Nett Price Items	<u>\$ -</u>
Less	<u>\$ -</u>
Total of Nett Item	<u>\$ -</u>
(c) Special Nett Items	<u>\$ 3,670.00</u>
Total Parts Cost (Appendix A)	<u>\$ 34,745.20</u>
Labour (Appendix B)	<u>\$ 6,280.00</u>
Total Repair Cost	<u>\$ 41,025.20</u>

The above total will be subjected to 7% G.S.T.

Name of Surveyor	:	_____
Company	:	_____
Survey conducted on	:	_____ at _____
<u>Remarks By Surveyor</u>		
(a) The repair of this vehicle is authorized / is not authorized until further notice.		
(b) Recommended Days of Repair	:	_____ day(s)
(c) Resurvey	:	Required / Not Required
(d) Excess	:	\$ _____
(e) Signature of surveyor	:	_____ Date: _____



No. 39 DEFU LANE 12, SINGAPORE 539139
Tel: (65) 382 2736 FAX: (65) 6382 2817

VEHICLES & EQUIPMENT DIVISION

FINALIZATION REPAIR COST DETAILS

Vehicle No : SMH7283H Case Owner : BLUECAR EAST ASIA PTE LTD
 Make & Model : BLUECAR Year Manufacture : 2018
 Chassis No : VL4BCEB4RJ003465 Engine No : 0
 Date & Time : _____ Supplier : _____
 Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price		List Price	Nett Price	S/N
			Unit	Sub-Total			
1	FRONT BUMPER <i>cra</i>	1	\$ 2,073.00	\$ 2,073.00			
2	FRONT BUMPER CLIPS <i>MCC</i>	10	\$ 2.00	\$ 20.00			
3	FRONT REINFORCEMENT ?	1	\$ 340.00	\$ 340.00			
4	FRONT REINFORCEMENT BRACKET RH ?	1	\$ 280.00	\$ 280.00			
5	FRONT BUMPER SPONGE WITH CLIPS ?	1	\$ 225.00	\$ 225.00			
6	FRONT RADIATOR AIR GUIDE ?	1	\$ 79.00	\$ 79.00			
7	AIR GUIDE CLIP ?	7	\$ 2.00	\$ 14.00			
8	BOOT LID GLASS <i>cra</i>	1	\$ 966.00	\$ 966.00			
9	HATCH PININFARINA LOGO <i>MCC</i>	1	\$ 32.00	\$ 32.00			
10	HATCH PININFARINA EMBLEM <i>MCC</i>	1	\$ 62.00	\$ 62.00			
11	BOOT LID GLASS SCREW COVER X	4	\$ 18.00	\$ 72.00			
12	BOOT LID GLASS SCREW COVER X	4	\$ 2.00	\$ 8.00			
13	BOOT LID GLASS HINGE ASSY ?	1	\$ 154.00	\$ 154.00			
14	BOOT LID GLASS DAMPER RH X	1	\$ 36.00	\$ 36.00			
15	BOOT LID GLASS DAMPER LH X	1	\$ 36.00	\$ 36.00			
16	BOOT LID GLASS LOCK ?	1	\$ 132.00	\$ 132.00			
17	BOOT LID GLASS LOCK CATCH ?	1	\$ 55.00	\$ 55.00			
18	BOOT LID GLASS CATCH COVER ?	1	\$ 35.00	\$ 35.00			
19	REAR BOOT LID STICKER <i>MCC</i>	1		\$ -			\$ 40.00
20	REAR WEATHER STRIP <i>Avf</i>	1	\$ 115.00	\$ 115.00			
21	REAR TRIM ?	1	\$ 128.00	\$ 128.00			
22	REAR RH TAILAMP ASSY <i>cra</i>	1	\$ 512.00	\$ 512.00			
23	REAR RH TAILAMP FRAME <i>Dent</i>	1	\$ 403.00	\$ 403.00			
24	UPPER REAR BACKWINDOW COVER X	1	\$ 92.00	\$ 92.00			
25	THIRD BRAKE LIGHT X	1	\$ 108.00	\$ 108.00			
26	REAR BUMPER <i>missing</i>	1	\$ 1,950.00	\$ 1,950.00			
27	REAR BUMPER REINFORCEMENT <i>Dent</i>	1	\$ 275.00	\$ 275.00			
28	REAR BUMPER REINFORCEMENT BRACKET <i>Dent</i>	2	\$ 60.00	\$ 120.00			
29	REAR BUMPER REFLECTOR LH <i>missing</i>	1	\$ 173.00	\$ 173.00			
30	REAR BUMPER REFLECTOR RH <i>missing</i>	1	\$ 172.00	\$ 172.00			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL

\$ 8,517.00 \$ 8,667.00 \$ - \$ - \$ 40.00

Indeco

No. 39 DEFU LANE 12, SINGAPORE 539139

VEHICLES & EQUIPMENT DIVISION

Tel: (65) 382 2736 FAX: (65) 6382 2817

Vehicle No : SMH7283H Case Owner : BLUECAR EAST ASIA
 Make & Model : BLUECAR-(A) Year Manufacture : 2017
 Chassis No : VL4BCEB4RHT002954 Engine No : 921955Q16W44146048
 Date & Time : _____ Supplier : _____
 Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price		List Price	Nett Price	S/N
31	REAR NUMBER PLATE LAMP <i>missing</i>	2	\$ 158.00	\$ 316.00			
32	NUMBER PLATE <i>missing</i>	2		\$ -			\$ 90.00
33	REAR AIR VENT (BOOT/TRUNK) <i>ORA</i>	2	\$ 46.00	\$ 92.00			
34	CHARGER AIR INLET <i>ORA</i>	1	\$ 172.00	\$ 172.00			
35	CPL CHARGER INLET <i>?</i>	1	\$ 118.00	\$ 118.00			
36	REAR RH FENDER <i>Bent</i>	1	\$ 3,316.00	\$ 3,316.00			
37	REAR RH FENDER COVER <i>Deform</i>	1	\$ 269.00	\$ 269.00			
38	REAR RH FENDER INNER SHIELD <i>cut</i>	1	\$ 215.00	\$ 215.00			
39	REAR FENDER STICKER RH <i>MEC</i>	1		\$ -			\$ 40.00
40	REAR FENDER INNER TRIM RH <i>cut ?</i>	1	\$ 787.00	\$ 787.00			
41	REAR STORAGE TANK <i>?</i>	1	\$ 221.00	\$ 221.00			
42	LUGGAGE COMPARTMENT COVER LH <i>?</i>	1	\$ 113.00	\$ 113.00			
43	LUGGAGE COMPARTMENT COVER RH <i>Dent</i>	1	\$ 113.00	\$ 113.00			
44	REAR END PANEL <i>dent</i>	1	\$ 655.00	\$ 655.00			
45	REAR FLOOR PANEL <i>dent</i>	1	\$ 850.00	\$ 850.00			
46	REAR RH WHEEL HOUSING <i>dent</i>	1	\$ 1,150.00	\$ 1,150.00			
47	BATTERY CHARGER DOOR EXT CLADD <i>cut</i>	1	\$ 162.00	\$ 162.00			
48	ROOF LINING <i>X</i>	1	\$ 512.00	\$ 512.00			
49	SEAT BELT LH <i>X</i>	1	\$ 960.00	\$ 960.00			
50	SEAT BELT RH <i>3mm</i>	1	\$ 977.00	\$ 977.00			
51	HV CHARGER <i>?</i>	1	\$ 4,580.00	\$ 4,580.00			
52	LMP BATTERY PACK <i>?</i>	1		\$ -			\$ 3,500.00
53	Ewp High Charging Plug Prise T2 Tyco <i>?</i>	1	\$ 1,356.00	\$ 1,356.00			
54	C PILLAR NODE REINFORCEMENT RH <i>?</i>	1	\$ 295.00	\$ 295.00			
55				\$ -			
56				\$ -			
57				\$ -			
58				\$ -			
59				\$ -			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL \$17,025.00 \$ 17,229.00 \$ - \$ - \$ 3,630.00

Indeco

VEHICLES & EQUIPMENT DIVISION

No. 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

Labour

Vehicle No. : SMH7283H
 Make & Model : BLUECAR

Case Owner : PTE LTD
 Year of Manufacture : 2018

BLUECAR
 EAST ASIA

S/No	Labour Description	Estimated Price	Adjusted Price
1	LABOUR TO REMOVE FRONT ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.	\$700.00	200
2	TO PUTTY AND RESPRAY FRONT BUMPER, BONNET AND AFFECTED AREAS	\$400.00	200
3	LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.	\$2,200.00	1800
4	TO PUTTY AND RESPRAY REAR BUMPER, REAR LH FENDER, REAR RH FENDER, REAR END PANEL, REAR FLOOR PANEL, REAR RH WHEEL HOUSE, ROOF PANEL AND AFFECTED AREAS	\$1,400.00	600
5	TO APPLY RUSTPROOFING/TUFFCOATING TREATMENT TO REPLACED PARTS	\$180.00	60
6	TO REMOVE & REFIT REAR RH FENDER GLASS	\$120.00	60
7	REMOVE INTERIOR UPHOLSTERY INCLUDING INNER ROOF LINING, REAR SEATS, FLOOR PANEL LINING, ETC, IN ORDER TO FACILITATE REPAIRS TO REAR PANELS AND CHASSIS AND REFIT BACK.	\$380.00	80
8	TO REMOVE & REPLACE REAR HV CHARGER	\$120.00	?
9	TO REMOVE AND REPLACE LMP BATTERY PACK	\$280.00	?
10	TO DEACTIVATE AND ACTIVE EV HIGH VOLTAGE BATTERY AS SAFETY PRECAUTION (EV REPAIR PROTOCOL BY LTA)	\$200.00	?
11	TO CARRY OUT DIAGNOSTIC SCAN TEST AND UPDATE SYSTEM UPON COMPLETION OF COLLISION REPAIRS	\$300.00	✓
TOTAL		\$ 6,280.00	

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

11 days 4/5 8/15/23
 1/16/23 90097659