



No . 39 DEFU LANE 12, SINGAPORE 539139

VEHICLES & EQUIPMENT DIVISION Tel: (65) 382 2736 FAX: (65) 6382 2817

### ACCIDENT REPAIR ESTIMATES

Our Ref: TP / SMH7283H

Type of Claim : TP

Vehicle No. : SMH7283H

Make & Model : BLUECAR

Year of Manufacture : 2018

Chassis No. : VL4BCEB4RJT003465

Ins Company : MS FIRST CAPITAL

Engine No. : \_\_\_\_\_

Excess : \_\_\_\_\_

Policy No. : \_\_\_\_\_

Date of Accident : 15/04/2023

Time of Accident : \_\_\_\_\_

Suggested Days of Repair : 18

Case Owner : BLUECAR EAST ASIA PTE LTD

TP Vehicle No. : SHB1319U

#### Repair Estimates

Parts (a) Cost / List Price Items \$ 25,896.00

Plus/Less- 20.0% \$ 5,179.20

Total of Cost / List \$ 31,075.20

(b) Nett Price Items \$ -

Less \$ -

Total of Nett Item \$ -

(c) Special Nett Items \$ 3,670.00

**Total Parts Cost (Appendix A) \$ 34,745.20**

**Labour (Appendix B) \$ 6,280.00**

**Total Repair Cost \$ 41,025.20**

*The above total will be subjected to 7% G.S.T.*

Name of Surveyor	:	_____
Company	:	_____
Survey conducted on	:	_____ at _____
<u>Remarks By Surveyor</u>		
(a) The repair of this vehicle is authorized / is not authorized until further notice.		
(b) Recommended Days of Repair	:	_____ day(s)
(c) Resurvey	:	Required / Not Required
(d) Excess	:	:\$ _____
(e) Signature of surveyor	:	_____ Date: _____



VEHICLES & EQUIPMENT DIVISION

No . 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

**FINALIZATION REPAIR COST DETAILS**

Vehicle No	: <u>SMH7283H</u>	Case Owner	: <u>BLUECAR EAST ASIA PTE LTD</u>
Make & Model	: <u>BLUECAR</u>	Year Manufacture	: <u>2018</u>
Chassis No	: <u>VL4BCEB4RJT003465</u>	Engine No	: <u>0</u>
Date & Time	: _____	Supplier	: _____
Order By	: _____	Type of Claim	: <u>TP</u>

S/No	Part Description	QTY	Cost Price		List Price	Nett Price	S/N
			Unit	Sub-Total			
1	FRONT BUMPER	1	\$ 2,073.00	\$ 2,073.00			
2	FRONT BUMPER CLIPS	10	\$ 2.00	\$ 20.00			
3	FRONT REINFORCEMENT	1	\$ 340.00	\$ 340.00			
4	FRONT REINFORCEMENT BRACKET RH	1	\$ 280.00	\$ 280.00			
5	FRONT BUMPER SPONGE WITH CLIPS	1	\$ 225.00	\$ 225.00			
6	FRONT RADIATOR AIR GUIDE	1	\$ 79.00	\$ 79.00			
7	AIR GUIDE CLIP	7	\$ 2.00	\$ 14.00			
8	BOOT LID GLASS	1	\$ 966.00	\$ 966.00			
9	HATCH PININFARINA LOGO	1	\$ 32.00	\$ 32.00			
10	HATCH PININFARINA EMBLEM	1	\$ 62.00	\$ 62.00			
11	BOOT LID GLASS SCREW COVER	4	\$ 18.00	\$ 72.00			
12	BOOT LID GLASS SCREW COVER	4	\$ 2.00	\$ 8.00			
13	BOOT LID GLASS HINGE ASSY	1	\$ 154.00	\$ 154.00			
14	BOOT LID GLASS DAMPER RH	1	\$ 36.00	\$ 36.00			
15	BOOT LID GLASS DAMPER LH	1	\$ 36.00	\$ 36.00			
16	BOOT LID GLASS LOCK	1	\$ 132.00	\$ 132.00			
17	BOOT LID GLASS LOCK CATCH	1	\$ 55.00	\$ 55.00			
18	BOOT LID GLASS CATCH COVER	1	\$ 35.00	\$ 35.00			
19	REAR BOOT LID STICKER	1		\$ -			\$ 40.00
20	REAR WEATHER STRIP	1	\$ 115.00	\$ 115.00			
21	REAR TRIM	1	\$ 128.00	\$ 128.00			
22	REAR RH TAILAMP ASSY	1	\$ 512.00	\$ 512.00			
23	REAR RH TAILAMP FRAME	1	\$ 403.00	\$ 403.00			
24	UPPER REAR BACKWINDOW COVER	1	\$ 92.00	\$ 92.00			
25	THIRD BRAKE LIGHT	1	\$ 108.00	\$ 108.00			
26	REAR BUMPER	1	\$ 1,950.00	\$ 1,950.00			
27	REAR BUMPER REINFORCEMENT	1	\$ 275.00	\$ 275.00			
28	REAR BUMPER REINFORCEMENT BRACKET	2	\$ 60.00	\$ 120.00			
29	REAR BUMPER REFLECTOR LH	1	\$ 173.00	\$ 173.00			
30	REAR BUMPER REFLECTOR RH	1	\$ 172.00	\$ 172.00			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**TOTAL**                      \$ 8,517.00    \$ 8,667.00    \$ -    \$ -    \$ 40.00



No . 39 DEFU LANE 12, SINGAPORE 539139

VEHICLES & EQUIPMENT DIVISION

Tel: (65) 382 2736 FAX: (65) 6382 2817

Vehicle No : SMH7283H Case Owner : BLUECAR EAST ASIA  
 Make & Model : BLUECAR-(A) Year Manufacture : 2017  
 Chassis No : VL4BCEB4RHT002954 Engine No : 921955Q16W44146048  
 Date & Time : \_\_\_\_\_ Supplier : \_\_\_\_\_  
 Order By : \_\_\_\_\_ Type of Claim : TP

S/No	Part Description	QTY	Cost Price		List Price	Nett Price	S/N
31	REAR NUMBER PLATE LAMP	2	\$ 158.00	\$ 316.00			
32	NUMBER PLATE	2		\$ -			\$ 90.00
33	REAR AIR VENT (BOOT/TRUNK)	2	\$ 46.00	\$ 92.00			
34	CHARGER AIR INLET	1	\$ 172.00	\$ 172.00			
35	CPL CHARGER INLET	1	\$ 118.00	\$ 118.00			
36	REAR RH FENDER	1	\$ 3,316.00	\$ 3,316.00			
37	REAR RH FENDER COVER	1	\$ 269.00	\$ 269.00			
38	REAR RH FENDER INNER SHIELD	1	\$ 215.00	\$ 215.00			
39	REAR FENDER STICKER RH	1		\$ -			\$ 40.00
40	REAR FENDER INNER TRIM RH	1	\$ 787.00	\$ 787.00			
41	REAR STORAGE TANK	1	\$ 221.00	\$ 221.00			
42	LUGGAGE COMPARTMENT COVER LH	1	\$ 113.00	\$ 113.00			
43	LUGGAGE COMPARTMENT COVER RH	1	\$ 113.00	\$ 113.00			
44	REAR END PANEL	1	\$ 655.00	\$ 655.00			
45	REAR FLOOR PANEL	1	\$ 850.00	\$ 850.00			
46	REAR RH WHEEL HOUSING	1	\$ 1,150.00	\$ 1,150.00			
47	BATTERY CHARGER DOOR EXT CLADD	1	\$ 162.00	\$ 162.00			
48	ROOF LINING	1	\$ 512.00	\$ 512.00			
49	SEAT BELT LH	1	\$ 960.00	\$ 960.00			
50	SEAT BELT RH	1	\$ 977.00	\$ 977.00			
51	HV CHARGER	1	\$ 4,580.00	\$ 4,580.00			
52	LMP BATTERY PACK	1		\$ -			\$ 3,500.00
53	Ewp High Charging Plug Prise T2 Tyco	1	\$ 1,356.00	\$ 1,356.00			
54	C PILLAR NODE REINFORCEMENT RH	1	\$ 295.00	\$ 295.00			
55				\$ -			
56				\$ -			
57				\$ -			
58				\$ -			
59				\$ -			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**TOTAL**      \$17,025.00    \$ 17,229.00    \$ -    \$ -    \$ 3,630.00



VEHICLES & EQUIPMENT DIVISION

No . 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

## Labour

**BLUECAR  
EAST ASIA  
PTE LTD**  
**2018**

Vehicle No. : SMH7283H  
Make & Model : BLUECAR

Case Owner :  
Year of Manufacture : 2018

S/No	Labour Description	Estimated Price	Adjusted Price
1	LABOUR TO REMOVE FRONT ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.	\$700.00	
2	TO PUTTY AND RESPRAY FRONT BUMPER, BONNET AND AFFECTED AREAS	\$400.00	
3	LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.	\$2,200.00	
4	TO PUTTY AND RESPRAY REAR BUMPER, REAR LH FENDER, REAR RH FENDER, REAR END PANEL, REAR FLOOR PANEL, REAR RH WHEEL HOUSE, ROOF PANEL AND AFFECTED AREAS	\$1,400.00	
5	TO APPLY RUSTPROOFING/TUFFCOATING TREATMENT TO REPLACED PARTS	\$180.00	
6	TO REMOVE & REFIT REAR RH FENDER GLASS	\$120.00	
7	REMOVE INTERIOR UPHOLSTERY INCLUDING INNER ROOF LINING, REAR SEATS, FLOOR PANEL LINING, ETC, IN ORDER TO FACILITATE REPAIRS TO REAR PANELS AND CHASSIS AND REFIT BACK.	\$380.00	
8	TO REMOVE & REPLACE REAR HV CHARGER	\$120.00	
9	TO REMOVE AND REPLACE LMP BATTERY PACK	\$280.00	
10	TO DEACTIVATE AND ACTIVE EV HIGH VOLTAGE BATTERY AS SAFETY PRECAUTION (EV REPAIR PROTOCOL BY LTA)	\$200.00	
11	TO CARRY OUT DIAGNOSTIC SCAN TEST AND UPDATE SYSTEM UPON COMPLETION OF COLLISION REPAIRS	\$300.00	
	<b>TOTAL</b>	<b>\$ 6,280.00</b>	

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.