

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI23004484/SNP3Q2**Date:** 07/06/2023**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MQ003064
Claimant Vehicle No :	SHC8262Y	Insured Vehicle No :	SNA9685T
Date of Loss:	03/05/2023	Nature of Claim:	TP
		Claim No:	M2302781

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC8262Y	Engine No:	G4LEKU422227
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVLU193068
Reg. Date:	29/04/2021 (Man. Year: 2019)	Odometer:	225726 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,693.60	55.00	1,638.60	96.75
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	820.00	630.00	190.00	23.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,524.60	696.00	1,828.60	72.43
+ GST 8.00/8.00% (S\$)	201.97	55.68	146.29	72.43
Nett Amount (S\$)	2,726.57	751.68	1,974.89	72.43

INSPECTION

Date of Assignment:	03/05/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	04/05/2023	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 07 Jun 2023)
Parts: 192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHC8262Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	459.40 FL	*- FL
2	1		*REAR BUMPER CENTRE MOULDING	Not Necessary	451.25 FL	*- FL
3	1		*REAR BUMPER LOWER MOULDING	Not Necessary	155.00 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	394.80 FL	*- FL
5	10		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
6	1		*REAR BUMPER FOGLAMP	Not Necessary	201.50 FL	*- FL
7	1		*REAR SMART KEY ANTENNA	Not Necessary	40.50 FL	*- FL
8	1		*REAR BUMPER TOW COVER	Not Necessary	98.80 FL	*- FL
9	1		*REVERSE SENSORS	Not Necessary	180.00 F	*- F
10	1		*REAR NO.PLATE WITH TRIM COVER	Cracked	55.00 F	*55.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,058.25	55.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	364.65	0.00
Total Parts (\$\$)	1,693.60	55.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINTING	New	300.00	250.00
3	R/I REVERSE SENSORS	New	120.00	30.00
Gross Labour Cost (\$\$)			820.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >