



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 68661666



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Contact No 24/05/	Cust No/Name	/ONG ZONG YAN, MARK
	Reg No/Reg Date	SMY829R*# / 16/02/2021
	Date In/Mileage	19/05/2023/ 25244
	Chassis No	KNAF3416MM5097686
	Engine No	G4FGKH740432
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	KLK STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00080	Cash	31/05/2023/ 08:38	LER	972 / Mars Ler	19226			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z TEXT								
ACCIDENT ON 29/04/2023 ALONG TAMPINES STREET 62								
OWNER CLAIMING THIRD PARTY								
LOSS OF USE								
TP # GBK1244A TP INS: MS FIRST CAPITAL								
M SUNDRY								80.00
TO APPLY SEALANT KIT ON NEW PANEL								
M SUNDRY								100.00
TO APPLY ANTI-CORROSION ON REAR ACCIDENT AFFECTED AREAS								
M SUNDRY								50.00
C&C BADGE								
E PNT88000								100.00
TO CHECK AND TEST REVERSE SENSOR								
E PNT88000								220.00
TO SUPPLY REVERSE SENSOR SET								
E PNT88000								320.00
TO REMOVE AND REINSTALL TRIMMING AND CAPERTING TO GIVE WAY								
ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS								
E PNT88000								2240.00
TO REPLACE TRUNK LID PANEL,REAR BUMPER,REAR BODY KIT,REINFORCEMENT,ETC								
-INCLUDING TRANSFER TRUNK LID COMPONENT & MECHANISM PART								
-TO REPAIR REAR END PANEL								
STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS								
E PNT98000								2200.00
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS								
E PNT88000								50.00
TO SUPPLY REAR NUMBER PLATE WITH CASING								
A 10028901								280.00
TO CONDUCT DIAGNOSTIC CHECK BY KDS AND CLEAR TROUBLE CODE								
A 90000001								80.00
CHECK WIRING & ELECTRICAL SYSTEM								
M SUNDRY								30.00
SUNDRIES								

Confirm & accepted by

Finalization

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 68661666



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Contact No 24/05/	Cust No/Name	/ONG ZONG YAN, MARK
	Reg No/Reg Date	SMY829R*# / 16/02/2021
	Date In/Mileage	19/05/2023/ 25244
	Chassis No	KNAF3416MM5097686
	Engine No	G4FGKH740432
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	KLK STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	31/05/2023/ 08:38	LER	972 / Mars Ler	19226
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
X COVER-RR BUMPER		1.00	749.00	00.00	749.00
X CLIP		10.00	1.00	00.00	10.00
X COVER-RR BUMPER FOG LAMP,LH		1.00	19.00	00.00	19.00
X BODY KIT		1.00	1721.00	00.00	1721.00
X PANEL ASSY-TRUNK LID		1.00	1566.00	00.00	1566.00
X LOGO ASSY-KIA SUB		1.00	32.00	00.00	32.00
X EMBLEM-CERATO		1.00	28.00	00.00	28.00
X LAMP ASSY-CENTER GARNISH		1.00	690.00	00.00	690.00
X LAMP ASSY-REAR COMB INSIDE,LH		1.00	608.00	00.00	608.00
Estimate					

Confirm & accepted by

8% GST on **Nett** **11,173.00**
 11173.00 **893.84**

Finalization

Total Payable **12,066.84**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.