



Your Ref : S3M04M4S

Date: 15th May 2023

Our Ref : CS/HSB23004488/Aqp3m4

M/s HSBC Life (Singapore) Pte Ltd

10 Marina Boulevard

#48-01 Marina Bay Financial Centre Tower 2

Singapore 018983

(The Motor Claims Department)

Attn: Garnet Low

Dear Sirs/Madam,

AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SJG 3407K

INSURED VEHICLE: SHA 8099M

ACCIDENT ON 29/04/2023

Instruction was received to inspect the vehicle Reg. No. SJG 3407K. The inspection was conducted on 04/05/2023 at the premises of M/s 2020 Spray Painting Pte Ltd, 8 Kaki Bukit Avenue 4, #03-19, Premier @ Kaki Bukit, Singapore 415875.

The following vehicle information was recorded:

Registration Number	: SJG 3407K
Make/Model	: Toyota Estima 2.4X A
Year of Registration	: 2008
Body Colour	: White
Chassis Number	: ACR500072432
Engine Capacity	: 2362 cc
Speedometer Reading	: 239809 km

The vehicle sustained damages at the rear portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$	2,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$	526.00)
Nett Liability	S\$	1,474.00
	=====	

Vehicle Inspected By:



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser



K.K.LAU

MSc(Eng M), B Eng(Hons), PEng(UK),

MASME(USA), B Bus(Aust),MBA(UK),

IEng(UK), MIIIE(mech), MinstAEA, MFIEA,

MIRTE,MIMI,MSAE,MCIAd, AM,NIJAAR(USA),

AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.