



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR ED21J*RA

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information
WIP No 64634
Reg No/Reg Date ED21J*RA / 26/02/2021
Date In/Mileage 1 / 0
Chassis No W1N2477872J2328062
Engine No 28291480523917
Make/Model MB/GLA 200 SPORT UTILITY VEH
Colour/Trim 027 787 Mountain Gr/ 041 101 ARTICO Leat

Account No	Terms	Date/Time Printed	CSE	Operator
WA000001	Credit	02/05/2023/ 11:41	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : SP2004270937 // 28-04-2023 DRIVE IN/EXCESS : 28-04-2023 // TBA DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT			0.10	380.00
S BPNSUB SUPPLY 1 PC REG. PLATE WITH HOUSING.NETT PURCHASE ORDER NO:				60.00
A BPILAB REMOVE & REPLACE FRONT BUMPER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH.				1440.00
A BPIRES RESPRAY FRONT BUMPER			0.07	1000.00
M FRT BUMPER	1.00	1171.52	00.00	1171.52
M LICENSE PLATE BASE	1.00	104.48	00.00	104.48
M CT/F BOTTOM TRIM	1.00	101.34	00.00	101.34
M CT/F BOTTOM CHROME	1.00	283.83	00.00	283.83
M CT/F BOTTOM GRILLE	1.00	106.59	00.00	106.59
M RH/F BOTTOM GRILLE	1.00	126.57	00.00	126.57
M FRT IMPACT ABSORBER	1.00	134.64	00.00	134.64
M RADIATOR GRILLE SUPPORT	1.00	585.46	00.00	585.46

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
approved by the approved by Insurance Company

Acknowledged by Repairer

Signature:

Date:

Authorized signatory and company stamp

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Nett 5,494.43
8% GST on 5494.43 439.55

Total Payable 5,933.98

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG