



**TLM Automobile Pte Ltd**  
**1 Defu Lane 6 Singapore 539365**  
**UEN number: 202244624K**

*not authorized  
 on  
 15/5/23  
 2/5 \$ 1400/  
 2 days  
 weight after repair*

Third Party Insurer: AIG

Date of accident : 28 Apr 2023

Date: 04 May 2023

Mr Tan Jin Qin Pearlyn (Chen Yanqin)

Estimate To Repair

SMD133A - BMW X1 SDRIVE 18L

Chassis No : WBA32AA0105T37241

S/No	Quantity	Description	Amount
<b>LIST ITEMS</b>			
1	1 pc	rear bumper <i>o/s</i>	\$ 1,089.36
2	1 pc	rear bumper center <i>gross</i>	\$ 299.69
3	1 pc	rear bumper tow cover <i>gross</i>	\$ 47.70
4	1 pc	rear bumper lower garnish <i>n</i>	\$ 256.96
5	1 pc	o/s rear bumper reflector <i>n</i>	\$ 60.50
6	1 pc	rear bumper freinforcement <i>n</i>	\$ 553.75
			\$ 2,307.96
Less 5%			\$ 115.40
			\$ 2,192.56
<b>SPECIAL NETT ITEMS</b>			
7	2 ps	rear bumper reverse sensor @ \$225.60 <i>su</i>	\$ 511.20
8	1 pc	rear bumper reverse sensor cover <i>n</i>	\$ 10.50
			\$ 521.70
<b>LABOUR CHARGES &amp; MISC</b>			
1		To check electrical lighting concerned.	\$ 80.00
2		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,000.00
3		Putty and spray painting of the affected portion.	\$ 800.00
			\$ 1,880.00
Grand Total			\$ 4,594.26
			<p><i>2-</i> 1436.75</p> <p>5%</p> <p>1364.91</p> <p>420</p> <hr/> <p>1784.91</p> <p>202</p> <hr/> <p>1427</p>

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Not authorized by Repairer