



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)		Ref:	CS/SPF23004497/Kny3e2
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1		Date:	20/06/2023
HEMMANT ROAD SINGAPORE 438675			
ATTN: LUI LAI KUEN		Code:	SPF
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	QX 1206P	Veh. Inspected	SLN 4233C
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2023/028	Excess (\$)	0.00
Assign From	LUI LAI KUEN	Assign Date	03/05/2023
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	HYUNDAI ELANTRA (A)	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KMHD841CMHU333460	Colour	METALLIC BLACK
Odometer	175281 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	MICHELIN	6 mm
L/H Front Tyre	195/65 R15	MICHELIN	6 mm
R/H Rear Tyre	195/65 R15	MICHELIN	6 mm
L/H Rear Tyre	195/65 R15	MICHELIN	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	27/04/2023	Inspection Date	05/05/2023
Survey held at	6 MARSILING LANE S739145		
Repairer	CENTURY MOTORS PTE LTD		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.			
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	