



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 03/05/2023

User ID : JeongCH

Section A - Accident Details			
Registration Number	SMB3576X		
Case Reference Number	BUS/04/23/5020		
Registration Date	2/2/2015		
Company Type	SMRT Buses Ltd		
Make	ALEXANDER DENNIS		
Model	ENVIRO 500		
Name of Driver	Zhu Peng		
Type of Accident	Side Swipe		
Accident Date and Time	4/13/2023 5:10 PM		
Accident Reported Date and Time	4/25/2023 2:03 PM		
Is Surveyor Required?	No		
Survey by			
Vehicle is Towed Back?	No		
Towed Back Date and Time			
Replacement Vehicle issued?	No		
Job Card Number			
Special Instruction to ARC,if any	SMB3576X - RIGHT REAR PORTION SJC6500X (TP) - INSURED WITH AIG		
Prepared Date and Time	5/3/2023 1:46 PM		
Chassis Number	SFD76CLR5EMTL3728		
Mileage			
Work Shop			
Repair Completion Date and Time			

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,060.00	\$0.00
Total Spray Cost	\$0.00	\$0.00
Total Spare Part Cost	\$874.82	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,934.82	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	03/05/2023 1:58 PM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 03/05/2023

User ID : JeongCH

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope				Quotation from AR				Adjusted by Surveyor, if applicable	
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.				\$1,060.00					
Total Labour				\$1,060.00					
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS				\$878.00					
Total Spray Painting & Panel Beating				\$878.00					
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6011253		2038001L24	Door, Fuel Filler Access	1.00	\$375.00	10.00	\$337.50	Replace	
6011242	BODY RH	30106514	PANEL,EXTERIOR:R/H,F OR ADL DD BUS	1.00	\$511.14	10.00	\$460.03	Replace	
6011242	BODY RH	30106514	PANEL,EXTERIOR:R/H,F OR ADL DD BUS	1.00	\$464.09	100.00	\$0.00	Repair	
4006314	CONSUMABLE		ADHESIVE:DIRECT GLAZING	8.00	\$37.00	0.00	\$296.00	Replace	
Total					\$1,387.23		\$1,093.53		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									