

Section A - Accident Details

Registration Number	SHD6177T
Case Reference Number	TAX/04/23/2072
Registration Date	27/Jul/2016
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	TEO KIOK SENG
Type of Accident	Head On
Accident Date and Time	30/Apr/2023 10:10 AM
Accident Reported Date and Time	2/May/2023 12:43 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118303
Special Instruction to ARC, if any	DAMAGE TO THE FRONT LHS OF OUR TAXI
Prepared Date and Time	2/May/2023 3:30 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$300.00
Total Spray Cost	\$1,574.00	\$700.00
Total Spare Part Cost	\$8,365.37	\$3,054.90
Total Other Cost	\$436.00	\$60.00
TOTAL COST	\$11,389.37	\$4,114.90
Lump Sum Total	\$11,400.00	\$4,100.00 (L/S)
Number of Repair Days	8.0	3.0
Prepared / Adjusted By	Boon Chew Tay	Taufikh (LKK)/ AIG
ARC / Surveyor Sign Off Date	09/05/2023 1:54 PM	09/05/2023 11:29 AM
Signature		
Remarks	REQ NBV INITIAL = 8 DAYS WITH SUPPLEMENTARY = 0 DAY TOTAL = 8 DAYS	LUMPSUM REPAIR / AFTER PAINT PHOTO , FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Taufikh (LKK) / HP : 9749 5749 / Email : taufikh@lkkauto.com

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2305-0224	Invoice Number	
Quotation Date	19.05.2023	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$1,014.00	\$300.00 ✓
Total Labour	\$1,014.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00 ✓
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$220.00	\$100.00 ✓
TO RESPRAY FRONT HOOD	\$378.00	\$200.00 ✓
TO RESPRAY FRONT SUPPORT PANEL	\$220.00	\$0.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00 ✓
Total Spray Painting & Panel Beating	\$1,574.00	\$700.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$30.00 ✓
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00 ✓
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$436.00	\$60.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		16534-37010	SUPPORT RADIATOR, LH	0.00	\$23.40	0.00	\$0.00	Replace	Check
		53420-47070	HOOD HINRE LH	0.00	\$63.70	0.00	\$0.00	Replace	Not Given
		51410-12105	UNDER COVER CENTER	0.00	\$511.20	0.00	\$0.00	Replace	Check
		53852-47020	FENDER LINER PAD, FR WHEEL. LH	0.00	\$56.30	0.00	\$0.00	Replace	Not Given
		81220-12230	FOG LAMP LH	0.00	\$319.30	0.00	\$0.00	Replace	Check
		75374-47051	NAME PLATE (HYBRID)	1.00	\$59.20	25.00	\$44.40	Replace	Replace
		53201-47902	SUPPORT SUB-ASSY	0.00	\$1,839.70	0.00	\$0.00	Replace	Check
		81521-47050	LENS & BODY,FR TURN LH	1.00	\$581.40	10.00	\$523.26	Replace	Replace
		52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$567.90	0.00	\$0.00	Replace	Not Given
		53111-47040	GRILLE, RADIATOR	0.00	\$389.30	0.00	\$0.00	Replace	Check
		51444-12050	UNDER COVER SIDE/LH	0.00	\$52.50	0.00	\$0.00	Replace	Check

X
X
X XNN
X
X
✓ NEC
X
✓ CRA
X
X X NN
X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 20/05/2023

User ID : PohSuan

		53410-47070	HOOD HINGE RH	0.00	\$63.70	0.00	\$0.00	Replace	Not Given	X
		53802-47050	FENDER FRT/LH	1.00	\$916.30	25.00	\$687.23	Replace	Replace	√ BT
		53113-47040	GRILLE, RADIATOR LOWER NO.2	0.00	\$118.30	0.00	\$0.00	Replace	Check	X
		53301-47060	HOOD PANEL	1.00	\$988.50	100.00	\$0.00	Replace	Repair	R
		52611-47080	BUMPER ENERGY ABSORBER FRT	1.00	\$97.60	25.00	\$73.20	Replace	Replace	√ CRA
		53876-47030	FENDER LINER FRT/LH	0.00	\$195.40	0.00	\$0.00	Replace	Check	X
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	Replace	√ NEC
		52128-47903	COVER, FR BUMPER HOLE LH	0.00	\$21.40	0.00	\$0.00	Replace	Not Given	X
		81170-47500	HEAD LAMP LH	1.00	\$1,075.40	10.00	\$967.86	Replace	Replace	√ CRA
		76851-47020	BUMPER LIP FRT	1.00	\$182.70	25.00	\$137.03	Replace	Replace	√ CUT
		53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	1.00	\$389.90	25.00	\$292.43	Replace	Replace	√ CUT
		57014-47030	ARM SUB-ASSY, FR BUMPER LH	0.00	\$284.00	0.00	\$0.00	Replace	Not Given	X
		81529-47060	BRACKET, FR TURN CENTER LH	0.00	\$76.60	0.00	\$0.00	Replace	Check	X
		75310-47010	EMBLEM FRONT	1.00	\$98.70	25.00	\$74.03	Replace	Replace	√ NEC
		57013-47030	ARM SUB-ASSY, FR BUMPER RH	0.00	\$284.00	0.00	\$0.00	Replace	Not Given	X
		81529-47050	BRACKET, FR TURN LOWER LH	0.00	\$34.50	0.00	\$0.00	Replace	Check	X
		52119-47930	BUMPER FRT	1.00	\$602.60	25.00	\$451.95	Replace	Replace	√ TN
		52116-47040	BUMPER SUPPORT F/LH	1.00	\$86.20	25.00	\$64.65	Replace	Replace	√ CRA
		81529-47040	BRACKET, FR TURN UPPER LH	0.00	\$32.40	0.00	\$0.00	Replace	Check	X
		52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$159.30	0.00	\$0.00	Replace	Check	X
Total					\$10,176.20		\$3,352.04			

*All XX = NN

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
		81220-12230	FOG LAMP LH	1.00	\$319.30	25.00	\$239.48	Replace	Replace	√ CRA
		81529-47040	BRACKET, FR TURN UPPER LH	1.00	\$32.40	25.00	\$24.30	Replace	Replace	√ CRA
		81529-47060	BRACKET, FR TURN CENTER LH	1.00	\$76.60	25.00	\$57.45	Replace	Replace	√ CRA
		81529-47050	BRACKET, FR TURN LOWER LH	1.00	\$34.50	25.00	\$25.88	Replace	Replace	√ DIS
		52618-47050	BUMPER FRT ABSORBER LOWER	1.00	\$159.30	25.00	\$119.48	Replace	Replace	√ DIS
Total					622.10		466.59			

3,818.63

-20%

3054.90

L/S \$4,100/-

+ 300.00

+ 760.00

4,114.90