

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG23004525/ANCM4**Date:** 03/08/2023**REFERENCE**

Insured/Claimant:	LIM YOUN BOON ALEX	Policy No:	1900010033-03	
Date of Loss:	02/05/2023	Nature of Claim:	OD	Claim No: 3336030572SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMH7438D</b>		
Make & Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Engine No:	CVK076040
Reg. Date:	30/01/2019 (Man. Year: 2018)	Chassis No:	WAUZZZF4XKA030709
Colour:	White	Odometer:	70937 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$114,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	19,747.00	6,229.04	13,517.96	68.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,552.00	3,202.00	12,350.00	79.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>35,299.00</b>	<b>9,431.04</b>	<b>25,867.96</b>	<b>73.28</b>
<b>- Excess (\$\$)</b>	600.00	600.00	0.00	0.00
<b>(\$\$)</b>	34,699.00	8,831.04	25,867.96	74.55
<b>+ GST 8.00/8.00% (\$\$)</b>	2,775.92	706.48	2,069.44	74.55
<b>Nett Amount (\$\$)</b>	<b>37,474.92</b>	<b>9,537.52</b>	<b>27,937.40</b>	<b>74.55</b>

**INSPECTION**

Date of Assignment:	04/05/2023		
Date Inspected:	03/05/2023	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	6.0 days		

**Adjuster:** ADRIAN LING**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	3,374.00 FS	*2,699.20 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	496.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Necessary	264.00 FS	*210.80 FS
4	1		*REAR BUMPER SPOILER	Cut	292.00 FS	*233.60 FS
5	1		*REAR BUMPER TRIM - CENTER LOWER	Not Necessary	345.00 FS	*- FS
6	1		*REAR BUMPER BRACKET - LH	Not Necessary	138.00 FS	*- FS
7	1		*REAR BUMPER REFLECTOR - LH	Cracked	49.00 FS	*38.72 FS
8	1		*REAR OUTER TAIL LIGHT - LH	Cracked	1,200.00 FS	*960.00 FS
9	1		*REAR OUTER TAIL LIGHT TRIM - LH	Not Necessary	36.00 FS	*- FS
10	1		*REAR INNER TAIL LIGHT - LH	Cut	1,200.00 FS	*960.00 FS
11	1		*REAR INNER TAIL LIGHT TRIM - LH	Not Necessary	36.00 FS	*- FS
12	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	1,197.00 FS	*- FS
13	2		*REAR BUMPER IMPACT BAR GASKET - LH / RH	Not Necessary	34.00 FS	*- FS
14	1		*REAR BUMPER GUIDE SECTION - LH UPPER	Damaged	52.00 FS	*41.44 FS
15	1		*REAR BUMPER GUIDE SECTION - LH LOWER	Damaged	27.00 FS	*21.36 FS
16	1		*REAR BUMPER HOLDING STRAP - LH	Not Necessary	100.00 FS	*- FS
17	1		*REAR PARKING AID SENSOR - INNER / OUTER 2PIECES	Missing (1Piece Only)	543.00 FS	*212.00 FS
18	4		*REAR PARKING AID SEAL RING	Not Necessary	11.00 FS	*- FS
19	1		*SET REAR BUMPER WIRING	Not Necessary	751.00 FS	*- FS
20	1		*REAR AERIAL RETAINER - LH	Not Necessary	30.00 FS	*- FS
21	1		*REAR TELEPHONE AERIAL	Not Necessary	197.00 FS	*- FS
22	1		*REAR VENT TRIM	Cracked	77.00 FS	*60.96 FS
23	1		*PACKING ADHESIVE	Necessary	22.00 FS	*16.88 FS
24	1		*AUDI EMBLEM	Necessary	152.00 FS	*121.60 FS
25	1		*A4 INSCRIPTION	Necessary	110.00 FS	*87.60 FS
26	1		*REAR SIDE PANEL - LH	Repair	4,612.00 FS	*- FS
27	1		*REAR WINDOW	Not Necessary	1,362.00 FS	*- FS
28	1		*REAR QUARTER WINDOW - LH	Not Necessary	726.00 FS	*- FS
29	2		*WINDOW PRIMER	Not Necessary	47.00 FS	*- FS
30	1		*REAR WHEEL HOUSING LINER - LH	Crumpled	281.00 FS	*224.40 FS
31	1		*EXHAUST TAIL PIPE TRIM - LH	Bent	406.00 FS	*324.80 FS
32	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
33	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
34	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
35	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
36	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*- FS
37	1		*REAR WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
38	1		*SUNDRIES	Necessary	500.00 FS	*15.68 FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$) 19,747.00 6,229.04**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTON	New	360.00	360.00
2	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGED AND RENEW WHERE NECESSARY	New	1,400.00	0.00
3	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBANG ETC	New	1,400.00	0.00
4	TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS TO FACILITATE RENEWAL LHS REAR FENDER	New	600.00	0.00
5	TO INSTALL SOLAR FILM FOR ALL AFFECTED GLASSES	New	400.00	0.00
6	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN	New	200.00	0.00
7	TO DISMANTLE AND RENEW REAR BUMPER. TO CUT OUT AND WELD LHS REAR FENDER. TO REPAIR REAR LID. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,000.00	1,000.00
8	TO RESPRAY REAR BUMPER, REAR LID, LHS REAR FENDER, DRAIN CHANNEL, LHS SILL PANEL, DOOR ENTRANCE, ROOF CHANNEL AND REAR END PANELLING	New	6,000.00	1,650.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>15,552.00</b>	<b>3,202.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >