

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way  
#09-16  
Singapore 079120From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Noor Amran, Noor Yussyuhaila

Date: 04 May 2023

**Preliminary Advice**

Vehicle No	: SMH7438D	Accident Date	: 02/05/2023
Make	: AUDI A4	Policy No.	: 1900010033-03
Assignment Date	: 04/05/2023	Excess	: S\$0.00
Date of Inspection	: 03/05/2023	Est. Duration of Repair	: 14
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	35,299.00
Revised Amount	:S\$	13,247.50
Check Items (Estimated)	:S\$	14,849.00
Total	:S\$	28,096.50

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	114,000.00
COE / PARF Rebate	:S\$	48,926.00
Salvage Value	:S\$	
Margin for Repair	:S\$	65,074.00

**Remarks**

- ( x ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.