

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0423/2023/EQ
DATE : 3-May-23
WIP : 18763

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 3/5/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

6 days exclude 1 S

Johnny Boo 26 Jun

OWNER'S NAME : MR LIM YOUN BOON ALEX
ADDRESS : 29 FERNVALE CLOSE
#02-19
SINGAPORE 797464
TELEPHONE : HP +65 97304885
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900010033-03
VEHICLE NO : **SMH 7438 D**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI
MODEL YEAR : 30/1/2019
ENGINE NO : CVK 076040
CHASSIS NO : WAUZZZF4XKA030709
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 2-May-23
PLACE OF ACCIDENT : TPE TOWARDS LOYANG BEFORE LORONG HALUS

unday
23



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMH 7438 D**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00	\$ 360.00
2	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,400.00	
3	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,400.00	
4	TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS TO FACILITATE RENEWAL LHS REAR FENDER.	S/N \$	600.00	
5	TO INSTALL SOLAR FILM FOR ALL AFFECTED GLASSES.	S/N \$	400.00	
6	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$	200.00	
TOTAL LABOUR CHARGES		: \$	4,360.00	\$ 360.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMH 7438 D

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		c/f		\$ 360.00
7	TO DISMANTLE AND RENEW REAR BUMPER. TO CUT OUT AND WELD LHS REAR FENDER. TO REPAIR REAR LID. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	5,000.00	\$ 1,000.00
8	TO RESPRAY REAR BUMPER, REAR LID, LHS REAR FENDER, DRAIN CHANNEL, LHS SILL PANEL, DOOR ENTRANCE, ROOF CHANNEL AND REAR END PANELLING.	\$	6,000.00	\$ 1,650.00
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 15,552.00	\$ 3,202.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 7438 D

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER	1	\$ 3,374.00	\$	2,699.20
2	REAR BUMPER FIXING PARTS	1	\$ 496.00		
3	REAR BUMPER SECURING STRIP	1	\$ 264.00	\$	210.80
4	REAR BUMPER SPOILER	1	\$ 292.00	\$	233.60
5	REAR BUMPER TRIM - CENTER LOWER	1	\$ 345.00		
6	REAR BUMPER BRACKET - LH	1	\$ 138.00		
7	REAR BUMPER REFLECTOR - LH	1	\$ 49.00	\$	38.72
8	REAR OUTER TAIL LIGHT - LH	1	\$ 1,200.00	\$	960.00
9	REAR OUTER TAIL LIGHT TRIM - LH	1	\$ 36.00		
10	REAR INNER TAIL LIGHT - LH	1	\$ 1,200.00	\$	960.00
11	REAR INNER TAIL LIGHT TRIM - LH	1	\$ 36.00		
12	REAR BUMPER REINFORCEMENT BEAM	1	\$ 1,197.00		
13	REAR BUMPER IMPACT BAR GASKET - LH / RH	2	\$ 34.00		
14	REAR BUMPER GUIDE SECTION - LH UPPER	1	\$ 52.00	\$	41.44
15	REAR BUMPER GUIDE SECTION - LH LOWER	1	\$ 27.00	\$	21.36
16	REAR BUMPER HOLDING STRAP - LH	1	\$ 100.00		
17	REAR PARKING AID SENSOR - INNER / OUTER	2	\$ 543.00	\$	212.00
18	REAR PARKING AID SEAL RING	4	\$ 11.00		
19	REAR BUMPER WIRING SET	1	\$ 751.00		
20	REAR AERIAL RETAINER - LH	1	\$ 30.00		
SUB TOTAL SPARE PARTS		:	\$ 10,175.00	\$	5,377.12

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 7438 D

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS
		<i>c/f</i>		\$	5,377.12
21	REAR TELEPHONE AERIAL	1	\$	197.00	
22	REAR VENT TRIM	1	\$	77.00	\$ 60.96
23	PACKING ADHESIVE	1	\$	22.00	\$ 16.88
24	AUDI EMBLEM	1	\$	152.00	\$ 121.60
25	"A4" INSCRIPTION	1	\$	110.00	\$ 87.60
26	REAR SIDE PANEL - LH	1	\$	4,612.00	
27	REAR WINDOW	1	\$	1,362.00	
28	REAR QUARTER WINDOW - LH	1	\$	726.00	
29	WINDOW PRIMER	2	\$	47.00	
30	REAR WHEEL HOUSING LINER - LH	1	\$	281.00	\$ 224.40
31	EXHAUST TAIL PIPE TRIM - LH	1	\$	406.00	\$ 324.80
32	ACRYLIC SEALANT	S/N	\$	180.00	
33	CAVITY WAX	S/N	\$	140.00	
34	STONE CHIP	S/N	\$	180.00	
35	METAL FILLER POWDER	S/N	\$	280.00	
36	1/4 GLASS SEALANT	S/N	\$	100.00	
37	REAR WINDSCREEN SEALANT	S/N	\$	200.00	
38	SUNDRIES		\$	500.00	\$ 15.68
TOTAL SPARE PARTS		:	\$	19,747.00	\$ 6,229.04
TOTAL LABOUR CHARGES		:	\$	15,552.00	\$ 3,202.00
GRAND TOTAL		:	\$	35,299.00	\$ 9,431.04

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-08/06/23



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT