

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wenyo

Date: 11 May 2023

Preliminary AdviceInsured Vehicle No : SLW241H
TP Vehicle No : SKV8761M
Make : TOYOTA WISH
Date of Inspection : 08/05/2023
Inspection At : Z-ONE AUTOMOTIVE PTE LTD
1 KAKI BUKIT AVENUE 6
#01-87 AUTOBAY@KAKI BUKIT
SINGAPORE 417883Accident Date : 26/04/2023
Assignment Date : 04/05/2023
Est. Duration of Repair : 4**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,092.95
Revised Amount	:S\$	3,654.62
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,654.62
Lump Sum Repair	:S\$	2,900.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	47,000.00
COE / PARF Rebate	:S\$	25,369.00
Salvage Value	:S\$	
Margin for Repair	:S\$	21,631.00

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (X) Lump Sum repair
- (X) The above survey was conducted on a 'without prejudice' basis. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.