

L H Express Motor Trading

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
Tel : 64817221

Oh Hang Khim
Blk 436 Choa Chu Kang Ave 4
#10-505
Singapore 680436

Not Authorized
L1 Pump & 725.0h
Penny After Rain
Folay

Vehicle No : SLD 8813 E
Make : Toyota Wish
Year : 2016

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear tail-gate assy			Ry	\$1,275.60	✓
1 pc	Rear windscreen moulding			an	\$115.60	✓
1 pc	Rear tail-gate outer chrome garnish	321.20		cm	\$355.10	✓
1 pc	Rear wiper motor	398.20		Al/m	\$487.60	✓
1 pc	Rear tail-gate emblem " Logo "			ru	\$55.60	✓
1 pc	Rear tail-gate emblem " Elegance "			ru	\$45.20	✓
1 pc	Rear tail-gate emblem - Badge			ru	\$48.70	✓
1 pc	Rear tail-gate inner trim board	508.10		m/gm	\$680.10	✓
1 pc	Rear tail-gate inner lock			nd	\$359.10	✓
1 pc	Rear tail-gate inner lock sensor	161.70		cm	\$291.50	✓
2 pcs	Rear tail-gate lamp				\$974.20	✓
2 pcs	Rear tail-lamp				\$1,100.40	✓
2 pcs	Rear no plate lamp				\$47.10	✓
1 pc	Rear boot rubber			su	\$94.20	X
1 pc	Rear end panel (outer)	546.80		su	\$269.70	X
1 pc	Rear end panel inner garnish			su	\$577.10	✓
1 pc	Rear bumper			m/gm	\$284.90	✓
2 pcs	Rear bumper side retainer			Bu	\$684.20	✓
2 pcs	Rear bumper bracket				\$75.10	✓
2 pcs	Rear bumper reflector				\$105.10	✓
1 pc	Rear o/s fender	1121.35			\$65.10	✓
2 pcs	Rear fender inner trim board			su	\$130.20	X
1 pc	Rear exhaust silencer			Bu	\$1,355.60	✓
					\$1,100.20	✓
					\$655.70	X
					\$12,401.30	
					Less 25 %	\$3,100.33
						\$9,300.97

n/s for o/s m
o/s m/gm

o/s d/s

o/s nd

o/s before

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

balance c/f \$9,300.97

balance b/f \$9,300.97

S. Nett Item

1 pc	Rear reverse camera
1 pc	Rear reverse sensor
1 pc	Rear windscreen sealant
20 pcs	Bumper clip

shun	\$400.00	2501
shun	\$200.00	✓
na	\$55.00	4051
\$2.00	na	\$40.00
		<u>\$695.00</u>

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.	\$1,500.00	12001
To putty & spray paint on rear accident affected portion.	\$1,500.00	9001
Check/reconnect wiring.	\$45.00	201
To spray anti rust on accident affected portion.	\$120.00	601
Remove/renew rear windscreen glass	\$120.00	✓
Remove/refit rear boot lid lock mechanism, inner trim to new lid..	\$100.00	601
Remove/renew rear exhaust silencer	\$150.00	601
	<u>\$1,530.00</u>	
Total	<u>\$13,530.97</u>	