

# L H Express Motor Trading

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541  
Tel : 64817221

Oh Hang Khim  
Blk 436 Choa Chu Kang Ave 4  
#10-505  
Singapore 680436

Vehicle No : SLD 8813 E  
Make : Toyota Wish  
Year : 2016

NOT Authorized  
L1 Pump &  
Resurvey After Repair  
Today

| Qty | Description | Unit Price | Amount |
|-----|-------------|------------|--------|
|-----|-------------|------------|--------|

## Estimate Cost Of Repair

|       |                                     |               |          |           |             |   |
|-------|-------------------------------------|---------------|----------|-----------|-------------|---|
| 1 pc  | Rear tail-gate assy                 |               |          | By        | \$1,275.60  | ✓ |
| 1 pc  | Rear windscreen moulding            |               |          | an        | \$115.60    | ✓ |
| 1 pc  | Rear tail-gate outer chrome garnish |               |          | cm        | \$355.10    | ✓ |
| 1 pc  | Rear wiper motor                    |               |          |           | \$487.60    | ? |
| 1 pc  | Rear tail-gate emblem " Logo "      |               |          | na        | \$55.60     | ✓ |
| 1 pc  | Rear tail-gate emblem " Elegance "  |               |          | na        | \$45.20     | ✓ |
| 1 pc  | Rear tail-gate emblem - Badge       |               |          | na        | \$48.70     | ✓ |
| 1 pc  | Rear tail-gate inner trim board     |               |          |           | \$680.10    | ? |
| 1 pc  | Rear tail-gate inner lock           |               |          | na        | \$359.10    | ✓ |
| 1 pc  | Rear tail-gate inner lock sensor    |               |          |           | \$291.50    | ? |
| 2 pcs | Rear tail-gate lamp                 | n/s for alarm | \$487.10 |           | \$974.20    | ✓ |
| 2 pcs | Rear tail-lamp                      |               | \$550.20 |           | \$1,100.40  | ? |
| 2 pcs | Rear no plate lamp                  |               | \$47.10  | sm        | \$94.20     | X |
| 1 pc  | Rear boot rubber                    |               |          | sm        | \$269.70    | X |
| 1 pc  | Rear end panel ( outer )            |               |          |           | \$577.10    | ? |
| 1 pc  | Rear end panel inner garnish        |               |          |           | \$284.90    | ? |
| 1 pc  | Rear bumper                         |               |          | Br        | \$684.20    | ✓ |
| 2 pcs | Rear bumper side retainer           | o/s o/s       | \$75.10  |           | \$150.20    | ✓ |
| 2 pcs | Rear bumper bracket                 |               | \$105.10 |           | \$210.20    | ? |
| 2 pcs | Rear bumper reflector               |               | \$65.10  | sm        | \$130.20    | X |
| 1 pc  | Rear o/s fender                     |               |          | Br        | \$1,355.60  | ✓ |
| 2 pcs | Rear fender inner trim board        | n/s sm x      |          |           | \$1,100.20  |   |
| 1 pc  | Rear exhaust silencer               | o/s ?         | \$550.10 |           | \$655.70    | ? |
|       |                                     |               |          |           | \$12,401.30 |   |
|       |                                     |               |          | Less 25 % | \$3,100.33  |   |
|       |                                     |               |          |           | \$9,300.97  |   |

balance c/f \$9,300.97

### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

SLD 8813 E

balance b/f \$9,300.97

S. Nett Item

1 pc Rear reverse camera  
1 pc Rear reverse sensor  
1 pc Rear windscreen sealant  
20 pcs Bumper clip

|        |             |                 |             |
|--------|-------------|-----------------|-------------|
|        | <i>Sn</i>   | \$400.00        | <i>x</i>    |
|        | <i>Shon</i> | \$200.00        | <i>✓</i>    |
|        | <i>na</i>   | \$55.00         | <i>405a</i> |
| \$2.00 | <i>na</i>   | \$40.00         | <i>✓</i>    |
|        |             | <u>\$695.00</u> |             |

Labour Charges

|   |                    |             |
|---|--------------------|-------------|
| Remove/renew the above parts including knocking, welding & cutting. | \$1,500.00         | <i>1200</i> |
| To putty & spray paint on rear accident affected portion.           | \$1,500.00         | <i>900</i>  |
| Check/reconnect wiring.   | \$45.00            | <i>201</i>  |
| To spray anti rust on accident affected portion.                    | \$120.00           | <i>601</i>  |
| Remove/renew rear windscreen glass                                  | \$120.00           | <i>✓</i>    |
| Remove/refit rear boot lid lock mechanism, inner trim to new lid..  | \$100.00           | <i>601</i>  |
| Remove/renew rear exhaust silencer                                  | \$150.00           | <i>601</i>  |
| Total   | <u>\$13,530.97</u> |             |