

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/AIS23004545/KQY3M4**Date:** 12/05/2023REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SP2003108123  
**Claimant Vehicle No :** SML8475T **Insured Vehicle No :** GBL738T  
 Date of Loss: 01/05/2023 Nature of Claim: TP Claim No: 2023 32007847KC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SML8475T**  
 Make & Model: KIA CERATO, 1.6 EX (A) Engine No: G4FGKH738460  
 Reg. Date: 07/06/2019 (Man. Year: 2018) Chassis No: KNAF3416MK5045428  
 Colour: Metallic Grey Odometer: 40114 km  
 Engine Capacity: 1591 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16  
 Front Left Side: Yokohama 9 mm Rear Left Side: Yokohama 9 mm  
 Front Right Side: Yokohama 9 mm Rear Right Side: Yokohama 9 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>              | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                              | 0.00              | 0.00              | 0.00              |               |
| Miscellaneous Items                | 0.00              | 0.00              | 0.00              |               |
| Labour                             | 0.00              | 0.00              | 0.00              |               |
| Paintwork Labour                   | 0.00              | 0.00              | 0.00              |               |
| Towing                             | 0.00              | 0.00              | 0.00              |               |
| <b>Nett Amount (S\$)</b>           | <b>0.00</b>       | <b>0.00</b>       | <b>0.00</b>       |               |
| <b>Global Sum Settlement (S\$)</b> |                   | <b>0.00</b>       |                   |               |

INSPECTION

Date of Assignment: 04/05/2023  
 Date Inspected: 05/05/2023 Inspected At: Hiap Lek Automobile Trading (HQ)  
 160 Sin Ming Drive, #05-17 Sin Ming Autocity  
 Singapore 575722  
 Estimated Period of Repair: 11.0 days

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$9,000.00  
-\$11,000.00

REPAIR DETAILS

|               |                                                                                                                                                                              |                                                         |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------|
| Reference     |                                                                                                                                                                              |                                                         |
| Part Source:  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 12 May 2023)           |
| Parts:        | 143                                                                                                                                                                          | KIA CERATO 1.6 EX (A) (Catalogue:Merimen Singapore 1.0) |
| Labour:       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                       |
| Print Code:   | (Unsubmitted, no print-code for SML8475T)                                                                                                                                    |                                                         |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                         |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                         |

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >