



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909		Ref: CS/UOI23004548/Acy3e2 Date: 13/07/2023 Code: UOI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMH 72X	Veh. Inspected	SLL 7853D
Policy No.		Coverage (\$)	0.00
Claim No.	M11D00122305	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	04/05/2023
2. Vehicle Particulars & Condition			
Make & Model	SUBARU XV	c.c	1600
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JF1GP3KC5HG203336	Colour	BLUE
Odometer	82243 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/55 R17	LAUFENN	6 mm
L/H Front Tyre	225/55 R17	LAUFENN	6 mm
R/H Rear Tyre	225/55 R17	LAUFENN	6 mm
L/H Rear Tyre	225/55 R17	LAUFENN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	02/05/2023	Inspection Date	04/05/2023
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	