



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)		Ref:	CS/SPF23004552/Uvy3m4
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1		Date:	17/05/2023
HEMMANT ROAD SINGAPORE 438675			
ATTN: LUI LAI KUEN		Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	QX 405R	Veh. Inspected	SLL 450D
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2023/027	Excess (\$)	0.00
Assign From	LUI LAI KUEN	Assign Date	03/05/2023
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ESTIMA (A)	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	ACR507134673	Colour	GREY
Odometer	86908 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/50 ZR18	KUMHO	7 mm
L/H Front Tyre	225/50 ZR18	KUMHO	7 mm
R/H Rear Tyre	225/50 ZR18	MICHELIN	7 mm
L/H Rear Tyre	225/50 ZR18	MICHELIN	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.			
DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	29/04/2023	Inspection Date	09/05/2023
Survey held at	EURO SUCCESS SERVICES PTE LTD 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	