

# LCL APPRAISER PTE LTD

Blk 416 Pasir Ris Dr 6 #08-235, Singapore 510416  
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783  
Reg No: 201000228E

## VEHICLE INSPECTION REPORT

To: Sangye Quek Qi Ping  
C/o: YS Auto Werkz  
10 Kaki Bukit Road 2  
#01-03 First East Centre, Singapore 417868

Date : 12 April 2023  
Our ref : YS/04/2301/TP

Accident Date : 29 March 2023  
Inspection Date : 4 April 2023  
Repairer Name : YS Auto Werkz  
10 Kaki Bukit Road 2  
#01-03 First East Centre, Singapore 417868

Type of Survey : Third Party

### PARTICULARS OF VEHICLE

Registration No	: SNE 8766 D	Year / Capacity	: 2017 / 999 cc
Make / Model	: Audi A3	Colour	: Black
Chassis No	: WAUZZZ8V2H1070457	Mileage	: 97366
Engine No	: CHZ359448		

### CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	: Bridgestone	205/55 R16	5 mm	Sport
Front Offside	: Bridgestone	205/55 R16	5 mm	Sport
Rear Nearside	: Bridgestone	205/55 R16	5 mm	Sport
Rear Offside	: Bridgestone	205/55 R16	5 mm	Sport

### GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear portion.  
(Details refer to the photographs attached)

Enclosed number of photographs: 103 copies

### REMARKS

This inspection was conducted entirely on a "**WITHOUT PREJUDICE**" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

### RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$8,600.00** on a contractual basis.

Under normal circumstances, the repair period would be about 6 (Six) working days.

# **SCL APPRAISER PTE LTD**

Vehicle Registration No.: SNE 8766 D

Our Ref No.:

YS/04/2301/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

## SPARE PARTS - LIST ITEMS

1	Rear boot lid	Damage	\$ 1,632.00	\$ 1,632.00	
2	Rear boot lamps	Damage	\$ 1,050.00	\$ 1,050.00	
1	Rear boot lock	Damage	\$ 246.00	\$ 246.00	
1	Rear boot logo	Necessary	\$ 94.00	\$ 94.00	
1	Rear boot rubber	Necessary	\$ 211.00	\$ 211.00	
1	Rear boot "A3" emblem	Necessary	\$ 94.00	\$ 94.00	
1	Rear boot "TESI" emblem	Necessary	\$ 68.50	\$ 68.50	
2	Rear taillamps	Damage	\$ 1,513.60	\$ 1,513.60	
1	Rear end panel	Damage	\$ 885.00	\$ 885.00	XR
1	Rear end panel inner garnish	Intact	\$ 216.00		Xnn
1	Rear bumper	Damage	\$ 1,586.20	\$ 1,586.20	
1	Rear bumper inner frame garnish	Damage	\$ 129.00	\$ 129.00	
1	Rear bumper lower diffuser	Damage	\$ 492.00	\$ 492.00	
1	Rear bumper n/s reflector	Damage	\$ 85.20	\$ 85.20	
1	Rear bumper reinforcement	Damage	\$ 655.00	\$ 655.00	
2	Rear bumper side retainers	Necessary	\$ 110.00	\$ 110.00	
4	Rear bumper PDC sensors @ \$165 each	Damage	\$ 920.00	\$ 920.00	660
			<b>\$ 9,987.50</b>	<b>\$ 9,771.50</b>	
			<i>Less 10%</i>	<i>\$ 998.75</i>	<i>\$ 977.15</i>
<b>Total Cost - List Items</b>			<b>\$ 8,988.75</b>	<b>\$ 8,794.35</b>	8626.50 7763.85

## SPECIAL NETT ITEMS

1	Rear bumper clip (1 set)	Necessary	\$ 60.00	\$ 60.00	40
<b>Total Cost - Special Nett items</b>			<b>\$ 60.00</b>	<b>\$ 60.00</b>	

**Total cost of parts**

**\$ 9,048.75 \$ 8,854.35**

Vehicle Registration No.: SNE 8766 D

Our Ref No.:

YS/04/2301/TP

S/No	Description	Repairer's Estimate	Revised Amount
------	-------------	---------------------	----------------

**Total cost of parts c/f**

\$ 9,048.75

\$ 8,854.35

**LABOUR**

1	To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$ 80.00	\$ 50.00
2	To remove and refit inner garnishes, inner trim to assist repair.	\$ 150.00	\$ 120.00 60
3	To remove and refit rear reverse sensor.	\$ 120.00	\$ 120.00 50
4	To transfer boot lid mechanism and wiring assembly to assist repair.	\$ 80.00	\$ 80.00 60
5	To apply undercoating on repaired and replaced panel.	\$ 100.00	\$ 60.00 40
6	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,080.00	\$ 750.00
7	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,000.00	\$ 660.00

1670

**GRAND TOTAL**
**\$ 11,658.75 \$ 10,694.35**

9473.85  
l/s\$7550  
6 days

Vehicle Registration No.: SNE 8766 D

Our Ref No.:

YS/04/2301/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 8,600.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

**Disclaimer**

*The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.*

**C L APPRAISER PTE LTD**



Cheong K. H.  
Automotive Appraiser











































































































