

ASS. REC. BY:

REF:

AIG / 23004558 / Ky

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMA 1102 Z

Yr Regn:

05, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Shuttle

C.C

1496

Colour

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

417308

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GK8

1201583

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

185 / 60 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen

Front

Rear

R/Bal.

P

mm

R/Bal.

P

mm

L/Bal.

P

mm

L/Bal.

P

mm

D.O.A.

19/4/23

D.O.I.

24/4/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

26/4 21:50 @ 4500 Cebu

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation

S - RS - SI

Fees

Others

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

TOTAL

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No: 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

Not Authorised
L1 Reg 84500h
Permy After Perm
5 days

REPAIR ESTIMATE SMA1102Z

No.	Qty	List Items	
1	1	Rear bumper	\$ B 1,150.60 ✓
2	2	Rear bumper side reflector cover	\$ P 90.00 X
3	2	Rear bumper side reflector	\$ P 94.00 X
4	1	Rear bumper tow cover	\$ P 16.50 X
5	2	Rear bumper side retainer	\$ P 53.00 X
6	2	Rear bumper inner side foam	\$ P 113.00 2X
7	1 set	Rear bumper clips	\$ P 40.00 ✓
8	1	Rear tailgate	\$ B 1,293.00 ✓
9	1	Rear tailgate outer chrome garnish/handle	\$ P 383.00 X
10	1	Rear tailgate number plate lamp	\$ P 96.00 X
11	1	Rear tailgate centre "H" logo	\$ P 38.00 ✓
12	1	Rear tailgate LH "SHUTTLE" emblem	\$ P 55.00 ✓
13	1	Rear tailgate top lock	\$ P 157.00 ✓
14	1	Rear tailgate lower lock catch	\$ P 27.50 X
15	1	Rear tailgate weatherstrip	\$ P 168.00 50% 84500h
16	1	Rear tailgate inner trim board	\$ P 320.00 ✓
17	1 set	Rear tailgate inner trim board clips	\$ P 60.00 ✓
18	1 set	Rear tailgate windscreen moulding	\$ P 120.00 ✓
19	2	Taillamp	\$ P 1,041.00 X
20	1	Rear end panel	\$ P 560.80 ✓
21	1	Rear end panel top garnish	\$ P 155.50 ✓
22	1	Rear end panel keyless sensor	\$ P 85.00 ✓
23	1	Rear spare tyre panel	\$ P 956.00 X
24	1	Rear spare tyre panel top board	\$ P 655.00 ✓
25	1 set	Rear fender inner side garnish clips	\$ P 60.00 X
			\$ 7,787.90
Less 20%			\$ 1,557.58
Total :			\$ 6,230.32

Special Nett Items

26	1 set	Reverse sensors	\$ P 280.00 2005N
27	1 set	Reverse camera	\$ P 650.00 X
28	1	Rear number plate	\$ P 50.00 455N
29	1 set	Rear windscreen sealant	\$ P 50.00 405N
30	1 set	Rear end panel/spare tyre panel sealant	\$ P 120.00 X
Total :			\$ 1,150.00

Labour

1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$ 1,100.00 600
2	To putty and spray Spray Paintings charges.	\$ 1,000.00 660
3	To remove, refix rear windscreen glass.	\$ 140.00 120
4	To check wirings and lightings.	\$ 40.00 20
5	To remove, refit reverses sensors & reverse camera.	\$ 120.00 50
6	To remove, refit rear tailgate fittings.	\$ 80.00 60

7	To remove, refit rear upholstery and attachments.	\$	120.00	601
8	To supply and apply anti rust treatment	\$	90.00	601
Total :		\$	2,690.00	

Total Parts and Labour : \$ 10,070.32

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date: