

ASS. REC. BY:

REF: A/G/ 23 0045601kp

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s Trans Cab

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: S140 52157 Yr Regn: 01, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Pous c.c. 1798

Colour mp. white / Blw A/C: Insured / Std / NI / NA

Sp. Reading 274317 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDK B3FU 403 079088

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD / Rlm or

Tyre Size: Continental 195/65R15

R/ Fire 178

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front _____ Rear _____

R/Bal. 9 mm R/Bal. 3 mm

L/Bal. 9 mm L/Bal. 3 mm

D.O.A. 27/4/23 D.O.I. 28/4/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or None N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>30/5</u>	<u>21 Pmp @ 6700k Cabul</u>

Date/Time, File Pass to? : Prell. Report
 : Final Report

Days Of Repair: _____
Resurvey No. of Trlp: _____

Survey Fee:	
Transportation:	
S - RS. SI	
Others	
TOTAL	

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Report Format :
Lump Sum / I.B.I: (\$)

NOT AUTHORIZED
 1/1/2023 @ 6700h

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHD5215Z

AAD2304-

Vehicle No.:
 Chassis No.:
 Co UEN.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident:
 Third Party Insurer:
 Date of Registration:

28 APR 2023

SHD5215Z
 JTDKB3FU403079086
 200303878K
 TOYOTA
 PRIUS
 27/4/2023
 GBD9074H/AIG
 17/1/2019

PART	LIST
1 COVER, REAR BUMPER	\$ 558.39 ✓
1 COVER, REAR BUMPER, LOWER	\$ 19.43 X
1 GUARD, REAR BUMPER, CENTER	\$ 726.92 ✓
1 SEAL, REAR BUMPER SIDE, LH	\$ 111.41 ✓
1 SEAL, REAR BUMPER SIDE, RH	\$ 111.41 X
1 FILLER, REAR BUMPER EXTENSION, RH	\$ 155.72 X
1 FILLER, REAR BUMPER EXTENSION, LH	\$ 155.72 ✓
1 RETAINER, REAR BUMPER SIDE, LH	\$ 147.11 ✓
1 RETAINER, REAR BUMPER SIDE, RH	\$ 148.58 X
1 REINFORCEMENT SUB-ASSY, REAR BUMPER	\$ 419.90 ✓
1 COVER, FLOOR UNDER, RH	\$ 220.50 X
1 COVER, FLOOR UNDER, LH	\$ 304.92 X
1 COVER, REAR FLOOR	\$ 290.43 X
1 PANEL ASSY, DECK TRIM SIDE, LH	\$ 448.98 X
1 COVER, DECK TRIM, REAR	\$ 159.39 X
1 PANEL SUB-ASSY, BODY LOWER BACK	\$ 824.46 X
1 LENS & BODY, REAR COMBINATION LAMP, LH	\$ 559.13 X
1 LENS AND BODY, REAR LAMP, LH	\$ 634.73 ✓
1 COVER, REAR COMBINATION LAMP, LH	\$ 81.48 ✓
1 PANEL SUB-ASSY, BACK DOOR	\$ 1,443.86 ✓
1 SPOILER SUB-ASSY, REAR	\$ 1,986.92 ✓
1 SEAL, REAR SPOILER	\$ 21.32 ✓
1 STAY ASSY, BACK DOOR, LH	\$ 305.66 X
1 STAY ASSY, BACK DOOR, RH	\$ 305.66 X
1 HINGE ASSY, BACK DOOR, LH	\$ 77.18 X
1 HINGE ASSY, BACK DOOR, RH	\$ 77.18 X
1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$ 1,171.38 ✓
1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$ 68.88 ✓
1 PLATE, BACK DOOR NAME, NO.1	\$ 68.88 ✓
1 ORNAMENT SUB-ASSY, BACK DOOR	\$ 90.30 ✓

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel Nc Fax No. : 62571330
 CO./ GST Reg. No. 201019626G
SHD5215Z

AAD2304-

TOTAL	\$	11,695.77
25%	\$	2,923.94
	\$	8,771.82

SPECIAL NETT

1SET PARKING AID	\$	700.00	<i>220SA</i>
1 REAR BUMPER CLIP	\$	65.00	<i>60SA</i>
1 REAR SPOILER CLIP	\$	65.00	<i>✓</i>
1 BOOT STICKER TRANSCAB	\$	100.00	<i>30SA</i>
1 BOOT STICKER TEL NO.	\$	100.00	<i>30SA</i>
1 REAR LH BUMPER RETAINER CLIP	\$	65.00	<i>X</i>
1 REAR RH BUMPER RETAINER CLIP	\$	65.00	<i>X</i>
1 END PANEL INNER TRIM CLIP	\$	60.00	<i>X</i>
1 REAR BUMPER PROTECTOR	\$	180.00	<i>X</i>
2 WINDSCREEN SEALANT	\$	150.00	<i>80SA</i>
1 WINDSCREEN MOULDING	\$	200.00	<i>✓</i>
1 WINDSCREEN INNER SPONGE SEAL	\$	130.00	<i>30SA</i>
TOTAL	\$	1,880.00	
TOTAL PARTS	\$	10,651.82	

LABOUR

To rust-proofing of the affected areas.	\$	600.00	<i>X</i>
Putty and spray painting of the affected portion.	\$	1,200.00	<i>80SA</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,000.00	<i>60SA</i>
To transfer of tailgate fittings and conduct water seepage test.	\$	170.00	<i>60A</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	<i>60A</i>
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00	<i>✓</i>

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHD5215Z

AAD2304-

To transfer of tailgate fittings and conduct water seepage test.

\$ *Amnew* 170.00 *201 X*

To transfer of bootlid fittings, attachments and perform water seepage test.

\$ 170.00 *601*

To reinstall rear bumper parking sensor.

\$ 170.00 *501*

To check steering geometry and computer wheel alignment

\$ *na* 220.00 *X*

To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.

\$ *na* 170.00 *X*

TOTAL \$ 5,420.00

OVERALL TOTAL \$ 16,071.82

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: