

ASS. REC. BY:

REF:

CTZ/ 23004561/Kp

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

1 1/2 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S/HO 91514

Yr Regn:

06, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

C.C

1798

Colour

M.P. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

499219

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDK B3FU 203081130

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Wanli

Front

Rear

R/Bal.

2

mm

R/Bal.

9

mm

L/Bal.

2

mm

L/Bal.

9

mm

D.O.A.

6/4/23

D.O.I.

2/5/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

3/5 / 15mg @ 1000k Calm

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS. SI

Fines

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Not Authorized
 C/Smp \$1000/-

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHD9151Y

AAD2304-126

Vehicle No.:

Chassis No.:

Co UEN.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

02 MAY 2023

SHD9151Y

JTDKB3FU203081130

200303878K

TOYOTA

PRIUS

6/4/2023

GBH6047K/ China.

18/6/2019

PART

LIST

- 1 COVER, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 GUARD, REAR BUMPER, CENTER
- 1 SEAL, REAR BUMPER SIDE, LH
- 1 SEAL, REAR BUMPER SIDE, RH
- 1 FILLER, REAR BUMPER EXTENSION, RH
- 1 FILLER, REAR BUMPER EXTENSION, LH
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 COVER, FLOOR UNDER, RH
- 1 COVER, FLOOR UNDER, LH
- 1 COVER, REAR FLOOR
- 1 COVER, DECK TRIM, REAR
- 1 PANEL SUB-ASSY, BODY LOWER BACK

\$	R	558.39	X
\$	Sm	19.43	X
\$	nd	726.92	
\$	Sm	111.41	
\$	Sm	111.41	
\$	Sm	155.72	
\$	Sm	155.72	
\$	Sm	147.11	
\$	Sm	148.58	
\$	As	419.90	
\$	Sm	220.50	
\$	Sm	304.92	
\$	Sm	290.43	
\$	Sm	159.39	
\$	R	824.46	
TOTAL \$		4,354.25	
25% \$		1,088.56	
\$		3,265.68	

SPECIAL NETT

- 1SET PARKING AID
- 1 REAR BUMPER CLIP
- 1 REAR LH BUMPER RETAINER CLIP
- 1 REAR RH BUMPER RETAINER CLIP
- 1 END PANEL INNER TRIM CLIP
- 1 REAR BUMPER PROTECTOR
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

\$	Sm	700.00	X
\$	na	65.00	X
\$	na	65.00	X
\$	na	65.00	X
\$	na	60.00	X
\$	na	180.00	30sm
\$	na	150.00	X
\$	na	200.00	X
\$	na	130.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHD9151Y**AAD2304-126**

TOTAL	\$	1,615.00
TOTAL PARTS	\$	4,880.68

LABOUR

To rust-proofing of the affected areas.	\$	nn 600.00	X
Putty and spray painting of the affected portion.	\$	1,200.00	2201
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,000.00	1501
To transfer of tailgate fittings and conduct water seepage test.	\$	nn 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	4 380.00	X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	4 170.00	X
To transfer of tailgate fittings and conduct water seepage test.	\$	4 170.00	X
To reinstall rear bumper parking sensor.	\$	4 170.00	X
To check steering geometry and computer wheel alignment	\$	4 220.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	4 170.00	X

TOTAL \$ 5,250.00**OVERALL TOTAL \$ 10,130.68**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

1 1/2 days

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHD9151Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	27 Apr 2023
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2C24812
Chassis No.:	JTDKB3FU203081130
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	18 Jun 2019
First Registration Date:	18 Jun 2019
Transfer Count:	0
Actual ARF Paid:	\$14,247.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Jun 2027
PARF Rebate Amount:	\$10,685.00
Intended COE Rebate Details	
COE Expiry Date:	17 Jun 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$23,872.00
COE Rebate Amount:	\$12,357.00
Total Rebate Amount:	\$23,042.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 27 Apr 2023

OK