

Not Authorized
 C1 Imp @ 750%

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No Fax No. : 62571330
 CO./ GST Reg. No. 201019626G
 SHD9151Y

AAD2304-126

Vehicle No.:
 Chassis No.:
 Co UEN.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident:
 Third Party Insurer:
 Date of Registration:

02 MAY 2023

SHD9151Y
 JTDKB3FU203081130
 200303878K
 TOYOTA
 PRIUS
 6/4/2023
 GBH6047K/ China.
 18/6/2019

PART

LIST

- 1 COVER, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 GUARD, REAR BUMPER, CENTER
- 1 SEAL, REAR BUMPER SIDE, LH
- 1 SEAL, REAR BUMPER SIDE, RH
- 1 FILLER, REAR BUMPER EXTENSION, RH
- 1 FILLER, REAR BUMPER EXTENSION, LH
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 COVER, FLOOR UNDER, RH
- 1 COVER, FLOOR UNDER, LH
- 1 COVER, REAR FLOOR
- 1 COVER, DECK TRIM, REAR
- 1 PANEL SUB-ASSY, BODY LOWER BACK

\$	R	558.39	X
\$	Rn	19.43	X
\$	Rd	726.92	
\$	Rn	111.41	} X
\$	Rn	111.41	
\$	Rn	155.72	
\$	Rn	155.72	
\$	Rn	147.11	
\$	Rn	148.58	
\$	R	419.90	
\$	Rn	220.50	
\$	Rn	304.92	
\$	Rn	290.43	
\$	Rn	159.39	
\$	R	824.46	

TOTAL \$ 4,354.25
 25% \$ 1,088.56
 \$ 3,265.68

SPECIAL NETT

- 1SET PARKING AID
- 1 REAR BUMPER CLIP
- 1 REAR LH BUMPER RETAINER CLIP
- 1 REAR RH BUMPER RETAINER CLIP
- 1 END PANEL INNER TRIM CLIP
- 1 REAR BUMPER PROTECTOR
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

\$	Rn	700.00	X
\$	na	65.00	X
\$	na	65.00	X
\$	na	65.00	X
\$	na	60.00	X
\$	na	180.00	300.00
\$	na	150.00	X
\$	na	200.00	X
\$	na	130.00	X

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel Nc Fax No. : 62571330
 CO./ GST Reg. No. 201019626G
 SHD9151Y

AAD2304-126

TOTAL	\$	1,615.00
TOTAL PARTS	\$	4,880.68

LABOUR

To rust-proofing of the affected areas.	\$	nn	600.00	X
Putty and spray painting of the affected portion.	\$		1,200.00	2201
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$		2,000.00	1501
To transfer of tailgate fittings and conduct water seepage test.	\$	nn	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	4	380.00	X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	4	170.00	X
To transfer of tailgate fittings and conduct water seepage test.	\$	4	170.00	X
To reinstall rear bumper parking sensor.	\$	4	170.00	X
To check steering geometry and computer wheel alignment	\$	4	220.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	4	170.00	X
TOTAL	\$		5,250.00	
OVERALL TOTAL	\$		10,130.68	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

1/4 days