

REF: CTZ/ 23004562/Ky

Kenneth

TOTAL

Not Authorized
L1 Rmp & 2150h

AAD2304-123

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9148H

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

02 MAY 2023

SHD9148H

JTDKB3FU403080643

200303878K

TOYOTA

PRIUS

8/4/2023

SKW7416L/ Chikan

24/5/2019

PART

- 1 COVER, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 GUARD, REAR BUMPER, CENTER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 FILLER, REAR BUMPER EXTENSION, RH
- 1 PANEL SUB-ASSY, QUARTER, RH
- 1 LINER, REAR WHEEL HOUSE, RH
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 COVER, REAR COMBINATION LAMP, RH
- 1 LENS AND BODY, REAR LAMP, RH (LOWER)
- 1 LENS & BODY, REAR COMBINATION LAMP, RH (UPPER)

LIST

\$	Bul/m3cm	558.39	✓
\$	RL	19.43	X
\$	RL	726.92	X
\$	RL	419.90	X
\$	m3cm	155.72	✓
\$	B	1,099.46	✓
\$	RL	176.09	X
\$	RL	824.46	X
\$	RL	81.48	X
\$	RL	634.73	X
\$	RL	570.15	X

TOTAL \$ 5,266.70
25% \$ 1,316.67
\$ 3,950.02

Special Nett

- 1SET PARKING AID
- 1 REAR BUMPER CLIP
- 1 FENDER LINER CLIP
- 1 REAR TAIL LAMP CLIP
- 1 END PANEL INNER TRIM CLIP
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

\$	RL	700.00	X
\$	RL	65.00	60.00
\$	RL	65.00	X
\$	RL	65.00	X
\$	RL	60.00	X
\$	RL	150.00	X
\$	RL	200.00	X
\$	RL	130.00	X

TOTAL \$ 735.00

TOTAL PARTS \$ 8,543.40

AAD2304-123

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9148H

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	301
Putty And Spray Painting Of The Affected Portion.	\$	1,800.00	5001
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	1001
To Check Electrical Lighting Concerned.	\$	170.00	201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	6001
To check steering geometry and computer wheel alignment	\$	na 220.00	X
To transfer of rear fender panel fittings, attachment and perform water seepage test.	\$	na 170.00	X

TOTAL \$ **5,990.00**

Over All Total \$ **18,483.42**

(PART-BY-PART) Repair Days

04 Days ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 878K

Vehicle Details

Vehicle No.: SHD9148H

Vehicle to be Exported: Yes

Intended Deregistration Date: 27 Apr 2023

Vehicle Make: TOYOTA

Vehicle Model: PRIUS 5DR HATCHBACK (AUTO)

Primary Colour: Red

Manufacturing Year: 2018

Engine No.: 2ZR2C18176

Chassis No.: JTDKB3FU403080643

Maximum Power Output: 90.0 kW (120 bhp)

Open Market Value: \$26,605.00

Original Registration Date: 24 May 2019

First Registration Date: 24 May 2019

Transfer Count: 0

Actual ARF Paid: \$14,247.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 23 May 2027

PARF Rebate Amount: \$10,685.00

Intended COE Rebate Details

COE Expiry Date: 23 May 2027

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$22,309.00

COE Rebate Amount: \$11,350.00

Total Rebate Amount: \$22,035.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 27 Apr 2023

OK