

Not Authorized
 L/Sing &
 Resurvey After Paving
 6 days

Vehicle Insured : GY 3795 E
 Accident Date : 02-May-2023

No. : 32914

Date : 05-May-2023

Our Ref : 023246 (CHINA) / SANDRA

PAGE : 1

CLEAR CHANNEL SINGAPORE PTE LTD
 Singapore

ESTIMATED COST OF REPAIR FOR TOYOTA HIACE (2982CC) (2014) GBD922U

1 pc rear bumper	<i>By/LM</i>	545.80	✓
2 pcs rear bumper side retainer (LH/RH)	@ S\$ 30.50 <i>DIY</i>	61.00	—
10 pcs rear bumper clips	@ S\$ 5.50 <i>me</i>	55.00	✓
4 pcs rear bumper lower bracket	@ S\$ 41.30 <i>mt</i>	165.20	✓
2 pcs taillamp (LH/RH)	@ S\$367.70 <i>d/sym</i>	735.40	✓
2 pcs taillamp lower apron garnish (LH/RH)	@ S\$112.40 <i>mt/LM</i>	224.80	✓
2 pcs taillamp lower apron garnish side bracket (LH/RH)	@ S\$ 30.50	61.00	7
1 pc rear end panel-outer	<i>By</i>	412.40	—
1 pc rear end panel top moulding	<i>mt</i>	126.90	—
1 pc tailgate	<i>By</i>	2,448.00	—
1 pc tailgate lock	<i>mt</i>	332.70	✓
1 pc tailgate lock catch	<i>R</i>	118.60	X
1 pc tailgate logo	<i>me</i>	72.20	—
1 pc tailgate outer garnish	<i>me</i>	171.20	X
		5,530.20	
	Less 25% :	-1,382.55	

1 pc rear number plate	
1 pc reverse sensor assy	
1 pc tailgate '6PAX' sticker	
1 pc tailgate '70KM/H' sticker	
1 pc tailgate company advertisement sticker	
1 pc tailgate glass sealant	
1 pc tailgate glass damping seal	

	4,147.65	
<i>2000w</i>	<i>mt</i> 40.00	sn
	<i>mt</i> 220.00	sn
	<i>me</i> 15.00	sn —
	<i>me</i> 15.00	sn —
	<i>me</i> 450.00	sn <i>2500w</i>
	<i>me</i> 40.00	sn ✓
	<i>me</i> 20.00	sn —

key to continue...

Vehicle Insured : GY 3795 E
Our Ref : 023246

Page : 2
No. : 32914

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.	800.00 ⁶⁰⁰
To transfer tailgate's fittings	80.00 ⁶⁰
To remove and refit rear windscreen glass and conduct water leak test	120.00 ✓
To remove and refit reverse sensor assy.	60.00 ⁵⁰
To putty and respray on affected portions.	680.00 ⁶⁰⁰
To focus taillamps. To check rear wiring and lighting operation.	50.00 ²⁰
Total :	<u>S\$ 6,737.65</u>

Singapore Dollars SIX THOUSAND SEVEN HUNDRED
THIRTY SEVEN AND CENTS SIXTY FIVE Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: