



# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06819

Vehicle Insured : SMD1078U  
 Accident Date : 30-Apr-2023

Date : 03-May-2023

Our Ref : 023092 (AIG) / CHAN

PAGE : 1

TAN YI GUANG  
 BLK462A YISHUN AVE 6  
 #07-1151  
 Singapore 761462

*Not Authorized  
 1/1 Surp @ 1500h  
 Resurvey After Paint  
 3 days*

ESTIMATED COST OF REPAIR FOR MAZDA 3 SLJ6467C  
 =====

1 pc Rear bumper fascia  
 1 pc Rear bumper reinforcement  
 2 pcs Rear bumper tow cover  
 2 pcs Rear bumper side retainer

	<i>Buyer work</i>	1,127.00	<i>✓</i>
		563.00	<i>✓</i>
@ S\$ 28.90		57.80	<i>X</i>
@ S\$ 38.00		76.00	<i>X</i>
		-----	
		1,823.80	
Less 20% :		364.76	
		-----	

1,459.04

To putty and spray replaced parts

*3500* 400.00 *8000*

To remove, cut-out damaged parts,  
 panel beating, welding, align,  
 refix and to renew above parts

400.00 *2000*

Total : S\$ 2,259.04  
 =====

Singapore Dollars Two Thousand Two Hundred and  
 Fifty Nine and Cents Four Only

**LKK Auto Consultants** hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: