

LC AUTOMOTIVE

25 KAKI BUKIT ROAD 4 #05-26 Synergy @ KB Singapore 417800

TP China.
Xiao Tong

11th APRIL 2023

KWAN KHAI WAH
25 KAKI BUKIT ROAD4
05-26 SYNERGY @KB
Singapore 417800

WMWYV 720403L21185

Accident date: 04th APRIL 2023

Estimated repair cost for vehicle no: SDT63R MINI COOPER S

S/n	Qty	Items	U/price	Amount
1	1	Rear boot lid Cooper logo		\$65.00 x
2	1	Rear boot lid S logo		\$45.00 x
3	1	Rear boot lid emble logo		\$105.00 x
4	1	Rear boot lid number plate		\$50.00 x
5	1	Rear bumper -upper		\$2,855.00 x
6	1	rear bumper- lower		\$1,250.00 x
7	1	Rear bumper -centre		\$855.00 x
8	2	rear bumper side retainer	\$265.10	\$530.20 x
9	2	Rear Bumper Side Bracket	\$285.10	\$570.20 x
10	2	Rear Bumper Side Reflector	\$105.00	\$210.00 x
11	10	Rear bumper clips	\$6.50	\$65.00 x
12	4	Rear bumper reverse sensor	\$200.00	\$800.00 x
13	1	Rear bumper reinforcement		\$1,358.00 x
14	1	Rear exhaust aluminum chrome		\$588.00 x
15	1	rear step panel swift		\$512.00 x
16	1	Rear end panel		\$1,050.00 x
17	1	Rear end panel top garnish		\$488.00 x

Subtotal :- \$11,396.40

Labour charges

To remove & re-fix cushion

\$120.00 x

To remove & re-fix reverse sensor

\$120.00 x

to remove & Refix rear exhaust chrome pipe

\$180.00 x

to remove & Refix rear step panel swift

\$100.00 x

To check wiring system

\$80.00 x

Tuff note LKK Auto Consultants hence notify the Repairer of the following:

Panel beating resurvey before/after spray painting

• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Subtotal :-

\$2,120.00

Total:-

\$13,516.40

33K