

ASS. REC. BY:

REF:

6621

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7-11 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLR 1517H

Yr Regn:

07, 17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 3

C.C.

1496

Colour:

M. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM6BN22A8H0167000

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / XOKO or

Front

Rear

R/Bal.

5 mm

R/Bal.

6 mm

L/Bal.

5 mm

L/Bal.

6 mm

D.O.A.

29/4/23

D.O.I.

5/5/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Barking Plot

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Firm's

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format:

Lump Sum / I.B.I: (\$

TOTAL

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	218Z

Vehicle Details

Vehicle No.:	SLR1517H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	05 May 2023
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SEDAN 1.5 AT EU6
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	P520458750
Chassis No.:	JM6BN22A8H0167000
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$16,034.00
Original Registration Date:	17 Jul 2017
First Registration Date:	17 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$11,034.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Jul 2027
PARF Rebate Amount:	\$7,723.00

Intended COE Rebate Details

COE Expiry Date:	16 Jul 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,801.00
COE Rebate Amount:	\$17,960.00
Total Rebate Amount:	\$25,683.00

The information contained herein is correct as at 05 May 2023

OK

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version:	1.0 (Last Synchronised: 04 May 2023)
Parts:	143	MAZDA 3 1.5 SEDAN AT EU6 (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	Alan's United Auto Pte Ltd/SLR1517H/04/05/2023 16:40		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*BONNET	0.00	0.00	Ry *650.00 F	✓
2	2		*BONNET HINGE	0.00	0.00	Dij *74.00 F	✓
3	1		*BONNET FRONT RUBBER	0.00	0.00	Ry *56.00 F	✓
4	1		*BONNET INNER LOCK	0.00	0.00	Ry *185.00 F	✓
5	1		*BONNET LOCK COVER	0.00	0.00	Mit *48.00 F	✓
6	1		*LH BONNET STOPPER	0.00	0.00	Mit *25.00 F	✓
7	1		*FRONT BUMPER FASCIA	0.00	0.00	CM *580.00 F	✓
8	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	*440.00 F	?
9	2		*FRONT BUMPER SIDE BRACKET	0.00	0.00	*60.00 F	✓
10	2		*FRONT BUMPER LOWER GRILLE SIDE COVER	0.00	0.00	Mit *52.00 F	✓
11	1		*FRONT LH FOGLAMP	0.00	0.00	CM *85.00 F	✓
12	1		*LH FOGLAMP SIDE GARNISH	0.00	0.00	Mit *56.00 F	✓
13	1		*FRONT BUMPER TOP	0.00	0.00	CM *240.00 F	✓
14	3		*FRONT BUMPER TOP CLIP	0.00	0.00	Ne *13.50 F	✓
15	3		*FRONT BUMPER TOP RIVET	0.00	0.00	Ne *16.50 F	✓
16	1		*FRONT GRILLE	0.00	0.00	CM *165.00 F	✓
17	1		*FRONT GRILLE TOP BEAM	0.00	0.00	*125.00 F	?
18	1		*FRONT GRILLE TOP BEAM COVER	0.00	0.00	*155.00 F	?
19	2		*FRONT GRILLE SIDE BRACKET	0.00	0.00	*60.00 F	?
20	2		*FRONT GRILLE LOWER SIDE CHROME	0.00	0.00	*230.00 F	?
21	2		*HEADLAMP ASSY	0.00	0.00	*1,100.00 F	✓
22	2		*LH HEADLAMP BACK COVER	0.00	0.00	*36.00 F	✓
23	1		*LH HEADLAMP BULB	0.00	0.00	*35.00 F	✓
24	1		*LH HEADLAMP HIGH BEAM BULB	0.00	0.00	*30.00 F	✓
25	1		*LH HEADLAMP HARNESS WIRE	0.00	0.00	*95.00 F	?
26	1		*LH HEADLAMP TOP CLIP	0.00	0.00	*4.50 F	✓
27	1		*FRONT SUPPORT PANEL	0.00	0.00	Ry *360.00 F	✓
28	1		*FRONT SUPPORT PANEL TOP PANEL	0.00	0.00	Ry *125.00 F	✓
29	1		*SUPPORT PANEL CENTRE COVER	0.00	0.00	CM *55.00 F	✓
30	1		*SUPPORT RH COVER	0.00	0.00	*50.00 F	?
31	1		*SUPPORT LH LOWER GUIDE	0.00	0.00	*70.00 F	?
32	1		*SUPPORT CENTRE LOWER COVER	0.00	0.00	*155.00 F	?
33	1		*AIR CLEANER HOUSING TOP	0.00	0.00	CM *105.00 F	✓
34	1		*AIR FLOW SENSOR	0.00	0.00	*260.00 F	?
35	1		*AIR CLEANER HOUSING TOP HOSE	0.00	0.00	CM *75.00 F	✓
36	2		*AIR CLEANER TOP HOSE CLIP	0.00	0.00	Ne *18.00 F	✓
37	1		*AIR FILTER	0.00	0.00	Dij *38.00 F	✓
38	1		*AIR CLEANER HOUSING LOWER	0.00	0.00	CM *115.00 F	✓
39	1		*AIR CLEANER LOWER HOUSING HOSE	0.00	0.00	CM *85.00 F	✓
40	1		*AIR INTAKE HOSE LOWER	0.00	0.00	*90.00 F	?
41	2		*AIR CLEANER HOUSING STOPPER	0.00	0.00	*24.00 F	?
42	1		*THROTTLE BODY ASSY	0.00	0.00	*580.00 F	?
43	1		*FRONT LH FENDER	0.00	0.00	Ne *210.00 F	✓
44	1		*FRONT LH FENDER TOP GARNISH	0.00	0.00	Dij *56.00 F	✓
45	3		*FRONT LH FENDER TOP GARNISH CLIP	0.00	0.00	Ne *13.50 F	✓

Alan's United Auto Pte Ltd/SLR1517H/04/05/2023 16:40. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
46	1		*FRONT LH FENDER RETAINER	0.00	0.00	CM *35.00 F	✓
47	1		*FRONT LH FENDER INNER SHIELD	0.00	0.00	CM *90.00 F	✓
48	1		*FRONT LH FENDER INNER SHIELD BRACKET	0.00	0.00	R *27.00 F	✓
49	11		*FRONT LH FENDER INNER SHIELD CLIP	0.00	0.00	R *38.50 F	✓
50	1		*FRONT LH WHEEL HOUSE	0.00	0.00	*380.00 F	?
51	1		*FRONT LH WHEEL HOUSE OUTER PANEL	0.00	0.00	*215.00 F	?
52	1		*FRONT LH WHEEL HOUSE FRONT PANEL	0.00	0.00	*170.00 F	?
53	1		*FRONT LH CHASSIS ASSY	0.00	0.00	R *750.00 F	X
54	1		*RADIATOR AUTO	0.00	0.00	*570.00 F	?
55	1		*RADIATOR FAN ASSY	0.00	0.00	*660.00 F	?
56	1		*RADIATOR SPARE TANK	0.00	0.00	*80.00 F	?
57	2		*RADIATOR TOP STOPPER	0.00	0.00	MT *24.00 F	✓
58	2		*RADIATOR LOWER STOPPER	0.00	0.00	*32.00 F	?
59	1		*RADIATOR TOP HOSE	0.00	0.00	*45.00 F	?
60	1		*RADIATOR LOWER HOSE	0.00	0.00	*55.00 F	?
61	1		*AIR CON CONDENSER	0.00	0.00	*570.00 F	?
62	1		*LH FUSE BOX ASSY	0.00	0.00	CM *370.00 F	✓
63	1		*BATTERY TOP BRACKET	0.00	0.00	R *22.00 F	X
64	1		*LH ENGINE MOUNTING	0.00	0.00	*185.00 F	?
65	1		*RADIATOR COOLANT	0	0.00	R *30.00 FS	✓
66	1		*AUTO OIL	0	0.00	*20.00 FS	?
67	1		*FRONT NO.PLATE WITH BOX	0	0.00	SM *50.00 FS	X
68	1		*BATTERY	0	0.00	*180.00 FS	?
69	1		*LH HEADLAMP SMALL BULB	0.00	0.00	MT *12.00 F	✓

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	11,711.50
+ Margin on L,N Items 10.00% (\$\$)	1,143.15
Total Parts (\$\$)	12,854.65

Alan's United Auto Pte Ltd/SLR1517H/04/05/2023 16:40. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature.

Date

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REWIRE DAMAGED PARTS & REFOCUS HEADLAMP BEAM	New	20.00 ✓ 55
2	TO REMOVE AIR CON CONDENSER, PIPES 7 DRIER, VACUUM AND TO RECHARGE GAS	New	120.00 100 ✓
3	TO DISMANTLE & LOWER FRONT UNDERCARRIAGE	New	200.00 7 ✓
4	TO CHECK & ADJUST WHEEL ALIGNMENT	New	65.00 60 ✓
5	TO REMOVE & LIFT UP ENGINE ASSY	New	400.00 ? ✓
6	TO PUTTY AND SPRAY REPLACE PARTS	New	900.00 800 ✓
7	TO REMOVE , CUT OUT DAMAGED PARTS , PANEL BEATING , WELDING , ALIGN , REFIX AND TO RENEW ABOVE PARTS	New	1,600.00 900 ? ✓
8	TO REMOVE & RENEW THROTTLE BODY & TUNNING ENGINE	New	60.00 ? ✓
9	TO REMOVE & RENEW FUSE BOX , TRANSFER AND REWIRING	New	60.00 ✓
Gross Labour Cost (S\$)			3,425.00

Alan's United Auto Pte Ltd/SLR1517H/04/05/2023 16:40. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Alan's United Auto Pte Ltd (Co.Reg.No:201113667N)

Blk 7 Sin Ming Industrial Estate, #01-76

Singapore 575642

Tel: 6453 8686 Fax: 6459 6550 Email: kennychan@alanutd.com;Janicechou@alanutd.com

INSURER:

ERGO Insurance Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	023090
Policy No:	DMPG22009092	Date of Loss:	29/04/2023
Vehicle Reg. No.:	SLR1517H	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	YAP BENG YEN (YE MINGYAN)	Contact No:	+6591181517
Driver:	ONG KIAM YEOW (WANG TIANYAO)		

Make/Model:	MAZDA 3, 1.5 SEDAN AT EU6 (A)	Vehicle Reg. Date:	17/07/2017
Vehicle Colour:	BLUE		
Engine No:	P520458750	Chassis No:	JM6BN22ABH0167000
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	14 7-11days

*Not Authorized
Returning After Repair
11 Day @
£18500*

Present Location:	ALAN'S UNITED AUTO PTE LTD (HQ)
-------------------	---------------------------------

COST OF CLAIMS**Amount**

Parts	12,854.65
Miscellaneous Items	0.00
Labour	3,425.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (S\$)	16,279.65
-------------------	-----------

+ GST 8.00% (S\$)	1,302.37
-------------------	----------

Nett Amount (S\$)	17,582.02
-------------------	-----------

This claim is handled by: CHAN YEW SIAH

Generated using Merimen e-Claims Internet Estimation & Adjusting System