



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
 #08-1339 Singapore 470130
 Tel: 9450 7920
 * zoomautowerks@gmail.com

not fullund

9 May 2023

REG NO. : SNE 5103 L
 MAKE/MODEL : HONDA FREED

*der
 meny
 5/5/23
 2/5 \$ 2400
 the photo the repair*

4 days

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
LIST ITEMS		
1	Front door -LH <i>Body 2D</i>	\$ 1021.10 1,725.90
1	Front door glass outer moulding <i>11</i>	\$ 121.30 X
1	Front door lock <i>11</i>	\$ 268.80 X
1	Front door outer handle <i>11</i>	\$ 342.80 X
1	Front door regulator <i>11</i>	\$ 364.50 X
1	Front door regulator motor <i>11</i>	\$ 355.80 X
1	Front door rubber <i>11</i>	\$ 138.80 X
1	Front door black tape <i>11</i>	\$ 86.90 X
1	Rocker panel -LH <i>R</i>	\$ 900.30 X
1	Rear sliding door -LH <i>Body 2D / Bent</i>	\$ 1220.30 1,450.80
1	Rear sliding door lower roller <i>11</i>	\$ 155.00 X
1	Rear sliding door inner board <i>11</i>	\$ 672.40 X
1	Rear sliding door lock <i>11</i>	\$ 328.00 X
1	Rear sliding door regulator <i>11</i>	\$ 389.40 X
1	Rear sliding door regulator motor <i>11</i>	\$ 355.80 X
1	Rear sliding door rubber <i>11</i>	\$ 188.60 X
1	Rear sliding door black tape <i>11</i>	\$ 85.50 X
1	Rear bumper <i>R</i>	\$ 967.30 X
1	Rear bumper side retainer -LH <i>11</i>	\$ 40.90 X
1	Rear fender -LH <i>R</i>	\$ 1,294.60 X
1	Rear fender quarter glass moulding <i>11</i>	\$ 15.00 X
1	Rear wheel hub with bearing <i>11</i>	\$ 321.40 X
1	Rear shock absorber <i>11</i>	\$ 336.40 X
		\$ 10,906.20
	Less 20%	\$ 2,181.24
		\$ 8,724.96

SPECIAL NETT ITEMS

1	Rear bumper clip (1 set) <i>11</i>	\$ 50.00 X
1	Rear fender quarter glass sealant <i>11</i>	\$ 50.00 X
1	Rear tyre <i>SUC</i>	\$ 400.00 X
1	Rear wheel rim -LH <i>R</i>	\$ 850.00 X
		\$ 1,350.00

S/N

LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	20
2	To remove and refit inner garnishes.	\$	150.00	60
3	To remove and refit rear undercarriage.	\$	11 300.00	X
4	To conduct wheel alignment.	\$	180.00	60
5	To remove and refit quarter glass to assist repair.	\$	11 150.00	X
6	To remove, refit door fittings and replace damaged parts, transfer all fittings to new door.	\$	400.00	120
7	To apply undercoating.	\$	200.00	60
8	Panel beating.	\$	1,600.00	480
9	To re-spray painting on the affected areas.	\$	1,500.00	800
		\$	<u>4,560.00</u>	

GRAND TOTAL :

\$ 14,634.96

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-2241.4
 202
 P-1793.12
 L-1600