



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PER/AIS/2022/0002465	Date of Loss:	26/04/2023
Vehicle Reg. No.:	SCJ3838S	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHEE TENG HOCK CECIL		
Make/Model:	LOTUS ELISE, 1.6 (M)	Vehicle Reg. Date:	09/12/2011
Vehicle Colour:	WHITE	Chassis No:	SCCLHCXC5CHC10124
Engine No:	1ZRU411712		
Odometer:	65595 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	18		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS

	Amount
Parts	88,484.00
Miscellaneous Items	750.00
Labour	8,250.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	97,484.00
+ GST 8.00% (S\$)	7,798.72
Nett Amount (S\$)	105,282.72

This claim is handled by: BRIAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplement (v items) must be resurveyed and is subject to that approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Taufik 97495749
Not Authorise 5/5/23 @ 5pm
Ex \$5000
4/5 Resurvey after repair
Taufik @ hkan.com
15 days

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 05 May 2023)
Parts: N/A LOTUS ELISE 1.6 (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SCJ3838S)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT CLAM	0.00	0.00	<i>Car</i> *27,500.00 F
2	2		*FRONT CLAM RETAINER	0.00	0.00	? *370.00 F
3	2		*HEADLAMP LH/RH (CHECK)	0.00	0.00	-
4	2		*HEADLAMP SEAL LH/RH (CHECK)	0.00	0.00	-
5	1		*ENAMEL LOTUS NOSE BADGE	0.00	0.00	<i>ml</i> *280.00 F
6	1		*REAR CLAM	0.00	0.00	<i>Car</i> *28,500.00 F
7	1		*ROCKER CLAM LH	0.00	0.00	<i>Car</i> *12,000.00 F
8	1		*STONE GUARD	0.00	0.00	<i>ml</i> *185.00 F
9	1		*SIDE SCOOP LH	0.00	0.00	<i>ml</i> *850.00 F
10	1		*ELISE DECAL	0.00	0.00	<i>ml</i> *85.00 F
11	2		*SIDE DECAL	0.00	0.00	<i>ml</i> *370.00 F
12	1		*CLAM SUPPORT (REAR)	0.00	0.00	<i>Car</i> *1,800.00 F
13	1		*RIM	0.00	0.00	<i>Car</i> *8,500.00 F
				Sub Total (\$\$)		80,440.00
				+ Margin on L,N Items 10.00% (\$\$)		8,044.00
				Total Parts (\$\$)		88,484.00

F=Franchise part.

Report was unsubmitted during this print-out.
 Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

No Qty Particulars

			Amount
<u>Miscellaneous Items</u>			
1	1	ELISE FRONT CLAM SHELL FITTING KIT	250.00
2	1	ELISE REAR CLAM SHELL FITTING KIT	250.00
3	1	TYRE ADLAN 225/45R17	250.00
Sub Total (S\$)			750.00

Handwritten notes: ne 200, ne 200, packed 80%

Estimates on Labour

No Particulars

		Lab.Type	Amount
<u>Labour Items</u>			
1	TO REMOVE/ REPLACE FRONT CLAM SHELL AND REALIGN ALL THE CONNECTION	New 1200	1,500.00
2	TO REMOVE/ REPLACE REAR CLAM SHELL, ROCKER CLAM AND REALIGN ALL THE CONNECTION	New 1200	2,000.00
3	TO REMOVE/ REFIT HARD TOP ROOF, FUEL LID CONNECTION, ENGINE ATTACHEMENT PART & WASHER CONTAINER	New 800	1,800.00
4	TO DISMANTLE & REFIT DRIVE SEAT/ PASSENGER SEAT	New 150	250.00
5	TO CONDUCT UNDERCARRIAGE CHECKING	New 200 ?	600.00
6	TO DO WHEEL ALIGNMENT	New 120	200.00
7	TO SPRAY PAINT FRONT CLAM, ROCKER CLAM, REAR CLAM	New 1700	1,900.00
Gross Labour Cost (S\$)			8,250.00

Handwritten notes: photo, photo

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >