

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 09 May 2023

Preliminary Advice

Vehicle No	: SML8320G	Accident Date	: 28/04/2023
Make	: MITSUBISHI LANCER	Policy No.	: DMPCSNW00282132200
Assignment Date	: 05/05/2023	Excess	: S\$0.00
Date of Inspection	: 08/05/2023	Est. Duration of Repair	: 0
Inspection At	: AUTOMOTIVE REPAIR CENTRE PTE LTD (HQ) 38 WOODLANDS INDUSTRIAL PARK E1, #05-18 SINGAPORE 757700		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	55,360.00
Revised Amount	:S\$	Total Loss
Check Items (Estimated)	:S\$	
Total	:S\$	
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	27,000.00
COE / PARF Rebate	:S\$	7,260.00
Salvage Value	:S\$	
Margin for Repair	:S\$	19,740.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :According to surveyor, vehicle fitted with non-original rear exhaust and extractor. The brand is compatible for this make and model vehicle.