



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR23004594/Uqy3m4 Date: 26/05/2023 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 1655Z	Veh. Inspected	PD 896X	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/05/23/2008	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	05/05/2023	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE COMMUTER GL 2.8 (A)	c.c	2754	
Engine No.	HIDDEN	Year of Reg.	2023	
Chassis No.	GDH2232004974	Colour	WHITE	
Odometer	9353 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	HABILEAD	6 mm	
L/H Front Tyre	195 R15	HABILEAD	6 mm	
R/H Rear Tyre	195 R15	HABILEAD	6 mm	
L/H Rear Tyre	195 R15	HABILEAD	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/05/2023	Inspection Date	08/05/2023	
Survey held at	ZERO GRAVITY 2 KAKI BUKIT AVE 2 #01-25 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	