

金興(龔)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Your Reference : DHOM110171451903  
Accident Date : 29-Apr-2023

No. : 32910

Date : 03-May-2023

Our Ref : 023239 / THERESA

PAGE : 1

LIM ENG CHEONG (MR)  
C/O UNITED OVERSEAS INSURANCE LIMITED  
146 ROBINSON ROAD  
#02-01  
UOI BUILDING  
Singapore 068909

ESTIMATED COST OF REPAIR FOR SUBARU FORESTER 2.0I-L CVT (2017) SFD6969Z  
=====

1 pc front bumper		400.00 c
1 pc front bumper tow cover		15.00 c
2 pcs front bumper side retainer (LH/RH)	@ S\$ 18.00	36.00 c
2 pcs front bumper fog lamp (LH/RH)	@ S\$185.00	370.00 c
2 pcs front bumper fog lamp chrome moulding (LH/RH)	@ S\$ 45.00	90.00 c
2 pcs front bumper nozzle cover (LH/RH)	@ S\$ 50.00	100.00 c
2 pcs front bumper nozzle pump (LH/RH)	1 @ S\$100.00	200.00 c
2 pcs front bumper nozzle pump bracket (LH/RH)	1	
1 pc front bumper nozzle pump hose		85.00 c
1 pc front bumper centre intake cover		40.00 c
1 pc front bumper absorber		125.00 c
1 pc front bumper reinforcement		270.00 c
16 pcs front bumper clips	@ S\$ 2.00	32.00 c
1 pc bonnet		580.00 c
1 pc bonnet lock-lower		65.00 c
1 pc bonnet lock catch-upper		40.00 c
2 pcs bonnet hinges (LH/RH)	@ S\$ 40.00	80.00 c
1 pc bonnet lock:pull cable		60.00 c
1 pc bonnet insulation		100.00 c

Con't Page 2 ...

金興(龔)汽車私人有限公司

**K. KIM HIN AUTO PTE LTD**

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Your Reference : DHOM110171451903  
Our Ref : 023239

Page : 2  
No. : 32910

7 pcs bonnet insulation clips	@ S\$ 2.50	17.50 c
1 pc bonnet lock pull cable clip		6.00 c
1 pc bonnet outer chrome		145.00 c
1 pc front grille c/w lower chrome		260.00 c
2 pcs front grille side stopper	@ S\$ 6.50	13.00 c
1 pc front grille inner lower bracket		35.00 c
1 pc front grille inner upper bracket		30.00 c
1 pc front grille centre assy		150.00 c
10 pcs front grille clips	@ S\$ 2.50	25.00 c
2 pcs horn	@ S\$ 45.00	90.00 c
2 pcs headlamp assy (LH/RH)	@ \$1700.00	3,400.00 c
2 pcs headlamp lower bracket (LH/RH)	@ S\$ 40.00	80.00 c
1 pc wiper washer tank		115.00 c
1 pc front support panel assy		380.00 c
1 pc front support lower member		150.00 c
1 pc transmission oil cooler		295.00 c
1 pc transmission oil cooler inlet hose		55.00 c
1 pc transmission oil cooler outlet hose		55.00 c
1 pc air con condenser		420.00 c
1 pc air con liquid pipe		135.00 c
1 pc air con fan cowling		65.00 c
1 pc air con fan blade		60.00 c
1 pc air con fan motor		190.00 c
1 pc air con fan belt		65.00 c
1 pc air con compressor		980.00 c
1 pc radiator		520.00 c
1 pc radiator spare tank		65.00 c
1 pc radiator top hose		40.00 c
1 pc radiator lower hose		40.00 c
1 pc radiator fan cowling		65.00 c
1 pc radiator fan blade		55.00 c
1 pc radiator fan motor		195.00 c
1 pc main pulley		160.00 c

Con't Page 3 ...

金興(龔)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Your Reference : DHOM110171451903  
Our Ref : 023239

Page : 3  
No. : 32910

1 pc tensioner pulley		120.00 c	
1 pc tensioner bearing		65.00 c	
1 pc alternator top cover		80.00 c	
1 pc air intake duct		95.00 c	
2 pcs air intake duct clip	@ S\$ 2.50	5.00 c	
1 pc air cleaner box - top		80.00 c	
1 pc air cleaner box - lower		90.00 c	
1 pc air resonator box		60.00 c	
1 pc RH front fender		210.00 c	
1 pc RH front fender inner shield		85.00 c	
10 pcs RH front fender inner shield clips	@ S\$ 2.00	20.00 c	
2 pcs engine mounting (LH/RH)	@ S\$175.00	350.00 c	
1 pc gearbox mounting		95.00 c	
1 pc engine under cover - front		135.00 c	
		-----	
		12,534.50	
Add 10% :		1,253.45	
		-----	
			13,787.95
1 pc front number plate			40.00 sn
1 pc transmission oil fluid			90.00 sn
1 pc radiator coolant			48.00 sn
To remove, cut out damaged parts. panel beating, welding, align. refix and to renew affected parts.			800.00
To remove aircon condenser, pipes and driers. Vaccum and recharge gas			100.00
To putty and respray on affected portions.			900.00
To focus headlamps. To check front wiring and lighting operation.			50.00
		-----	
	Total :	S\$15,815.95	
		=====	

Singapore Dollars Fifteen Thousand Eight Hundred  
and Fifteen and Cents Ninety Five Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.