

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 12.04.2023 2016.
JTNGF3D1H 308004572
Ezlyan.

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLD8292H**
MODEL : **TOYOTA VELLFIRE**
DATE OF ACCIDENT : 11.04.2023
TIME OF ACCIDENT : 17:15 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Deformed.</i>	1	\$ 682.70 <i>882.70</i>	\$ 682.70 <i>882.70</i>
2	FRONT WINDSCREEN SIDE MOULDING <i>new</i>	2	\$ 364.70	\$ 729.40
3	FRONT BUMPER FOG LAMP <i>cracked</i>	2	\$ 398.80	\$ 797.60
4	FRONT BUMPER FOG LAMP CHROME <i>2 new</i>	2	\$ 78.90	\$ 157.80
5	FRONT BUMPER FOG LAMP COVER GARNISH <i>new</i>	2	\$ 128.60	\$ 257.20
6	FRONT BUMPER TOWING COVER <i>Deformed</i>	2	\$ 38.60	\$ 77.20
7	FRONT BUMPER LOWER GRILLE	1	\$ 286.50	\$ 286.50
8	FRONT BUMPER SENSOR <i>new</i>	2	\$ 419.60	\$ 839.20
9	FRONT BUMPER SENSOR RING <i>new</i>	2	\$ 48.50	\$ 97.00
10	FRONT BUMPER SENSOR WIRE HARNESS <i>new</i>	1	\$ 289.70	\$ 289.70
11	FRONT BUMPER SIDE RETAINER <i>new</i>	2	\$ 129.80	\$ 259.60
12	FRONT BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 560.70	\$ 560.70
13	FRONT BUMPER SPONGE <i>cracked</i>	1	\$ 128.40	\$ 128.40
14	FRONT BUMPER BOTTOM ABSORB GRNISH <i>Deformed</i>	1	\$ 185.40	\$ 185.40
15	FRONT FENDER LH <i>Repair</i>	1	\$ 1,385.60	\$ 1,385.60
16	FRONT FENDER COWLING <i>new</i>	2	\$ 268.40	\$ 536.80
17	FRONT GRILLE <i>cracked</i>	1	\$ 1,886.50	\$ 1,886.50
18	FRONT GRILLE MOULDING (UPPER) <i>cracked</i>	1	\$ 168.50	\$ 168.50
19	FRONT GRILLE CENTER MOULDING	1	\$ 462.80	\$ 462.80
20	FRONT GRILLE LOGO <i>new</i>	1	\$ 125.60	\$ 125.60
21	FRONT GRILLE LOGO (UPPER SIDE) <i>2 new</i>	2	\$ 88.40	\$ 176.80
22	FRONT GRILLE TOP RUBBER <i>new</i>	1	\$ 38.60	\$ 38.60

Handwritten notes and markings on the right side of the table, including plus signs (+), minus signs (-), and the number 466.

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLD8292H**
 MODEL : **TOYOTA VELLFIRE**
 DATE OF ACCIDENT : 11.04.2023
 TIME OF ACCIDENT : 17:15 HOURS

23	FRONT GRILLE CENTER MOULDING <i>Repeated cracked</i>	1	\$ 462.80	\$ 462.80	+
24	FRONT GRILLE LOWER MOULDING (CHROME) <i>cracked</i>	1	\$ 388.20	\$ 388.20	+
25	FRONT RADAR SENSOR <i>Not New</i>	1	\$ 2,685.30	\$ 2,685.30	+
26	HEADLAMP <i>cracked.</i>	2	\$ 4,855.20	\$ 9,710.40	+
27	HEADLAMP MOULDING (GARNISH) <i>not new</i>	2	\$ 96.80	\$ 193.60	+
28	FRONT TEMPERATURE WIRE HARNESS <i>3 NH</i>	1	\$ 298.90	\$ 298.90	+
29	FRONT TEMPERATURE WIRE HOLDER <i>Not</i>	1	\$ 87.10	\$ 87.10	+
30	FRONT WIPER GARNISH <i>cracked.</i>	1	\$ 935.20	\$ 935.20	791
31	FRONT WIPER GARNISH SIDE JOINT <i>cut</i>	2	\$ 128.90	\$ 257.80	+
32	FRONT AIR DUCT <i>Not New</i>	1	\$ 230.60	\$ 230.60	+
33	FRONT BONNET <i>Dented.</i>	1	\$ 895.60	\$ 895.60	+
34	FRONT BONNET HINGE <i>Bent.</i>	2	\$ 69.50	\$ 139.00	+
35	FRONT BONNET LOCK <i>Damaged.</i>	1	\$ 158.60	\$ 158.60	+
36	FRONT BONNET MOULDING (CHROME) <i>cut</i>	1	\$ 685.20	\$ 685.20	366.
37	FRONT BONNET INSULATOR <i>not new</i>	1	\$ 269.80	\$ 269.80	+
38	FRONT SUPPORT PANEL <i>Buckled</i>	1	\$ 1,358.60	\$ 1,358.60	+
39	FRONT SUPPORT PANEL TOP GARNISH <i>Deformed</i>	1	\$ 298.40	\$ 298.40	+
40	FRONT BRACE PANEL <i>Bent</i>	1	\$ 95.00	\$ 95.00	+
41	HORN <i>Not New</i>	2	\$ 228.60	\$ 457.20	+
42	AIR CON CONDENSER SIDE GARNISH <i>new</i>	2	\$ 135.20	\$ 270.40	+
43	AIR CON CONDENSER <i>Warpped</i>	1	\$ 2,431.80	\$ 2,431.80	1949
44	AIR CON CONDENSER MOUNTING <i>Not new</i>	4	\$ 25.60	\$ 102.40	+
45	RADIATOR TOP SUPPORT GARNISH <i>Cracked</i>	1	\$ 158.40	\$ 158.40	+
46	RADIATOR <i>Bent</i>	1	\$ 2,820.50	\$ 2,820.50	2423.
47	RADIATOR FAN COWLING <i>cracked</i>	1	\$ 381.00	\$ 381.00	+
48	FRONT TEMPERATURE SENSOR <i>not new</i>	1	\$ 228.30	\$ 228.30	+
49	REAR BUMPER <i>Distorted</i>	1	\$ 786.20 886.20	\$ 786.20 886.20	+
50	REAR BUMPER TOWING COVER <i>Deformed</i>	2	\$ 29.50	\$ 59.00	+
51	REAR BUMPER REFLECTOR <i>LH cracked</i>	2	\$ 68.50	\$ 137.00	68.50
52	REAR BUMPER SIDE INNER GARNISH LH <i>Deformed</i>	1	\$ 138.50	\$ 138.50	+
53	REAR BUMPER SIDE INNER GARNISH RH	1	\$ 138.50	\$ 138.50	+
54	REAR BUMPER SIDE RETAINER <i>Damaged</i>	2	\$ 165.80	\$ 331.60	+
55	REVERSE SENSOR <i>Damaged.</i>	4	\$ 419.70	\$ 1,678.80	1400.
56	REVERSE SENSOR RING HOLDER <i>new</i>	4	\$ 49.80	\$ 199.20	+

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLD8292H**
 MODEL : **TOYOTA VELLFIRE**
 DATE OF ACCIDENT : 11.04.2023
 TIME OF ACCIDENT : 17:15 HOURS

57	REVERSE SENSOR WIREHARNES <i>Snapped</i>	1	\$ 305.40	\$ 305.40	✓
58	TAILGATE <i>Distorted</i>	1	\$ 2,454.80	\$ 2,454.80	✓ 2164.
59	TAILGATE OUTER MOULDING (CHROME) <i>cracked</i>	1	\$ 985.20	\$ 985.20	✓ 885
60	TAILGATE LAMP <i>cracked</i>	2	\$ 748.50	\$ 1,497.00	✓ 1290
61	TAILGATE INNER AUTO SWITCH BUTTON <i>?</i>	1	\$ 187.90	\$ 187.90	+
62	TAILGATE OUTER SWITCH BUTTON <i>NP</i>	1	\$ 228.40	\$ 228.40	+
63	TAILGATE NUMBER PLATE LAMP <i>Not Nec</i>	2	\$ 89.40	\$ 178.80	+
64	TAILGATE REVERSE CAMERA <i>Damaged.</i>	1	\$ 1,785.20	\$ 1,785.20	✓ 895
65	TAILGATE WIRE HARNESS <i>Not nec</i>	1	\$ 355.80	\$ 355.80	+
66	TAIL GATE LOGO <i>3 NP</i>	1	\$ 98.20	\$ 98.20	✓
67	TAIL GATE EMBLEM 'VELLFIRE' <i>NP</i>	1	\$ 99.50	\$ 99.50	✓
68	TAILGATE LOCK DETECTOR <i>cracked</i>	1	\$ 225.80	\$ 225.80	✓
69	TAILGATE LOCK DETECTOR WIRE HARNESS <i>Not nec</i>	1	\$ 298.60	\$ 298.60	+
70	TAIL GATE LOCK BUZZER <i>cracked</i>	1	\$ 228.50	\$ 228.50	✓
71	TAILGATE TOP LOCK <i>Damaged.</i>	1	\$ 986.40	\$ 986.40	✓ 524.
72	TAILGATE LOWER LOCK <i>Not nec</i>	1	\$ 59.40	\$ 59.40	+
73	TAILGATE DAMPER <i>Not nec</i>	2	\$ 435.80	\$ 871.60	✓
74	TAILGATE AUTO SIDE SENSOR <i>Bent</i>	2	\$ 1,555.70	\$ 3,111.40	✓ 1986.40.
75	TAILGATE HINGE <i>3 NP</i>	2	\$ 87.90	\$ 175.80	+
76	TAILGATE SPOILER <i>NP</i>	1	\$ 4,554.80	\$ 4,554.80	+
77	TAILGATE INNER TRIM <i>cracked</i>	1	\$ 899.70	\$ 899.70	✓ 784.
78	TAILGATE INNER SIDE TRIM <i>Deformed.</i>	2	\$ 158.60	\$ 317.20	✓
79	TAILGATE INNER TOP TRIM <i>Not nec</i>	1	\$ 288.80	\$ 288.80	+
80	TAILGATE INNER HOLDER <i>Dehd.</i>	1	\$ 98.40	\$ 98.40	✓
81	TAILGATE WEATHER STRIP <i>lit</i>	1	\$ 520.80	\$ 520.80	✓ 388.
82	TAILGATE STOPPER <i>Not nec</i>	4	\$ 35.60	\$ 142.40	+
83	TAILGATE WINDSCREEN C/W MOULDING <i>shattered</i>	1	\$ 1,896.50	\$ 1,896.50	✓
84	REAR AIR CON BLOWER MOTOR <i>cracked</i>	1	\$ 2,889.10	\$ 2,889.10	✓ 2695
85	TAILLAMP <i>cracked</i>	2	\$ 825.60	\$ 1,651.20	✓
86	TAILLAMP PANEL (OUTER) <i>LH dented</i>	2	\$ 268.40	\$ 536.80	✓ 268.40
87	TAILLAMP PANEL (INNER) <i>Repair</i>	2	\$ 315.80	\$ 631.60	+
88	TAILLAMP PANEL (INNER) LOWER <i>LH Damaged</i>	2	\$ 296.30	\$ 592.60	✓ 296.30.
89	REAR CORNER PANEL <i>Deformed</i>	2	\$ 368.10	\$ 736.20	✓
90	REAR CORNER PANEL RETAINER <i>Not Nec</i>	2	\$ 142.10	\$ 284.20	+

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLD8292H**
 MODEL : **TOYOTA VELLFIRE**
 DATE OF ACCIDENT : 11.04.2023
 TIME OF ACCIDENT : 17:15 HOURS

91	REAR END PANEL (OUTER) <i>Distorted</i>	1	\$ 1,372.50	\$ 1,372.50	✓ 785
92	REAR END PANEL (INNER) <i>Distorted</i>	1	\$ 588.00	\$ 588.00	✓
93	REAR END PANEL INNER SUPPORT <i>Not new</i>	2	\$ 468.30	\$ 936.60	+
94	REAR END PANEL TOP GARNISH <i>Distorted</i>	1	\$ 245.60	\$ 245.60	✓
95	REAR FLOOR PANEL <i>Buckled</i>	1	\$ 986.40	\$ 986.40	✓
96	REAR FLOOR PANEL BOTTOM CROSS MEMBER <i>Distorted</i>	1	\$ 298.10	\$ 298.10	✓
97	REAR FLOOR PANEL TOP BOARD (SIDE) <i>Distorted</i>	2	\$ 587.20	\$ 1,174.40	✓
98	REAR FLOOR PANEL TOP BOARD (CENTER) <i>Distorted</i>	1	\$ 555.30	\$ 555.30	✓
99	REAR FLOOR MAT <i>Not new</i>	1	\$ 358.60	\$ 358.60	✓
100	REAR FLOOR PANEL TRAY (CENTER) <i>Distorted</i>	1	\$ 452.30	\$ 452.30	✓
101	REAR SEAT RAILWAY (CENTER) <i>Distorted</i>	2	\$ 1,283.20	\$ 2,566.40	✓ 1992.
102	REAR SEAT RAILWAY CENTER COVER GARNISH <i>Distorted</i>	2	\$ 195.80	\$ 391.60	✓
103	REAR SEAT RAILWAY CENTER COVER GARNISH JOINT <i>Not new</i>	4	\$ 65.30	\$ 261.20	+
104	REAR EXHAUST PIPE <i>Not new</i>	1	\$ 1,996.50	\$ 1,996.50	+
105	REAR EXHAUST MOUNTING <i>Not new</i>	2	\$ 48.50	\$ 97.00	+
106	REAR EXHAUST GASKET <i>Not new</i>	1	\$ 68.20	\$ 68.20	+
107	REAR SPARE TYRE BOLT <i>Distorted</i>	1	\$ 38.60	\$ 38.60	✓
108	REAR SPARE TYRE HOLDER GARNISH <i>Distorted</i>	1	\$ 385.60	\$ 385.60	✓
109	REAR SPARE TYRE COVER <i>Not new</i>	1	\$ 85.60	\$ 85.60	+

PRICE \$ 82,631.00
 LESS 25% \$ 20,657.75
SUB TOTAL PRICE \$ 61,973.25

544980
 4087485

SPECIAL NETT ITEMS

SPECIAL NETT ITEMS				
S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>Distorted</i>	1	\$ 80.00	\$ 80.00
2	FRONT BUMPER CLIP (SET) <i>New</i>	1	\$ 80.00	\$ 80.00
3	FRONT FENDER COWLING CLIP (SET) <i>Not new</i>	1	\$ 80.00	\$ 80.00
4	FRONT GRILLE CLIP (SET) <i>3 new</i>	1	\$ 80.00	\$ 80.00
5	FRONT SUPPORT PANEL SEALANT	1	\$ 120.00	\$ 120.00
6	FRONT SUPPORT PANEL TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00
7	FRONT SUPPORT PANEL BOTTOM COVER GARNISH <i>new</i>	1	\$ 60.00	\$ 60.00
8	AIR CON CONDENSER SIDE GARNISH CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00
9	BONNET INSULATOR CLIP (SET) <i>Not new</i>	1	\$ 60.00	\$ 60.00
10	COOLANT <i>New</i>	1	\$ 80.00	\$ 80.00

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLD8292H**
 MODEL : **TOYOTA VELLFIRE**
 DATE OF ACCIDENT : 11.04.2023
 TIME OF ACCIDENT : 17:15 HOURS

11	REAR NUMBER PLATE <i>Bent</i>	1	\$ 80.00	\$ 80.00	<i>50</i>
12	REAR BUMPER CLIPS (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
13	TAILGATE AUTO SYSTEM (SPECAIL TYPE) <i>Not rec</i>	1	\$ 2,200.00	\$ 2,200.00	<i>X</i>
14	TAILGATE SEALANT <i>Neu</i>	1	\$ 150.00	\$ 150.00	<i>60</i>
15	TAILGATE INNER TRIM CLIP (SET) <i>3</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
16	TAILGATE INNER SIDE TRIM CLIP (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
17	TAILGATE WINDSCREEN SEALANT	1	\$ 80.00	\$ 80.00	<i>40</i>
18	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00	<i>30</i>
19	TAIL GATE WINDSCREEN SOLAR FILM	1	\$ 650.00	\$ 650.00	<i>280</i>
20	TAILGATE SPOILER CLIP <i>Not rec</i>	1	\$ 50.00	\$ 50.00	<i>X</i>
21	TAILLAMP CLIPS (SET) <i>Neu</i>	1	\$ 30.00	\$ 30.00	<i>✓</i>
22	TAILLAMP PANEL (OUTER) SEALANT <i>Neu</i>	2	\$ 80.00	\$ 160.00	<i>60</i>
23	TAILLAMP PANEL (INNER) SEALANT <i>Not rec</i>	2	\$ 80.00	\$ 160.00	<i>X</i>
24	TAILLAMP PANEL (INNER) LOWER SEALANT <i>Not rec</i>	2	\$ 80.00	\$ 160.00	<i>X</i>
25	REAR FENDER INNER TRIM CLIP (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00	<i>60</i>
26	REAR FENDER INNER COWLING CLIP (SET) <i>Not rec</i>	1	\$ 80.00	\$ 80.00	<i>X</i>
27	REAR END PANEL (OUTER) SEALANT <i>Not rec</i>	1	\$ 150.00	\$ 150.00	<i>60</i>
28	REAR END PANEL (INNER) SEALANT <i>Not rec</i>	1	\$ 150.00	\$ 150.00	<i>X</i>
29	REAR END PANEL TOP GARNISH CLIP (SET) <i>Neu</i>	1	\$ 60.00	\$ 60.00	<i>10</i>
30	REAR FLOOR PANEL SEALANT <i>Not rec</i>	1	\$ 350.00	\$ 350.00	<i>60</i>
31	REAR SEAT RAILWAY CENTER COVER GARNISH CLIP (SET)	1	\$ 80.00	\$ 80.00	<i>4.20</i>
32	REAR SEAT RAILWAY CENTER COVER GARNISH JOINT CLIP (SET)	1	\$ 80.00	\$ 80.00	<i>X</i>
33	TRIANGLE BREAKDOWN SIGN <i>Not rec</i>	1	\$ 180.00	\$ 180.00	<i>X</i>

34 Rear Video Recorder. 800. 1720
Missing 580. TOTAL \$ 5,990.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	<i>1000</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	<i>700</i> ✓
3	TURFF COAT	\$ 250.00	<i>80</i>
4	WIRING CHECK	\$ 250.00	<i>30</i>

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLD8292H**
 MODEL : **TOYOTA VELLFIRE**
 DATE OF ACCIDENT : 11.04.2023
 TIME OF ACCIDENT : 17:15 HOURS

5	REFOCUS HEADLAMP BEAM	\$ 80.00	X
6	REMOVE AND REFIX AND RESET FRONT SENSOR	\$ 80.00	50
9	REMOVE & REFIX AUDIO SPEAKER	\$ 120.00	X
12	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	60
13	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	60
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 450.00	X 200.

2880

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 2,800.00	1400
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	1000
3	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 650.00	180
4	TUFF COAT	\$ 250.00	100
5	REMOVE AND REPLACE REAR WIREHARNES	\$ 480.00	100
6	REMOVE & REFIX UPHOLSTERY TO FACILITATE REPAIR	\$ 350.00	120
7	REMOVE & REFIX REVERSE SENSOR & DISTANCE SETTING	\$ 80.00	50
8	REMOVE & REFIX REVERSE CAMERA & DISTANCE SETTING	\$ 80.00	50

TO : AIG MOTOR CLAIMS DEPTS
 VEHICLE NO : SLD8292H
 MODEL : TOYOTA VELLFIRE
 DATE OF ACCIDENT : 11.04.2023
 TIME OF ACCIDENT : 17:15 HOURS

9	REMOVE AND REFIX REAR AIRCON BLOWER AND REFILL AIRCON GAS	\$ 350.00	150
10	REAR CHASSIS ALIGNMENT	\$ 250.00	X
11	REMOVE & REFIX AND RESET TAILGATE AUTO SYSTEM	\$ 450.00	200
12	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓
13	REMOVE & REFIX VIDEO RECORDER	\$ 180.00	50
14	REMOVE & REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
15	REMOVE AND REFIX REAR UNDER CARRIAGE & CROSS MEMBER	\$ 650.00	X
16	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X
17	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	X 80

TOTAL \$ 13,460.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 67,963.25
 TOTAL LABOUR COST : \$ 13,460.00
 TOTAL REPAIR COST : \$ 81,423.25

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY

IRENE

SERVICE ADVISOR

IRENE

HP : 8297 9787

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ly
 4/s 14/04/23

16 Days

Supplementary: 335175

total. 52506.60

4/s: 3642K.

3680

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 12.04.2023

TO : **AIG** MOTOR CLAIMS DEPTS (SUPPLEMENTARY)
VEHICLE NO : **SLD8292H**
MODEL : **TOYOTA VELLFIRE**
DATE OF ACCIDENT : 11.04.2023
TIME OF ACCIDENT : 17:15 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR FENDER INNER TRIM <i>Ref 1</i>	2	\$ 2,234.50	\$ 4,469.00

TOTAL PRICE	\$ 4,469.00
LESS 25%	\$ 1,117.25
TOTAL PRICE	\$ 3,351.75

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

Adrian G
St. S.

Supplying: 3351.75