


Section A - Accident Details

Registration Number	SHD6186S
Case Reference Number	TAX/05/23/2013
Registration Date	3/Nov/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	WONG CHONG PENG (HUANG ZHONGPING)
Type of Accident	Head To Side
Accident Date and Time	4/May/2023 9:24 PM
Accident Reported Date and Time	5/May/2023 9:55 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118341
Special Instruction to ARC, if any	REAR PORTION
Prepared Date and Time	5/May/2023 1:01 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,345.00	\$450.00
Total Spray Cost	\$1,856.00	\$500.00
Total Spare Part Cost	\$8,627.98	\$1,710.04
Total Other Cost	\$796.88	(\$260.04)
TOTAL COST	\$12,625.86	\$2,400.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	9.0	4.0
Prepared / Adjusted By	Boon Chew Tay	Kenneth Kong (LKK) / INCOME
ARC / Surveyor Sign Off Date	10/05/2023 12:21 PM	10/05/2023 9:21 AM
Signature		
Remarks	INITIAL = 8 DAYS WITH SUPPLEMENTARY = 1 DAYS TOTAL = 9 DAYS	LUMPSUM REPAIR / AFTER PAINT PHOTO , FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) / HP : 9691 0663 / Email : kennethkong@lkkauto.com

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2305-0306	Invoice Number	
Quotation Date	25.05.2023	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$845.00	\$200.00
ADDITIONAL JOB TO REPAIR REAR PROTION	\$500.00	\$250.00
Total Labour	\$1,345.00	\$450.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR PANEL	\$220.00	\$0.00
TO RESPRAY BUMPER BEAM	\$220.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$220.00	\$150.00
TO RESPRAY REAR SPARE TYRE PANEL	\$220.00	\$0.00
TO RESPRAY REAR PANEL	\$220.00	\$150.00
Total Spray Painting & Panel Beating	\$1,856.00	\$500.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$296.88	\$296.88
Lump Sum Adjustment by Surveyor	\$0.00	(\$606.92)
Total Other Costs	\$796.88	(\$260.04)

Part 4 - Spare Parts / Material Usage										
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		52159479 13	COVER, RR BUMPER ASSY	1.00	\$478.90	25.00	\$359.18	Replace	Replace	√
		52023470 30	REAR BUMPER REINFORCEMENT	0.00	\$360.10	0.00	\$0.00	Replace	Check	X
		52462470 30	PAD, RR BUMPER, RH & LH , 1	2.00	\$4.30	25.00	\$6.45	Replace	Replace	√
		52462470 20	PAD, RR BUMPER, RH & LH , 2	2.00	\$4.30	25.00	\$6.45	Replace	Replace	√
		52462470 10	PAD, RR BUMPER, RH & LH , 3	2.00	\$4.30	25.00	\$6.45	Replace	Replace	√
		52461470 10	PAD, RR BUMPER, CTR	3.00	\$2.50	25.00	\$5.63	Replace	Replace	√

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 04/06/2023

User ID : PohSuan

	52191470 30	SEAL, RR BUMPER ARM, RH & LH	1.00	\$12.30	25.00	\$9.23	Replace	Replace	√
	52599680 30	STOPPER, RR BUMPER, RH & LH	0.00	\$4.80	0.00	\$0.00	Replace	Not Given	X
	52575470 40	RETAINER, RR BUMPER, RH	0.00	\$127.40	0.00	\$0.00	Replace	Not Given	X
	52576470 40	RETAINER, RR BUMPER, LH	0.00	\$127.40	0.00	\$0.00	Replace	Not Given	X
	52591470 50	SEAL, RR BUMPER , RH	0.00	\$95.50	0.00	\$0.00	Replace	Check	X
	52592470 40	SEAL, RR BUMPER , LH	0.00	\$95.50	0.00	\$0.00	Replace	Check	X
	52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	Replace	√
	52453470 10	GUARD, RR BUMPER, LOWER	1.00	\$623.50	25.00	\$467.63	Replace	Replace	√
	52565479 00	FILLER, RR BUMPER , RH	0.00	\$168.60	0.00	\$0.00	Replace	Check	X
	52566479 00	FILLER, RR BUMPER , LH	0.00	\$168.60	0.00	\$0.00	Replace	Check	X
	52169470 20	COVER, GUARD RR BUMPER LOWER	0.00	\$16.70	0.00	\$0.00	Replace	Not Given	X
		SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace	√
	89997301 00	ANTENNA, ELECTRICAL KEY	0.00	\$78.00	0.00	\$0.00	Replace	Check	X
	90189060 29	REAR BUMPER GROMMET SCREW	0.00	\$2.20	0.00	\$0.00	Replace	Not Given	X
	81551472 81	LENS & BODY, REAR COMBINATION LAMP , RH	0.00	\$489.00	0.00	\$0.00	Replace	Not Given	X
	81561471 51	LENS & BODY, REAR COMBINATION LAMP , LH	0.00	\$489.00	0.00	\$0.00	Replace	Not Given	X
	81581470 10	LENS & BODY ASSY , RR BUMPER , RH	0.00	\$544.40	0.00	\$0.00	Replace	Not Given	X
	81591470 10	LENS & BODY ASSY , RR BUMPER , LH	0.00	\$544.40	0.00	\$0.00	Replace	Not Given	X
	81497470 20	COVER, REAR COMBINATION LAMP, RH	0.00	\$69.90	0.00	\$0.00	Replace	Not Given	X
	81498470 20	COVER, REAR COMBINATION LAMP, LH	0.00	\$69.90	0.00	\$0.00	Replace	Not Given	X
	58398470 50	COVER, REAR FLOOR UNDER , RH	0.00	\$189.20	0.00	\$0.00	Replace	Not Given	X
	58399470 30	COVER, REAR FLOOR UNDER , LH	0.00	\$261.60	0.00	\$0.00	Replace	Not Given	X
	66259470 10	COVER, REAR FLOOR UNDER CENTER	0.00	\$249.10	0.00	\$0.00	Replace	Check	X
	67005474 40	TAIL GATE PANEL SUB-ASSY, BACK DOOR	1.00	\$1,238.40	100.00	\$0.00	Replace	Repair	R
	67881470 50	TAIL GATE WEATHERSTRIP, BACK DOOR	0.00	\$402.50	0.00	\$0.00	Replace	Not Given	X
	76801471 10A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	0.00	\$992.30	0.00	\$0.00	Replace	Not Given	X
	75441470 90	NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT	1.00	\$59.10	25.00	\$44.33	Replace	Replace	√
	75442471 30	NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT	1.00	\$59.10	25.00	\$44.33	Replace	Replace	√
	69350470 50	TAIL GATE LOCK ASSY, BACK DOOR	1.00	\$505.50	100.00	\$0.00	Replace	Repair	R
	69321470 10	TAIL GATE LOCK COVER , BACK DOOR	0.00	\$32.70	0.00	\$0.00	Replace	Not Given	X
	75403480 10	EMBLEM SUB-ASSY REAR	1.00	\$77.40	25.00	\$58.05	Replace	Replace	√
		STRIDES LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	√
		STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	√
	58307470 90	END PANEL SUB-ASSY, BODY LOWER BACK	1.00	\$707.10	100.00	\$0.00	Replace	Repair	R
	58311471 30	SPARE TYRE PANEL , PAN, REAR FLOOR	1.00	\$630.30	100.00	\$0.00	Replace	Repair	R
		SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
Total				\$10,237.00		\$1,253.13			

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 04/06/2023

User ID : PohSuan

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52023470 30	REAR BUMPER REINFORCEMENT	1.00	\$360.10	25.00	\$270.08	Replace	Replace
		66259470 10	COVER, REAR FLOOR UNDER CENTER	1.00	\$249.10	25.00	\$186.83	Replace	Replace
Total					609.20		456.91		

√
√

	1,710.04	
+	450.00	
+	846.88	L/S \$2,400/-
	<u>3,006.92</u>	
	-20%	
	<u>2,405.54</u>	