

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 05 Jul 2023

Preliminary Advice

Insured Vehicle No	: XE8140R	Accident Date	: 05/05/2023
TP Vehicle No	: SMA2341T	Assignment Date	: 05/05/2023
Make	: BMW 216D	Est. Duration of Repair	: 12
Date of Inspection	: 05/05/2023		
Inspection At	: N-51 AUTOMOTIVE PTE LTD (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB SINGAPORE 417921		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	44,449.25
Revised Amount	:S\$	32,106.75
Check Items (Estimated)	:S\$	1,938.50
Total	:S\$	34,045.25

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.