

ASS. REC. BY:

REF:

EQ / 23004600/K943

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2 1/2 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHF-636P

Yr Regn:

09, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

C.C.

1798

Colour

m.p. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

428789

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDK B3 FUX C3092084

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / Rim or

Tyre Size:

F: Sailun 195/65R15

R: Wanki

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

6

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

4/5/23

D.O.I.

8/5/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

Battery Flat

30/3

11 PM

829001

Cable

Used

for

1164.76, 80%

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

2 1/2

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. \$

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format:

Lump Sum / I.B.L. (\$) 7P 2900

TOTAL

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHF636P**AAD2305-***Not Authorized
Penny B4 paint**1/1 Sep @ 2900h*

Vehicle No.:

Chassis No.:

Co UEN.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

08 MAY 2023**SHF636P****JTDKB3FUX03092084****200303878K****TOYOTA****PRIUS GEN 4****4/5/2023****GBK5771T/EQ****30/9/2020****PART****LIST**

- 1 COVER, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 GUARD, REAR BUMPER, CENTER
- 1 SEAL, REAR BUMPER SIDE, LH
- 1 SEAL, REAR BUMPER SIDE, RH
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 REAR BUMPER SIDE RETAINER RH
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 REFLECTOR ASSY, REFLEX, LH
- 1 REFLECTOR ASSY, REFLEX, RH
- 1 COVER, FLOOR UNDER, RH
- 1 COVER, FLOOR UNDER, LH
- 1 COVER, REAR FLOOR
- 1 COVER, DECK TRIM, REAR
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 SPOILER SUB-ASSY, REAR
- 1 PANEL SUB-ASSY, BACK DOOR
- 1 STAY ASSY, BACK DOOR, LH
- 1 STAY ASSY, BACK DOOR, RH
- 1 HINGE ASSY, BACK DOOR, LH
- 1 HINGE ASSY, BACK DOOR, RH
- 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
- 1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2
- 1 PLATE, BACK DOOR NAME, NO.1
- 1 ORNAMENT SUB-ASSY, BACK DOOR

\$	<i>B4</i>	612.68	✓
\$	<i>mis</i>	27.93	✓
\$	<i>B4</i>	472.19	✓
\$	<i>sn</i>	149.21	X
\$	<i>sn</i>	149.21	X
\$	<i>sn</i>	167.48	X
\$	<i>DI</i>	167.48	✓
\$	<i>B4</i>	419.90	✓
\$	<i>sn</i>	49.25	X
\$	<i>sn</i>	49.25	X
\$	<i>sn</i>	220.50	X
\$	<i>sn</i>	304.92	X
\$	<i>mis</i>	290.43	✓
\$	<i>sn</i>	159.39	X
\$	<i>R</i>	824.46	X
\$	<i>sn</i>	1,986.92	X
\$	<i>R</i>	1,443.86	X
\$	<i>sn</i>	305.66	X
\$	<i>sn</i>	305.66	X
\$	<i>R</i>	77.18	X
\$	<i>R</i>	77.18	X
\$	<i>mis</i>	1,156.89	✓
\$	<i>mc</i>	68.88	✓
\$	<i>mc</i>	68.88	✓
\$	<i>mc</i>	90.30	✓

TOTAL \$ 9,645.69
25% \$ 2,411.42
\$ 7,234.26

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHF636P**AAD2305-****SPECIAL NETT****1SET PARKING AID**

1 REAR BUMPER CLIP

1 REAR SPOILER CLIP

1 REAR RH BUMPER RETAINER CLIP

1 REAR LH BUMPER RETAINER CLIP

1 END PANEL INNER TRIM CLIP

1 REAR BUMPER PROTECTOR

2 WINDSCREEN SEALANT

1 WINDSCREEN MOULDING

1 WINDSCREEN INNER SPONGE SEAL

\$	<i>his</i>	700.00	<i>22000</i>
\$	<i>Nea</i>	65.00	<i>6000</i>
\$	<i>nn</i>	65.00	X
\$	<i>nn</i>	65.00	X
\$	<i>nn</i>	65.00	X
\$	<i>nn</i>	60.00	X
\$	<i>nsp</i>	180.00	X
\$	<i>nn</i>	150.00	X
\$	<i>nn</i>	200.00	X
\$	<i>nn</i>	130.00	X

TOTAL \$ 1,680.00**TOTAL PARTS \$ 8,914.26****LABOUR**

To rust-proofing of the affected areas.

\$ *nn* 600.00 X

Putty and spray painting of the affected portion.

\$ 1,200.00 *4400*

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,000.00 *3000*

To transfer of tailgate fittings and conduct water seepage test.

\$ *nn* 170.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 X

To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.

\$ *h* 170.00 X

To transfer of tailgate fittings and conduct water seepage test.

\$ *h* 170.00 X

To transfer of bootlid fittings, attachments and perform water seepage test.

\$ *h* 170.00 X

To reinstall rear bumper parking sensor.

\$ 170.00 *500*

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHF636P

AAD2305-

To check steering geometry and computer wheel alignment \$ *220.00* X
TOTAL \$ 5,250.00

OVERALL TOTAL \$ 14,164.26

2 1/2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHF636P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	04 May 2023
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2020
Engine No.:	2ZR2G97487
Chassis No.:	JTDKB3FUX03092084
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,807.00
Original Registration Date:	30 Sep 2020
First Registration Date:	30 Sep 2020
Transfer Count:	0
Actual ARF Paid:	\$14,530.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2028
PARF Rebate Amount:	\$10,897.00
Intended COE Rebate Details	
COE Expiry Date:	29 Sep 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$26,512.00
COE Rebate Amount:	\$17,904.00
Total Rebate Amount:	\$28,801.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 04 May 2023

OK