

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/HSB23004606/UPA3**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKW10GCat Workshop m/s SPRINTof SLD7437P

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**Bal. or Market Value: 890k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: LIA 849345Veh No: SKW10GC Yr Regn: 14/10/15Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Toyota Wellfire c.c. 2494Colour: Black A/C: Insured / Std / NI / NASp. Reading: 321057 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTNA F3DH 008002746Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: NH / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 245/45-2R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or CST

Front

Rear

R/Bal. 7 mmR/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 03/05/23D.O.I. 5/5/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Dep 28
1/5/23 1/5/23 inbound Leat

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$) _____)

SPEEDWERKZ PRIVATE LIMITED

6 Kaki Bukit Avenue #01-73, AUTOBAY, Singapore 417883

Tel: 96195936 / info@speedwerkz.biz

not Allowed
5/5/23
1/5 @ 8000
5 days.

VEHICLE NUMBER: SKW106C

MAKE & MODEL: TOYOTA VELLFIRE

DOA: 3/5/2023

CLAIM TYPE: TP CLAIM

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
REAR TAILGATE EMBLEM (VELLFIRE)	1	\$110.55	✓
REAR TAILGATE CENTRE CHROME MOULDING	1	\$846.50	X
REAR TAILGATE LOGO	1	\$95.20	X
REAR TAILGATE	1	\$2,880.50	✓ 2120.20
REAR TAILGATE LAMP @1013.75	2	\$2,027.50	X
REAR TAIL LAMP FILLER PANEL @589.60	2	\$1,179.20	X
REAR TAILGATE INNER LOCK	1	\$895.50	✓ 509.10
REAR TAILGATE LOCK CATCH	1	\$165.20	X
REAR TAILGATE INNER BOARD	1	\$1,550.60	✓ 815.10
REAR TAIL GATE PULL POCKET	1	\$126.80	X
REAR TAILGATE LOCK EYE	1	\$95.70	X
REAR TAILGATE WEATHER STRIP	1	\$441.55	✓ 366.10
REAR TAILGATE HINGES @115.00	2	\$230.00	X
REAR TAILGATE DAMPER \$380.50	2	\$761.00	X
REAR TAILLAMP @ 1185	2	\$2,370.00	X
REAR BOOT COVER WINDSCREEN GLASS SIDE GARNISH	1	\$365.00	X
REAR BOOTLID TOP SPOILER	1	\$3,917.00	X
REAR BOOTLID LOCK AUTO SIDE CONTROL SENSOR @452	2	\$904.00	X
REAR TAILGATE NUMBER PLATE LIGHT @ 46.10	2	\$92.20	X
REAR BOOT RUBBER	1	\$598.70	X
REAR BUMPER	1	\$2,802.00	✓ 1021.10
REAR BUMPER SIDE @815	2	\$1,630.00	✓ 682
REAR BUMPER REFLECTOR @209	2	\$418.00	✓ 92
REAR BUMPER RETAINER @ 115	2	\$230.00	X
REAR BUMPER SIDE RETAINER @145	2	\$290.00	X
REAR BUMPER INNER GARNISH @95	2	\$190.00	X
REAR BUMPER PDC SENSOR @441.50	4	\$1,766.00	2 per 772
REAR END PANEL	1	\$1,085.00	✓ 960.62
REAR END PANEL TOP GARNISH	1	\$586.90	X
REAR FENDER @ 1926.00	2	\$3,852.00	X
REAR FENDER QUARTER GLASS WITH MOUDING @ 856.90	2	\$1,713.80	X
REAR FENDER UNDER SHIELD @ 86.90	2	\$173.80	X
REAR FENDER INNER TRIM @986	2	\$1,972.00	✓ 1810.20
REAR FENDER AIR DUCT @ 85.40	2	\$170.80	X
REAR KEY LOCK ANTENNA	1	\$280.90	✓
REAR FLOOR MAT panel cloth	1	\$681.50	✓
REAR FLOOR RENAL panel	1	\$1,320.00	X
REAR FLOOR UNDER COVER @310	2	\$620.00	X
REAR EXHAUST SILENCER BOX	1	\$1,385.50	X

EXHUAUST MOUNTING @ 48.70	an	2	\$97.40	X
REAR TOW COVER @58.85	an	2	\$117.70	pc

25% Less 10 %
 Sub Total \$41,036.00
\$4,103.60
\$36,932.40

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
REAR WINDSCREEN GLASS SEALANT	121	1	\$120.00 40
REAR REVERSE CAMERA	11	1	\$550.00 X
REAR NUMBER PLATE	11	1	\$45.00 X
REAR BOOT COVER TRIM BOARD CLIP	nu	1 Set	\$50.00 ✓
REAR FENDER TRIM BOARD CLIP @ 50.00	11	2 Set	\$100.00 X
Sub Total		\$865.00	

LABOUR CHARGE	QTY	PRICE (\$)	REMARKS
TO CHECK WIRING		\$120.00	20
APPLY ANTI RUST CHEMICAL		\$200.00	60
REMOVE AND REFIX REAR WINDSCREEN		\$150.00	120
REMOVE AND REFIX UPHOLTERY CUSHION SEAT, CARPET AND REPAIR SEAT		\$350.00	80
REMOVE AND REPLACE PDC SENSOR		\$150.00	50
REMOVE AND REPLACE REAR EXHAUST PIPE		\$220.00	12 X
PANEL BEATING REMOVING AND REPLACING NEW PARTS		\$2,200.00	880
TP SPRAY PAINTING AND ETC		\$1,800.00	1000
Sub Total		\$5,190.00	

Grand Total \$42,987.40

1-10280.22
 252
 7710.16
 90
 2210
 1001016
 202
 1008

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____