

TO : AIG MOTOR CLAIMS DEPTS
 VEHICLE NO : SMD9834B
 MODEL : HONDA STREAM
 DATE OF ACCIDENT : 24.04.2023
 TIME OF ACCIDENT : 11:50 HOURS

24	REAR FLOOR PANEL COVER BOARD <i>RH delcd</i>	2	\$ 126.50	\$ 253.00	<i>126.50</i>
25	REAR FLOOR PANEL COVER BOARD (INNER SUPPORT)	1	\$ 697.60	\$ 697.60	<i>+</i>
26	REAR TOOLS SPONGE <i>delcd</i>	1	\$ 168.20	\$ 168.20	<i>+</i>
27	REAR JACK COVER GARNISH <i>delcd</i>	1	\$ 185.00	\$ 185.00	<i>+</i>
28	REAR CHASSIS MEMBER RH <i>Ry</i>	1	\$ 1,426.80	\$ 1,426.80	<i>+</i>
29	REAR SPARE TYRE BRACKET <i>delcd</i>	1	\$ 218.90	\$ 218.90	<i>+</i>
30	REAR SPARE TYRE SUPPORT HOLDER <i>delcd</i>	2	\$ 186.40	\$ 372.80	<i>+</i>
31	REAR SPARE TYRE HOLDER BOLT <i>delcd</i>	1	\$ 171.80	\$ 171.80	<i>+</i>
32	REAR EXHAUST PIPE	1	\$ 799.50	\$ 799.50	<i>+</i>
33	REAR EXHAUST GASKET (SET) <i>delcd</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
34	REAR EXHAUST MOUNTING <i>delcd</i>	4	\$ 29.20	\$ 116.80	<i>+</i>
35	REAR EXHAUST INSULATOR	1	\$ 89.10	\$ 89.10	<i>+</i>

4880.40 TOTAL PRICE \$ 12,253.20
 LESS 20% \$ 2,450.64
3904.32 SUB TOTAL PRICE \$ 9,802.56

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>delcd</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
2	REAR BUMPER CLIPS (SET) <i>delcd</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
3	TAILLAMP CLIP (SET) <i>delcd</i>	1	\$ 40.00	\$ 40.00	<i>20</i>
4	TAILGATE SEALANT <i>delcd</i>	1	\$ 80.00	\$ 80.00	<i>X</i>
5	TAILGATE WINDSCREEN SEALANT <i>delcd</i>	1	\$ 80.00	\$ 80.00	<i>40</i>
6	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00	<i>30</i>
7	REAR END PANEL INSULATION SEAL <i>delcd</i>	1	\$ 150.00	\$ 150.00	<i>60</i>
8	REAR END PANEL TOP GARNISH CLIP (SET) <i>delcd</i>	1	\$ 40.00	\$ 40.00	<i>10</i>
9	REAR FLOOR PANEL SEALANT	1	\$ 350.00	\$ 350.00	<i>+</i>
10	JACK <i>delcd</i>	1	\$ 150.00	\$ 150.00	<i>+</i>
11	SPARE TYRE <i>delcd</i>	1	\$ 350.00	\$ 350.00	<i>+</i>
12	REVERSE CAMERA <i>delcd</i>	1	\$ 450.00	\$ 450.00	<i>+</i>
13	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00	<i>200</i>

TOTAL *390* \$2,100.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,800.00	<i>800</i>

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMD9834B**
 MODEL : **HONDA STREAM**
 DATE OF ACCIDENT : 24.04.2023
 TIME OF ACCIDENT : 11:50 HOURS

2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	800
3	TUFF COAT	\$ 250.00	60
4	WIRING AND BULB CHECK	\$ 180.00	30
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
6	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
7	REAR CHASSIS ALIGNMENT	\$ 250.00	x
8	TRANSFER TAILGATE MECHANISM	\$ 80.00	60
9	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
10	CONDUCT WATER LEAKAGE TEST	\$ 180.00	x
11	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	x
12	REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT	\$ 80.00	x
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL \$ 5,060.00

ESTIMATE REPORT

TOTAL PARTS COST : \$11,902.56
 TOTAL LABOUR COST : \$5,060.00
 TOTAL REPAIR COST : \$16,962.56

Adrian Ly
 L/S 25/04/23.
 06 Days.

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

total: 6264.32
 L/S: SK

1970