

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 26.04.2023

TO : AIG MOTOR CLAIMS DEPTS
VEHICLE NO : SKU7959Y
MODEL : MERCEDES CLA200
DATE OF ACCIDENT : 23.04.2023
TIME OF ACCIDENT : 12:35 HOURS

Xiao Tong

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR LH <i>1455'</i>	1	\$ 2,280.00	\$ 2,280.00
2	FRONT DOOR HINGE LH	2	\$ 163.00	\$ 326.00
3	FRONT DOOR CHECKER LH	1	\$ 168.00	\$ 168.00
4	FRONT DOOR WEATHER STRIP LH	1	\$ 380.00	\$ 380.00
5	FRONT DOOR OUTER STRIP LH	1	\$ 228.00	\$ 228.00
6	FRONT VIEW MIRROR LH	1	\$ 1,886.30	\$ 1,886.30
7	FRONT FENDER LH <i>Perfect</i>	1	\$ 874.00	\$ 874.00
8	FRONT FENDER INNER COWLING LH (FRONT)	1	\$ 274.00	\$ 274.00
9	FRONT FENDER INNER COWLING LH (BACK)	1	\$ 247.00	\$ 247.00
10	FRONT KNUCKLE ARM LH	1	\$ 1,288.00	\$ 1,288.00
11	FRONT WHEEL HUP WITH BEARING LH	1	\$ 468.00	\$ 468.00
12	FRONT SHOCK ABSORBER LH	1	\$ 969.00	\$ 969.00
13	FRONT LOWER ARM LH (FRONT)	1	\$ 788.00	\$ 788.00
14	FRONT LOWER ARM LH (REAR)	1	\$ 725.00	\$ 725.00
15	FRONT LOWER ARM BUSH	2	\$ 138.00	\$ 276.00
16	FRONT UPPER ARM LH	1	\$ 468.00	\$ 468.00
17	FRONT STABILIZER LINKAGE LH	1	\$ 98.00	\$ 98.00
18	FRONT STEERING RACK AND PINION	1	\$ 7,106.00	\$ 7,106.00
19	FRONT WHEEL RIM <i>cut</i>	1	\$ 1,080.00	\$ 1,080.00

TOTAL PRICE

\$ 19,929.30

874
786.60

S.N: 780

780/SN

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKU7959Y**
 MODEL : **MERCEDES CLA200**
 DATE OF ACCIDENT : 23.04.2023
 TIME OF ACCIDENT : 12:35 HOURS

LESS 10% \$ -
SUB TOTAL PRICE \$ -

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTALS/NETT
1	FRONT BUMPER CLIP (SET)	1	\$ 50.00	\$ 50.00
2	FRONT FENDER COWLING CLIP (SET)	1	\$ 50.00	\$ 50.00
3	FRONT FENDER INNER GARNISH CLIP LH (SET)	1	\$ 30.00	\$ 30.00
4	FRONT DOOR INNER TRIM CLIP LH (SET)	1	\$ 60.00	\$ 60.00
5	SIDE SKIRT CLIP LH	1	\$ 60.00	\$ 60.00
6	FRONT WHEEL TYRE LH	1	\$ 850.00	\$ 850.00
7	WHEEL CAP (SET)	1	\$ 200.00	\$ 200.00
8	BRAKE OIL	1	\$ 280.00	\$ 280.00

TOTAL \$ **1,580.00**

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	200
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	500
3	TUFF COAT	\$ 250.00	30
4	WIRING CHECK	\$ 650.00	+
5	CONDUCT WATER LEAKAGE TEST	\$ 120.00	+
6	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 650.00	+
7	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 1,200.00	+
8	REMOVE AND REFIX POWER STEERING RACK AND PINION	\$ 800.00	+

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKU7959Y**
 MODEL : **MERCEDES CLA200**
 DATE OF ACCIDENT : 23.04.2023
 TIME OF ACCIDENT : 12:35 HOURS

9	FOUR WHEEL ALIGNMNET	\$ 180.00	80
10	REMOVE & REFIX AUDIO SPEAKER	\$ 120.00	+
11	TRANSFER FRONT DOOR MECHANISM	\$ 80.00	+
12	REMOVE & REINSTALL FRONT WINDOW GLASS LH	\$ 80.00	+
13	RESET ABS LIGHT	\$ 600.00	+
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 880.00	+

TOTAL \$ 9,210.00

TOTAL PARTS COST : \$ 1,580.00
 TOTAL LABOUR COST : \$ 9,210.00
 TOTAL REPAIR COST : \$ 10,790.00

810

Adrian L
 1/s 26/04/23.
 03 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

total: 2376'60
 1/s 1.9k

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: