

Date: 03/05/2023

Vehicle No: SCX2121J

Model: TESLA MODEL 3 STANDARD RANGE

Chassis: LRW3F7FA2MC384837-2021

Reg. Year: 2021

Third Party Insurer: AIG

Third Party Veh No: SCR988U

Date of Accident: 03/05/2023

Estimator: TING AN

Surveyor: LKic Kenneth

3046.77

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		R \$728.97
2	REAR TAILGATE "TESLA" EMBLEM	1		na \$37.38
3	REAR TAILGATE LAMP RH	1		cm \$177.57
4	REAR TAIL LAMP RH	1		cm \$280.37
5	REAR TAIL LAMP BRACKET RH	1		diy \$2.80
6	REAR BUMPER	1		cm \$766.00
7	REAR BUMPER REINFORCEMENT	1		R \$271.03
8	REAR BUMPER CENTER BRACKET	1		cm \$52.34
9	REAR BUMPER SIDE BRACKET RH	1		diy \$7.48
10	REAR BUMPER PARKING SENSOR	2	\$163.55	Shan \$327.10
11	REAR BUMPER PARKING SENSOR BRACKET	2	\$4.67	na \$9.34
12	REAR BUMPER REFLECTOR RH	1		cm \$20.56
13	REAR END PANEL	1		R \$448.60

SUB TOTAL	\$3,129.54	\$1951.97
LESS 10%	-\$312.95	\$195.20
PARTS TOTAL	\$2,816.59	\$1756.77

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE INNER TRIM BOARD CLIPS	1		na \$40.00
2	REAR BUMPER CLIPS	1		na \$50.00
3	REAR END PANEL JOINT SEALANT	1		na \$120.00
S/N TOTAL				\$210.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1893

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 568047
Tel: (+65) 6461 1522 | Fax: (+65) 6461 1011



Date: 03/05/2023
Vehicle No: SCX2121J
Model: TESLA MODEL 3 STANDARD RANGE
Chassis: LRW3F7FA2MC384837-2021
Reg.Year: 2021

Third Party Insurer: AIG
Third Party Veh No: SCR988U
Date of Accident: 03/05/2023
Estimator: TING AN
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

\$800.00

500/

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL & ETC.

\$800.00

660/

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.

\$150.00 X

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER PARKING SENSOR & ETC.

\$120.00

60/

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$150.00 X

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

\$150.00 X

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$120.00

20/

LABOUR TOTAL \$2,290.00 \$1240

TING AN

TOTAL \$5,316.59

Finalise:

Parts: \$1756.77

Nett: \$50

Labour: \$1240

P/P: \$3046.77

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 Fax: (+65) 6481 1893

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1922 Fax: (+65) 6481 1011

