

Section A - Accident Details

Registration Number	SHD6211C
Case Reference Number	TAX/04/23/2012
Registration Date	28/Jun/2016
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	ZULKIFILI BIN MAHUAN
Type of Accident	Side Swipe
Accident Date and Time	5/Apr/2023 3:40 PM
Accident Reported Date and Time	6/Apr/2023 11:37 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118133
Special Instruction to ARC, if any	RIGHT FRONT
Prepared Date and Time	9/Apr/2023 9:38 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$200.00
Total Spray Cost	\$1,196.00	\$350.00
Total Spare Part Cost	\$10,124.95	\$2,113.88
Total Other Cost	\$380.00	(\$513.88)
TOTAL COST	\$12,545.95	\$2,150.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	2.0
Prepared / Adjusted By	Boon Chew Tay	Kenneth Kong (LKK) / INCOME
ARC / Surveyor Sign Off Date	17/04/2023 7:51 AM	15/04/2023 12:36 PM
Signature		
Remarks	INITIAL = 6DAYS WITH SUPPLEMENTARY = 0 DAY WITH SUPPLEMENTARY = 0 DAY TOTAL = 6 DAYS	LUMPSUM REPAIR / AFTER PAINT PHOTO , FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) / HP : 9691 0663 / Email : kennethkong@lkkauto.com

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2305-0059	Invoice Number	
Quotation Date	07.05.2023	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT RH PORTION	\$845.00	\$200.00
Total Labour	\$845.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$220.00	\$150.00
TO RESPRAY FRONT SUPPORT PANEL	\$220.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$0.00
Total Spray Painting & Panel Beating	\$1,196.00	\$350.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$533.88)
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$380.00	(\$513.88)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		52119-47930	BUMPER FRT	1.00	\$602.60	25.00	\$451.95	Replace	Replace	√
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	Replace	√
		52115-47040	BUMPER SUPPORT F/RH	0.00	\$86.20	0.00	\$0.00	Replace	Check	X
		52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$97.60	0.00	\$0.00	Replace	Check	X
		52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$567.90	0.00	\$0.00	Replace	Check	X
		57014-47030	ARM SUB-ASSY,FR BUMPER LH	0.00	\$284.00	0.00	\$0.00	Replace	Check	X
		57013-47030	ARM SUB-ASSY,FR BUMPER RH	0.00	\$284.00	0.00	\$0.00	Replace	Check	X
		53293-47040	DEFLECTOR, RADIATOR RH	0.00	\$94.30	0.00	\$0.00	Replace	Not Given	X
		53294-47030	DEFLECTOR, RADIATOR LH	0.00	\$86.90	0.00	\$0.00	Replace	Not Given	X
		52114-47140	BRACKET, FR BUMPER	0.00	\$126.10	0.00	\$0.00	Replace	Check	X
			NUMBER PLATE FRAME	1.00	\$25.00	0.00	\$25.00	Replace	Replace	√

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 07/05/2023

User ID : PohSuan

			NUMBER PLATE	1.00	\$35.00	0.00	\$35.00	Replace	Replace	√
		52128-47903	COVER, FR BUMPER HOLE LH	0.00	\$21.40	0.00	\$0.00	Replace	Check	X
		52127-47903	COVER, FR BUMPER HOLE RH	0.00	\$21.40	0.00	\$0.00	Replace	Check	X
		53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	1.00	\$389.90	25.00	\$292.43	Replace	Replace	√
		81210-12230	FOG LAMP RH	0.00	\$335.60	0.00	\$0.00	Replace	Check	X
		81511-47050	LENS & BODY, FR TURN RH	0.00	\$581.40	0.00	\$0.00	Replace	Check	X
		75310-47010	EMBLEM FRONT	1.00	\$98.70	25.00	\$74.03	Replace	Replace	√
		81519-47040	BRACKET, FR TURN UPPER RH	0.00	\$32.30	0.00	\$0.00	Replace	Check	X
		81519-47060	BRACKET, FR TURN CENTER RH	0.00	\$76.60	0.00	\$0.00	Replace	Check	X
		81519-47050	BRACKET, FR TURN LOWER RH	0.00	\$34.40	0.00	\$0.00	Replace	Check	X
		53111-47040	GRILLE, RADIATOR	0.00	\$389.30	0.00	\$0.00	Replace	Not Given	X
		53289-47032	COVER, RADIATOR	0.00	\$139.30	0.00	\$0.00	Replace	Not Given	X
		53113-47040	GRILLE, RADIATOR LOWER NO.2	0.00	\$118.30	0.00	\$0.00	Replace	Not Given	X
		76851-47020	BUMPER LIP FRT	1.00	\$182.70	25.00	\$137.03	Replace	Replace	√
		52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$159.30	0.00	\$0.00	Replace	Check	X
		51410-12105	UNDER COVER CENTER	0.00	\$511.20	0.00	\$0.00	Replace	Not Given	X
		51444-12050	UNDER COVER SIDE/LH	0.00	\$52.50	0.00	\$0.00	Replace	Not Given	X
		51443-12080	UNDER COVER SIDE/RH	0.00	\$52.50	0.00	\$0.00	Replace	Not Given	X
		81521-47050	LENS & BODY, FR TURN LH	0.00	\$581.40	0.00	\$0.00	Replace	Not Given	X
		53201-47902	SUPPORT SUB-ASSY	1.00	\$1,839.70	100.00	\$0.00	Replace	Repair	R
		81170-47500	HEAD LAMP LH	0.00	\$1,075.40	0.00	\$0.00	Replace	Not Given	X
		81130-47500	HEAD LAMP RH	0.00	\$1,075.40	0.00	\$0.00	Replace	Not Given	X
		53801-47050	FENDER FRT/RH	1.00	\$916.30	100.00	\$0.00	Replace	Repair	R
		75374-47051	NAME PLATE (HYBRID)	0.00	\$59.20	0.00	\$0.00	Replace	Not Given	X
		53875-47030	FENDER LINER FRT/RH	0.00	\$195.40	0.00	\$0.00	Replace	Not Given	X
		53851-47040	FENDER LINER PAD, FR WHEEL. RH	0.00	\$56.30	0.00	\$0.00	Replace	Not Given	X
Total					\$11,290.30		\$1,051.44			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		81130-47500	HEAD LAMP RH	1.00	\$1,075.40	10.00	\$967.86	Replace	Replace
		52114-47140	BRACKET, FR BUMPER	1.00	\$126.10	25.00	\$94.58	Replace	Replace
Total					1,201.50		1,062.44		

	2,113.88	
+	200.00	
+	370.00	L/S \$2,150/-
	2,683.88	
	-20%	
	2,147.10	