

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0426/2023/EQ
DATE : 3-May-23
WIP : 18649

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 5/5/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR GAN CHEE WAH (YAN ZHIHUA)
ADDRESS : 72 WEST COAST ROAD
#02-97
SINGAPORE 126828
TELEPHONE : HP +65 98467754
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210028351-01
VEHICLE NO : **SMY 6517 B**
MODEL CODE : AUDI A6 DESIGN 2.0 TFSI S
MODEL YEAR : 18/3/2021
ENGINE NO : DKY 015263
CHASSIS NO : WAUZZZF23MN052433
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 29-Apr-23
PLACE OF ACCIDENT : SUNSET WAY, CLEMENTI ROAD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMY 6517 B

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	250
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00	500
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$	2,500.00	1100
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 5,972.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 6517 B

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Debond</i>	1	\$ 3,187.00	✓	
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 689.00	+	
3	FRONT BUMPER ADAPTER - LH / RH <i>new</i>	2	\$ 94.00	+	
4	FRONT BUMPER REINFORCEMENT - LH <i>new</i>	1	\$ 132.00	+	
5	FRONT BUMPER CLOSING ELEMENT - LOWER	1	\$ 248.00	+	
6	FRONT BUMPER AIR GUIDE GRILLE - LH <i>new</i>	1	\$ 513.00	+	
7	FRONT BUMPER AIR GUIDE - LH INNER <i>new</i>	1	\$ 39.00	+	
8	FRONT BUMPER AIR GUIDE - LH OUTER	1	\$ 31.00	+	
9	FRONT PARKING AID SENSOR - INNER / OUTER <i>new</i>	2	\$ 598.00	+	
10	FRONT PARKING AID SENSOR <i>new</i>	1	\$ 299.00	+	
11	FRONT PARKING AID SEAL RING	4	\$ 11.00	+	
12	FRONT BUMPER GUIDE SECTION - LH	1	\$ 53.00	?	
13	FRONT BUMPER BRACKET - LH <i>new</i>	1	\$ 65.00	+	
14	FRONT BUMPER TOP COVER	1	\$ 149.00	+	
15	OIL COMPLY WITH VW STANDARD STICKER <i>new</i>	1	\$ 14.00	+	
16	HORN LOW TONE - LH <i>new</i>	1	\$ 244.00	+	
17	HORN BRACKET - LH <i>new</i>	1	\$ 56.00	+	
18	FRONT FENDER - LH <i>Repair</i>	1	\$ 1,746.00	+	
19	FRONT FENDER BRACE - LH <i>new</i>	1	\$ 146.00	+	
20	FRONT FENDER BRACKET - LH UPPER <i>new</i>	1	\$ 52.00	+	

SUB TOTAL SPARE PARTS
: \$ 8,366.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 6517 B

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	FRONT WHEEL HOUSING LINER - LH <i>3H</i>	1	\$ 322.00	<i>x</i>	
22	FRONT WHEEL SPOILER - LH	1	\$ 196.00	<i>x</i>	
23	FRONT WHEEL SPOILER STONE CHIP GUARD - LH <i>MT</i>	1	\$ 60.00	<i>x</i>	
24	HEADLIGHT MOUNTING - LH <i>MT</i>	1	\$ 140.00	<i>x</i>	
25	HEADLIGHT - LH <i>cut</i>	1	\$ 9,712.00	<i>✓</i>	
26	LIFT CYLINDER - LH	1	\$ 230.00	<i>x</i>	
27	LIFT CYLINDER BRACKET - LH <i>Not</i>	1	\$ 8.00	<i>x</i>	
28	LIFT CYLINDER HOSE <i>Not</i>	1	\$ 208.00	<i>x</i>	
29	RADIATOR AIR GUIDE - LH	1	\$ 50.00	<i>x</i>	
30	SUNDRIES		\$ 400.00	<i>?</i>	
TOTAL SPARE PARTS			: \$ 19,692.00		
TOTAL LABOUR CHARGES			: \$ 5,972.00		
GRAND TOTAL			: \$ 25,664.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Ling.*
SURVEYED DATE : *05/05/23*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT